status of MACRO PMT pressure tests at SAB



Shih-Kai Lin, Logan Lebanowski 2010 September 16

overview

- 150 waterproof MACRO EMI PMT assemblies need to be pressure tested at the SAB. They have already passed performance tests at DGUT.
- We test about 10 PMTs per week (mid-August to December).
- For more information, see doc 5373.

As of September 16, we have passed 39 of 40 tested PMTs.



pressure test results


11 PMTs were tested during the past week (September 9 - September 15).

SN	Mass (g)	Pressure (psig)	Test time (h:m)	Status
7945	620.5!	12.2	14:46	*
7379	541!	6.3	08:35	**
8356	523!	6.3	15:17	*
7520	589.0!	12.1	08:11	*
7343	600	12.2	15:22	FAIL. LEAK into acrylic cap (see photo)
8756	590.5	12.1	23:08	* {added mastic tape at base}
7692	562	12.1	08:17	*
8870	587.5	12.1	15:39	A hole on the cable jacket. Fixed with mastic tape And shrink tubing. Will be tested again.
8901	606	12.1	07:42	*
6659	630	12.3	14:30	*
6432	603	12	08:33	*

PASS. Cable dry. No leaks or cracks.
** Some water penetrated the mastic tape seal of the cable strain relief plug, but did not penetrate the UW cable plug.
! recorded in the spredsheet(doc4617) but not on the PMT boxes.

photos

water in acrylic shell cap



signal test results

 This week the oscillascope was taken away for electronics tests. We will resume signal tests once the oscillascope is available.