

# ELI MOTORS LIMITED

49 VICTORIA ROAD, HENDON, LONDON, NW4 2RP  
 020 8203 6449, Sales 07950 250970  
[www.elimotors.co.uk](http://www.elimotors.co.uk)  
 VAT 330 9339 65




Mr Sassoon  
 5 Holmbrook Drive  
 London  
 NW42LT  
 Tel: 02082025738

## Estimate

**6036**

Estimate Date: 05/01/2026  
 Account No: SAS010  
 Order Ref:  
 Estimate Valid to: 04/02/2026

Registration	Make	Model	Chassis Number	Mileage
LD13 KLO	Ford	Focus Zetec	Wf0kxxgcbkdp46303	
Engine No	Engine Code	Engine CC	Date Reg	Colour
DP46303	PNDA	1596	20/06/2013	Black



### Investigate Loss Of Power Steering + Estimate

- Investigated Reported Loss Of Power Steering Following Impact
- Confirmed Power Steering Pipe Had Snapped Due To The Force Of The Collision
- Replaced Power Steering Fluid Container
- Refilled System With Correct Oil And Checked For Leaks
- Removed Damaged Rear Bumper Assembly
- Drilled Out Reverse Parking Sensors From Old Bumper And Transferred To New Bumper
- Supplied And Fitted New Rear Bumper Assembly (Pre-Painted From Manufacturer – No Paint Required)
- Replaced Rear Bumper Lower Skirting
- Replaced Rear Bumper Enforcer
- Replaced Rear Bumper Corner Brackets (Nearside And Offside)
- Replaced Offside Rear Fog Lamp
- Reassembled Rear Bumper And All Listed Components
- Checked Sensor Operation, Alignment, And Fixings
- Final Inspection And Functionality Checks Completed

Labour	Qty	Unit	D	Sub Total
Body Work Labour	1	280.00		280.00

# ELI MOTORS LIMITED

49 VICTORIA ROAD, HENDON, LONDON, NW4 2RP  
 020 8203 6449, Sales 07950 250970  
[www.elimotors.co.uk](http://www.elimotors.co.uk)  
 VAT 330 9339 65



Mr Sassoon  
 5 Holmbrook Drive  
 London  
 NW42LT  
 Tel: 02082025738

**Estimate** **6036**

Estimate Date: 05/01/2026  
 Account No: SAS010  
 Order Ref:  
 Estimate Valid to: 04/02/2026

Parts	Qty	Unit	D	Sub Total
Rear Bumper Assembly	1	480.98		480.98
Lower Bumper Skirting	1	98.76		98.76
Offside Rear Fog Lamp	1	18.58		18.58
Rear Bumper Corner Brackets Nearside And Offside	2	37.44		74.88
Power Steering Container	1	36.13		36.13
5/30 Oil	1	15.89		15.89
Rear Bumper Enforcer	1	128.09		128.09
Valet To Prepare Vehicle	1	25.00		25.00

I agree to pay for all work and parts required for the repairs described above at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. Any additional work found to be necessary must be authorised by myself prior to commencement. All goods shall remain the property of the seller until paid for in full. I have read and accept your terms and conditions.

**Nothing herein is designed to nor will it affect a customers statutory rights**

Signed \_\_\_\_\_ Date \_\_\_\_\_

Labour	280.00
Parts	878.31
<b>SubTotal</b>	<b>1158.31</b>
VAT (20%)	231.68
<b>Estimate Total</b>	<b>1389.99</b>