

Open Job Cards — for review

27 job cards opened over a fortnight ago, never priced, and with no invoice raised for that car since.

Printed 13/08/2026 · ELI MOTORS LTD

					CLOSE	INVOICE	CHASE
92464	FM06 OBX	23/02/2026 · 171 days open	Mrs Malky Grunewald · 07878761253	Investigate Clutch & Starter Motor NISSAN Micra Se	☐	☐	☐
92726	LL60 HYC	09/04/2026 · 126 days open	Mr Sandor Milun · 07891654578	Major Parking Brake Efficiency Below Requirements (1.4.2 (A) (I)) Major Nearside Front Bumper Damaged And Likely To Cause Injury When Grazed Or Contacted (6.1.4 (A) (I)) Major Offside Rear Fog Lamp Not Working (4.5.1 (A) (Ii)) Major Offside Rear Direction Indicator Incorrect Colour (4.4.3 (A)) Advisory Nearside Rear Direction Indicator Slightly Discoloured (4.4.3 (A)) Advisory Tyre Worn Close To Legal Limit/ Worn On Edge And Has Nail, Offside Rear (5.2.3 (E)) Major Nearside Front Outer Drive Shaft Joint Constant Velocity Boot Split Or Insecure, No Longer Prevents The Ingress Of Dirt (6.1.7 (G) (Ii)) Major Oil Leaking Excessively From Engine (8.4.1 (A) (I)) Major Oil Leaking Excessively From Transmission (8.4.1 (A) (I)) Advisory Nearside Play In Steering Rack Inner Joint(S) HYUNDAI Ix20 Active	☐	☐	☐
92857	LS05 WAA	30/04/2026 · 105 days open	Mr Simon Wieder · 07555293385	Investigate Hand Brake Lever Not Holding HYUNDAI Trajet Gsi Special Edition	☐	☐	☐
92979	MW11 JFU	28/05/2026 · 77 days open	Mr Adina Lebrecht · 07815124990	Check Aircon TOYOTA Verso T2 Valvematic	☐	☐	☐
93010	KF17 CRZ	01/06/2026 · 73 days open	Mr David Harounoff · 8203 9533	Carry Out Pre-Sales Inspection Check for faults or warning lights Check tyre condition and pressures Check brakes and suspension HONDA Hr-V I-Vtec Ex	☐	☐	☐
93017	OE71 BGU	02/06/2026 · 72 days open	Mr Ngoc Pham · 07731732152	Check Brakes MERCEDES-BENZ Glc-Class Glc 300 De 4matic Amg Line Premium	☐	☐	☐
93022	MT64 UKA	04/06/2026 · 70 days open	Ms Muzhan Zakeri · +447960593043	Investigate Noise Coming From The Front FORD Fiesta Studio	☐	☐	☐
93025	GD73 KUC	04/06/2026 · 70 days open	Mr Dolf Staszewski · 07956281816	Check Rear Brakes Hyundai Santa Fe Ultimate	☐	☐	☐
93053	MV63 ANX	08/06/2026 · 66 days open	Mr Yehuda Davidson · 07552749955	Investigate Bodywork For Bumper, Headlight Bracket And Nearside Front Panel TOYOTA Verso Valvematic Icon	☐	☐	☐
93063	LM19 FXE	10/06/2026 · 64 days open	Ms Emma Tatz · 07812067919	Ns Door Lock SKODA Kodiaq Edition Tsi Dsg	☐	☐	☐
93105	YB15 KFD	16/06/2026 · 58 days open	Mr Izack · +447949799925	Left Wing Mirror Glass HONDA Jazz i-VTec EX CVT	☐	☐	☐
93098	DA54 NTT	16/06/2026 · 58 days open	Miss Deborah Davis · +447749049772	Investigate Brakes Squeaking TOYOTA Yaris T Spirit Vvt-I	☐	☐	☐
93122	SK70WKC	22/06/2026 · 52 days open	Mrs Sandy Jacobs · 07948974119	Investigate tailgate struts which one is failing LAND ROVER Discovery Sport SE Auto	☐	☐	☐

Open Job Cards — for review

27 job cards opened over a fortnight ago, never priced, and with no invoice raised for that car since.

Printed 13/08/2026 · ELI MOTORS LTD

					CLOSE	INVOICE	CHASE
93131	MF62FBN	23/06/2026 · 51 days open	Mr Zach · 07719032222	Investigate Compressor not activating Topped up Gas on 23/06/26 KIA Picanto Halo EcoDynamics	☐	☐	☐
93142	PJ61ENU	24/06/2026 · 50 days open	Mrs Shira Joseph	(nothing written on the card) NISSAN Qashqai Tekna CVT	☐	☐	☐
93137	LO62UYT	24/06/2026 · 50 days open	Mr Norman Goldfoot · +447931520369	Investigate the report from breakdown TOYOTA Prius+ T4 CVT	☐	☐	☐
93148	PJ61ENU	24/06/2026 · 50 days open	Mrs Shira Joseph · 07801953207	Check front and rear brakes NISSAN Qashqai Tekna CVT	☐	☐	☐
93185	WP57CYT	30/06/2026 · 44 days open	Mr Simon Gold · +447956388097	Check Air con topped up a couple of months ago but may have a leak or compressor/condenser SUZUKI SX4 GLX Auto	☐	☐	☐
93229	DV16NWK	05/07/2026 · 39 days open	Mr H Lederman · +447443007843	- Small Service A/C Condenser Replacement - Park vehicle safely and apply handbrake - Disconnect battery negative terminal - Recover and properly dispose of A/C refrigerant - Remove front grille and intake trims for access - Remove undertray splash shield as needed - Remove front bumper cover retaining fixings - Loosen bumper to gain condenser access - Disconnect condenser-to-hose refrigerant fittings - Remove A/C condenser mounting bolts - Remove condenser and extract from vehicle - Transfer any clips/dry seals/retainers to new condenser - Fit new condenser to mounting points - Reconnect condenser refrigerant fittings - Tighten fittings to specified torque - Check all unions for correct seating and leak path - Reinstall bumper cover and trims - Refit undertray splash shield - Reconnect battery negative terminal - Evacuate A/C system using vacuum pump - Charge A/C system with correct refrigerant mass spec for vehicle/model year NISSAN Qashqai Tekna Dig-T Xtronic	☐	☐	☐
93231	YK16 FWB	06/07/2026 · 38 days open	Mrs Suzanne Clinton Davis · +447776256132	- No Coolant In The Expasnsion Bottle At All - For Temporary Solution, We Added Special Additive To Seal The Leak - Return In A Few Weeks To Check Coolant MINI Cooper Auto	☐	☐	☐
93264	EY14NKK	09/07/2026 · 35 days open	Mr Robert Gaginu · 07387009412	Carried Out Air Conditioning Service - Evacuated and recharged system - Checked for leaks and correct operation - Replaced refrigerant and lubricant to specification VAUXHALL Insignia SRI	☐	☐	☐
93300	MJ21WCU	14/07/2026 · 30 days open	Mr Paul Nurick · +447725947375	Check Front Brake Pads (Warning Light On) BMW X1 sDrive 18d XLine Auto	☐	☐	☐
93348	LL75PCZ	22/07/2026 · 22 days open	Ms Bernice Black · 07769970763	Front Panel Bodywork VAUXHALL Corsa GS Turbo	☐	☐	☐
93351	HV57LFS	22/07/2026 · 22 days open	Mr Ahmed Sidibe · +447404453577	Investigate fan belt contaminated with oil Steam clean front of engine To obtain access to auxiliary belt To supply and fit major auxiliary belt Reassemble as per removal Requires further diagnostic on Air Suspension Management Light Glow plug light on, front and rear suspension low and air suspension management light on We found fault with the front and rear suspension air system Requires front brake discs and pads replacement. MERCEDES-BENZ GL320 CDi 4Matic Auto	☐	☐	☐

Open Job Cards — for review

27 job cards opened over a fortnight ago, never priced, and with no invoice raised for that car since.

Printed 13/08/2026 · ELI MOTORS LTD

					CLOSE	INVOICE	CHASE
93369	EA56CWN	24/07/2026 · 20 days open	Mr Eli Moses · 07907460111	Drivers side shock absorber been replaced Had a knock on the motorway LEXUS RX 400 H SE CVT	☐	☐	☐
93373	LX62UCB	27/07/2026 · 17 days open	Mr Yaakov Tolwin · 07521012295	Investigate car not running smoothly (Clunking noise, not wanting to move smoothly) HONDA Jazz I-Vtec Ex	☐	☐	☐
93377	GF69XUL	27/07/2026 · 17 days open	Mr Joe Saleh · +447507504788	Investigate under shield needs to be reattached Also the tyre pressure light comes on might be faulty TPMS HONDA Jazz I-Vtec Ex Navi	☐	☐	☐

