TRACEIQ DEMO WALKTHROUGH

Supplier to finished-lot trace

A practical, repeatable path through supplier registration, evidence upload, quality gates, production genealogy, and final traceability.

Demo supplier	Raw lot	Finished lot
SUP-DEMO-3100 Cedar Grove Botanicals Ltd.	RAW-DEMO-3100 Acetaminophen API - 250 kg	FG-DEMO-3100 TraceRelief 500 mg - 900 units

Before you start

Use the local TraceIQ app at http://localhost:3000. These PDFs contain fictional demo data. Use the values exactly as listed so document fields, supplier, lots, production order, and evidence all match.

1. Register the supplier

Supplier Master > open Register a supplier. Enter Supplier ID **SUP-DEMO-3100**, Supplier name **Cedar Grove Botanicals Ltd.**, Country **Canada**, then click Create record. The new supplier starts in Under Review.

2. Upload and verify the supplier certificate

Open **Document Intelligence**. Upload **01_supplier_certificate_of_analysis_SUP-DEMO-3100.pdf** with category Auto. Wait for extraction, check the supplier ID, supplier name, material name, and lot identifier, then click Verify extraction. Copy the generated DOC ID from the document details.

3. Qualify the supplier

Open **Quality**. Choose record type Supplier, enter **SUP-DEMO-3100**, paste the certificate DOC ID into Evidence reference, and run the deterministic check. The sample supplier should change to Active after the passing check.

PHASE 2 - RECEIVE AND APPROVE MATERIAL

Create a traceable raw lot before production.

4. Record raw-material intake

Open **Traceability** and click Receive raw material. Enter Lot ID **RAW-DEMO-3100**, Material name **Acetaminophen API**, Qualified supplier ID **SUP-DEMO-3100**, and Quantity **250**. Click Record intake. The lot starts Pending Quality.

5. Upload the goods receipt evidence

In **Document Intelligence**, upload **02_goods_receipt_note_RAW-DEMO-3100.pdf**. Review its extracted supplier, lot, material, and quantity values and verify the extraction. In Evidence links, link it to LOT **RAW-DEMO-3100**.

6. Approve the raw lot

In **Quality**, select Lot, enter **RAW-DEMO-3100**, use the goods-receipt document DOC ID as Evidence reference, and run the check. The passing result should change the lot to Approved. Production accepts only an approved raw-material lot.

7. Record the production order

Return to **Traceability** and click Record production order. Enter Production order ID **PO-DEMO-3100**; Product ID **PROD-001**; Approved input lot **RAW-DEMO-3100**; Input quantity **180 kg**; Finished lot ID **FG-DEMO-3100**; Output name **TraceRelief 500 mg Demo Batch Oct 30**; Output quantity **900 units**. Click Save production links.

PHASE 3 - VERIFY EVIDENCE AND TRACE

Complete the genealogy and demonstrate the result.

8. Upload the production order PDF

In **Document Intelligence**, upload **03_production_order_PO-DEMO-3100.pdf**. Check the production-order ID and both lot IDs, then verify. Link the document to PRODUCTION_ORDER **PO-DEMO-3100** and LOT **FG-DEMO-3100**.

9. Upload finished-lot inspection evidence

Upload **04_quality_inspection_evidence_FG-DEMO-3100.pdf**. Review the finished-lot ID, production order, input lot, and output quantity, then verify. Link it to LOT **FG-DEMO-3100**.

10. Release and trace the finished lot

In **Quality**, run a check for Lot **FG-DEMO-3100** and use the inspection report DOC ID as Evidence reference. Confirm a passing result and Released status. In **Traceability**, search for **FG-DEMO-3100**. The graph should show the supplier, raw lot, production order, and finished lot.

Expected end state

Supplier: SUP-DEMO-3100 is Active. **Raw lot:** RAW-DEMO-3100 is Approved. **Production:** PO-DEMO-3100 connects RAW-DEMO-3100 to FG-DEMO-3100. **Finished lot:** FG-DEMO-3100 is Released and traceable to its supplier. Each uploaded source remains a separate document with a review decision and business-record link.

If a check does not pass, use its finding and evidence reference to correct the record, then run a new versioned check. The sample documents are intentionally marked as demo data and must never be treated as real certificates or quality records.