


Experiment 3

STEPPER MOTOR USING AT89C51 USING PROTEUS



```
main.asm
1  ORG 0000H
2  UP: MOV P2,#09H
3  ACALL DELAY
4  MOV P2,#0CH
5  ACALL DELAY
6  MOV P2,#06H
7  ACALL DELAY
8  MOV P2,#03H
9  ACALL DELAY
10 S: JUMP UP
11 DELAY: MOV R4,#18
12 H1: MOV R3,#255
13 H2: DJNZ R3,H2
14 DJNZ R4,H1
15 RET
16 END
```

