```
Checkpoint
```

return;

Checkpoint

```
If i2cRead(&data) == true
                           If i2cRead(&data) == false
calX = data[0]
                           return;
calY = data [1]
            Power fail
calZ = data[2]
```

```
function sensorMagInit {
   Checkpoint
    int rawData[3];
    if (i2cRead(&rawData[0])) {
        calX = rawData[0] + 128;
        calY = rawData[1] + 128;
        Power fail
        calZ = rawData[2] + 128;
```