

LOTO Procedure — BSAW-03 Horizontal Band Saw — Blade Guard Service

Energy-control procedure per 29 CFR 1910.147. Required before any task that opens the blade guard on BSAW-03.

```
--- METADATA ---
document_id: SP-LOTO-BSAW03-RevB
title: LOTO Procedure – BSAW-03 Horizontal Band Saw – Blade Guard Service
domain: compliance
source_system: SharePoint
revision: Rev B
effective_date: 2024-11-02
owner: J. Reyes, EH&S Officer – Wichita
part_numbers: []
operation_numbers: []
machine_ids: [BSAW-03]
controller_models: []
fault_codes: []
materials: [MAT-CF-ECO]
standards: [29-CFR-1910.147]
supplier_ids: []
jurisdictions: [US-Federal-OSHA]
classification: internal
safety_critical: true
---
```

1. Authorised personnel

Maintenance technicians trained per 29 CFR 1910.147(c)(7). Operators are **not** authorised to open the blade guard. Annual LOTO refresher required.

2. Energy sources to isolate

Source	Magnitude	Isolation device	Lockout point
Electrical	480 V 3-phase	Disconnect switch (wall, left of saw)	Hasp + personal lock
Pneumatic (clamp)	6 bar	Air shutoff valve (rear of saw)	Hasp + personal lock; bleed downstream pressure to 0 after closing
Hydraulic (feed)	20 bar	Hydraulic shutoff valve (rear)	Hasp + personal lock; bleed reservoir line

Stored mechanical (blade tension)	n/a	De-tension blade before guard removal	—
Cutting fluid (EcoCut 7700 — ERP-SDS-ECOCUT7700)	flowing	Coolant pump switch	Hasp + personal lock

3. Procedure — opening the blade guard

STOP. Never open the blade guard on a running saw. Never bypass the door interlock. This procedure must be completed before any task that opens the guard, including blade replacement, blade-tension adjustment, or coolant-line service inside the guard.

1. **Notify.** Inform operator and shift lead that the saw will be out of service. Tag the shift-handover board.
2. **Shutdown.** Stop the saw at the operator panel. Wait until the blade is fully stopped. Press E-stop.
3. **Isolate.** For each energy source in §2 above: operate the isolation device to the off position, apply hasp and personal lock, attach LOTO tag with name and date.
4. **Verify zero energy.** Attempt to start the saw from the operator panel — it must not move. Check pneumatic and hydraulic gauges read zero. Confirm coolant pump cannot start.
5. **De-tension the blade** via the manual tension wheel.
6. **Open the guard.** Now safe to open the blade guard and perform the service task.

4. Procedure — restoring service

1. Confirm all tools and personnel are clear of the blade area.
2. Close the blade guard and re-engage all interlocks.
3. Re-tension blade per OEM specification.
4. Remove personal locks and tags *in the reverse order* they were applied: the last-applied lock is removed first.
5. Restore each energy source. Verify gauges return to normal operating range.
6. Run a no-cut test cycle. Confirm normal operation. Release saw to production.

5. Cross-reference

Machine guarding context: SP-OSHA-MG-WICHITA . For any task involving the cutting fluid (sump cleaning, line work), additionally consult the SDS ERP-SDS-ECOCUT7700 and use the PPE specified there.

Document control / sign-off

Role	Name	Signature	Date
Document Owner	J. Reyes, EH&S Officer — Wichita	(on file)	2024-11-02

Approver	J. Reyes, EH&S Officer — Wichita	(on file)	2024-11-02
----------	----------------------------------	-----------	------------