Gen11 Service Pack for ProLiant version 2023.04.00.00 Contents

This table lists all of the software and firmware on this Gen11 Service Pack for ProLiant. For more information on this deliverable go to www.hpe.com/servers/spp/download.

Product Category	Description	Build #	Version	Upgrade Requirement	Filename	Release Status
Application - System Management	Integrated Smart Update Tools for Windows x64	18	4.1.0.0	Recommende d	cp054785 .exe	update
Application - System Management	Integrated Smart Update Tools 4.1.0 for ESXi 7.0	11	2023.03	Recommende d	cp054907 .zip	new
Application - System Management	Integrated Smart Update Tools 4.1.0 for ESXi 8.0	14	2023.03	Recommende d	cp055084 .zip	new
Application - System Management	Integrated Smart Update Tools for Linux x64	17	4.1.0.0	Recommende d	sut-4.1.0- 17.linux.x8 6_64.rpm	update
BIOS - System ROM	ROM Flash Firmware Package - HPE Alletra 4110/Alletra 4120/ProLian t DL380a Gen11 (U58) Servers	14	1.30_03 -01- 2023	Recommende d	U58_1.30_ 03_01_202 3.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Linux -	3	1.22_01 -19- 2023	Recommende d	firmware- system- a56- 1.22_2023	new

	HPE ProLiant DL325/DL34 5 Gen11 (A56) Servers				_01_19- 1.1.x86_64 .rpm	
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL110 Gen11 (U62) Servers	46	1.30_03 -01- 2023	Recommende d	firmware- system- u62- 1.30_2023 _03_01- 1.1.x86_64 .rpm	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL560 Gen11 (U59) Servers	47	1.30_03 -01- 2023	Recommende d	cp050030 .exe	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE Alletra 4110/Alletra 4120/HPE ProLiant DL380a (U58) Servers	12	1.30_03 -01- 2023	Recommende d	firmware- system- u58- 1.30_2023 _03_01- 1.1.x86_64 .rpm	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL365/DL38 5 Gen11	3	1.22_01 -19- 2023	Recommende d	cp055965 .exe	new

	(A55) Servers					
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL560 Gen11 (U59) Servers	44	1.30_03 -01- 2023	Recommende d	firmware- system- u59- 1.30_2023 _03_01- 1.1.x86_64 .rpm	new
BIOS - System ROM	ROM Flash Universal Firmware Package - HPE ProLiant DL325/DL34 5 Gen11 (A56) Servers	3	1.22_01 -19- 2023	Recommende d	A56_1.22_ 01_19_202 3.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL325/DL34 5 Gen11 (A56) Servers	3	1.22_01 -19- 2023	Recommende d	cp055962 .exe	new
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL110 Gen11 (U62) Servers	52	1.30_03 -01- 2023	Recommende d	U62_1.30_ 03_01_202 3.fwpkg	new
BIOS - System ROM	ROM Flash Universal Firmware	3	1.22_01 -19- 2023	Recommende d	A55_1.22_ 01_19_202 3.fwpkg	new

	Package - HPE ProLiant DL365/DL38 5 Gen11 (A55) Servers					
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL320/ML11 0 Gen11 (U63) Servers	16	1.30_03 -01- 2023	Recommende d	cp055738 .exe	new
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL320/ML11 0 Gen11 (U63) Servers	12	1.30_03 -01- 2023	Recommende d	U63_1.30_ 03_01_202 3.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL320/ML11 0 Gen11 (U63) Servers	13	1.30_03 -01- 2023	Recommende d	firmware- system- u63- 1.30_2023 _03_01- 1.1.x86_64 .rpm	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant ML350/DL36	12	1.30_03 -01- 2023	Recommende d	cp055744 .exe	new

	0/DL380 Gen11 (U54) Servers					
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL560 Gen11 (U59) Servers	50	1.30_03 -01- 2023	Recommende d	U59_1.30_ 03_01_202 3.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE Alletra 4110/Alletra 4120/HPE ProLiant DL380a Gen11 (U58) Servers	14	1.30_03 -01- 2023	Recommende d	cp055275 .exe	new
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant ML350/DL36 0/DL380 Gen11 (U54) Servers	10	1.30_03 -01- 2023	Recommende d	U54_1.30_ 03_01_202 3.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML350/DL36 0/DL380 Gen11 (U54) Servers	9	1.30_03 -01- 2023	Recommende d	firmware- system- u54- 1.30_2023 _03_01- 1.1.x86_64 .rpm	new

BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL365/DL38 5 Gen11 (A55) Servers	3	1.22_01 -19- 2023	Recommende d	firmware- system- a55- 1.22_2023 _01_19- 1.1.x86_64 .rpm	new
Driver - Network	Broadcom NetXtreme-E Driver for Microsoft Windows Server 2022	5	224.0.1 59.0	Recommende d	cp054748 .exe	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) ConnectX-4, ConnectX-5 and ConnectX-6 Driver for SUSE LINUX Enterprise Server 15 SP4 (AMD64/EM 64T)	9	5.8	Recommende d	mlnx- ofa_kerne	new
Driver - Network	Intel icen Driver for VMware vSphere 7.0	3	2023.03	Recommende d	cp055475 .zip	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for Red Hat	3	1.10.2- 224	Recommende d	kmod- bnxt_en- 1.10.2- 224.0.157. 0.rhel8u6.	new

	Enterprise Linux 8				x86_64.rp m	
Driver - Network	Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 "nmlx5_en" Driver Component for VMware ESXi 7.0 Update 3	9	2022.11	Recommende d	cp054875 .zip	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for Red Hat Enterprise Linux 9	8	1.10.2- 224.0.1 57.0	Recommende d	kmod- bnxt_en- 1.10.2- 224.0.157. 0.rhel9u0. x86_64.rp m	new
Driver - Network	Mellanox CX5 and CX6DX Driver for Microsoft Windows Server 2022	2	3.10.25 798.0	Recommende d	cp054856 .exe	new
Driver - Network	Intel ice Drivers for SUSE Linux Enterprise Server 15	5	1.10.1.2 -1	Recommende d	ice-kmp- default- 1.10.1.2_k 5.14.21_1 50400.22- 1.sles15sp 4.x86_64.r pm ice-kmp- default- 1.10.1.2_k 5.3.18_57- 1.sles15sp 3.x86_64.r pm	new

Driver - Network	Broadcom NetXtreme-E Driver for Microsoft Windows Server 2019	3	224.0.1 59.0	Recommende d	cp054747 .exe	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 8 Update 5.	4	222.0.1 42.0	Recommende d	libbnxt_re - 222.0.142. 0- rhel8u5.x8 6_64.rpm	new
Driver - Network	Intel ice Drivers for Red Hat Enterprise Linux 9	5	1.10.1.2 -1	Recommende d	kmod- ice- 1.10.1.2- 1.rhel9u0. x86_64.rp m	new
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 9	14	3.139j-1	Recommende d	kmod- tg3- 3.139j- 1.5.14.0.7 0.22.1.rhel 9u0.x86_6 4.rpm	new
Driver - Network	HPE Intel iavf Drivers for Red Hat Enterprise Linux 9	3	4.6.1-1	Recommende d	kmod-hp- iavf-4.6.1- 1.rhel9u0. x86_64.rp m	new
Driver - Network	HPE Intel igbn Driver for VMware vSphere 7.0	3	2023.03	Recommende d	cp055476 .zip	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE	2	224.0.1 57.0	Recommende d	libbnxt_re - 224.0.157. 0-	new

	Library for SUSE Linux Enterprise Server 15 SP4				sles15sp4. x86_64.rp m	
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) ConnectX-4, ConnectX-5 and ConnectX-6 Driver for Red Hat Enterprise Linux 9 Update 1 (x86_64)	3	5.8	Recommende d	mlnx- ofa_kerne l-5.8- OFED.5.8. 1.1.2.1.rhe l9u1.x86_6 4.rpm kmod- mlnx- ofa_kerne l-5.8- OFED.5.8. 1.1.2.1.rhe l9u1.x86_6 4.rpm	new
Driver - Network	HPE Intel iavf Drivers for Red Hat Enterprise Linux 8	3	4.6.1-1	Recommende d	kmod-hp- iavf-4.6.1- 1.rhel8u6. x86_64.rp m kmod-hp- iavf-4.6.1- 1.rhel8u5. x86_64.rp m	new
Driver - Network	HPE Intel igb Drivers for Red Hat Enterprise Linux 9	9	5.12.3-1	Recommende d	kmod-hp- igb- 5.12.3- 1.rhel9u0. x86_64.rp m	new
Driver - Network	Broadcom NX1 1Gb Driver for Windows Server x64 Editions	5	221.0.5. 0	Recommende d	cp054663 .exe	new

Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 9 Update 0.	5	224.0.1 57.0	Recommende d	libbnxt_re - 224.0.157. 0- rhel9u0.x8 6_64.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for SUSE Linux Enterprise Server 15	2	1.10.2- 224.0.1 57.0	Recommende d	bnxt_en- kmp- default- 1.10.2_k5. 3.18_57- 224.0.157. 0.sles15sp 3.x86_64.r pm bnxt_en- kmp- default- 1.10.2_k5. 14.21_150 400.22- 224.0.157. 0.sles15sp 4.x86_64.r pm	update
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) ConnectX-4, ConnectX-5 and ConnectX-6 Driver for Red Hat Enterprise Linux 8 Update 7 (x86_64)	4	5.8	Recommende d	mlnx- ofa_kerne l-5.8- OFED.5.8. 1.1.2.1.rhe l8u7.x86_6 4.rpm kmod- mlnx- ofa_kerne l-5.8- OFED.5.8. 1.1.2.1.rhe l8u7.x86_6 4.rpm	new

Driver - Network	HPE Broadcom tg3 Ethernet Drivers for SUSE Linux Enterprise Server 15	7	3.139j-2	Recommende d	tg3-kmp-default-3.139j_k5. 14.21_150 400.22- 2.sles15sp 4.x86_64.r pm tg3-kmp-default- 3.139j_k5. 3.18_57- 2.sles15sp 3.x86_64.r pm	update
Driver - Network	Intel iavf Driver for Windows Server 2022	1	1.13.8.0 (D)	Recommende d	cp055982 .exe	new
Driver - Network	Intel icea Driver for Windows Server 2019	1	1.12.14 8.0	Recommende d	cp055477 .exe	new
Driver - Network	HPE Intel igb Drivers for Red Hat Enterprise Linux 8	10	6.12.3-1	Recommende d	kmod-hp- igb- 6.12.3- 1.rhel8u5. x86_64.rp m kmod-hp- igb- 6.12.3- 1.rhel8u6. x86_64.rp m	new
Driver - Network	HPE Intel igb Drivers for SUSE Linux Enterprise Server 15	9	6.12.3-1	Recommende d	hp-igb- kmp- default- 6.12.3_k5. 14.21_150 400.22- 1.sles15sp 4.x86_64.r pm	update

					hp-igb- kmp- default- 6.12.3_k5. 3.18_57- 1.sles15sp 3.x86_64.r pm	
Driver - Network	Intel i350 Driver for Windows Server 2022	1	13.0.13. 0 (C)	Recommende d	cp055981 .exe	new
Driver - Network	Intel ice Drivers for Red Hat Enterprise Linux 8	3	1.10.1.2 -1	Recommende d	kmod- ice- 1.10.1.2- 1.rhel8u6. x86_64.rp m kmod- ice- 1.10.1.2- 1.rhel8u5. x86_64.rp m	new
Driver - Network	HPE Intel iavf Drivers for SUSE Linux Enterprise Server 15	3	4.6.1-1	Recommende d	hp-iavf- kmp- default- 4.6.1_k5.3. 18_57- 1.sles15sp 3.x86_64.r pm hp-iavf- kmp- default- 4.6.1_k5.1 4.21_1504 00.22- 1.sles15sp 4.x86_64.r pm	update
Driver - Network	Intel i350 Driver for	3	12.18.1 3.0 (C)	Recommende d	cp055495 .exe	new

	Windows Server 2019					
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 8	4	3.139j-1	Recommende d	kmod- tg3- 3.139j- 1.rhel8u6. x86_64.rp m	new
Driver - Network	Intel icea Driver for Microsoft Windows Server 2022	2	1.12.14 8.0	Recommende d	cp055478 .exe	new
Driver - Network	Mellanox CX5 and CX6DX Driver for Microsoft Windows Server 2019	4	3.10.25 798.0	Recommende d	cp054855 .exe	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 8 Update 6.	2	224.0.1 57.0	Recommende d	libbnxt_re - 224.0.157. 0- rhel8u6.x8 6_64.rpm	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) ConnectX-4, ConnectX-5 and ConnectX-6 Driver for Red Hat	5	5.8	Recommende d	mlnx- ofa_kerne l-5.8- OFED.5.8. 1.1.2.1.rhe l9u0.x86_6 4.rpm kmod- mlnx- ofa_kerne l-5.8- OFED.5.8.	new

	Enterprise Linux 9 Update 0 (x86_64)				1.1.2.1.20 22121707 54.rhel9u0 .x86_64.rp m	
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) ConnectX-4, ConnectX-5 and ConnectX-6 Driver for Red Hat Enterprise Linux 8 Update 6 (x86_64)	4	5.8	Recommende d	kmod- mlnx- ofa_kerne I-5.8- OFED.5.8. 1.1.2.1.rhe I8u6.x86_6 4.rpm mlnx- ofa_kerne I-5.8- OFED.5.8. 1.1.2.1.rhe I8u6.x86_6 4.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for VMware vSphere 7.0	3	2023.03	Recommende d	cp054746 .zip	new
Driver - Network	Intel iavf Driver for Windows Server 2019	6	1.13.8.0 (C)	Recommende d	cp054095 .exe	new
Driver - Storage Controller	HPE ProLiant Gen10, Gen10Plus and Gen11 Smart Array Controller (64-bit) Driver for Red Hat Enterprise	14	2.1.20- 035 (C)	Recommende d	kmod- smartpqi- 2.1.20- 035.rhel9u 0.x86_64.r pm	new

	Linux 9 (64- bit)					
Driver - Storage Controller	HPE MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p Gen10P and Gen11 controller (64-bit) Driver for vSphere 7.0	4	2023.04 .01	Recommende d	cp055449 .zip	new
Driver - Storage Controller	HPE ProLiant Gen10, Gen10Plus and Gen11 Smart Array Controller (64-bit) Driver for Red Hat Enterprise Linux 8 (64-bit)	1	2.1.20- 035 (C)	Recommende d	kmod- smartpqi- 2.1.20- 035.rhel8u 5.x86_64.r pm kmod- smartpqi- 2.1.20- 035.rhel8u 6.x86_64.r pm	new
Driver - Storage Controller	HPE Gen10 Smart Array and Gen10 Plus/Gen11 Smart RAID Controller Driver for Windows Server 2016, Windows Server 2019 and Windows Server 2022	2	1010.64 .0.1037	Recommende d	cp056170 .exe	update
Driver - Storage Controller	HPE MR416i-p, MR416i-o,	7	7.722.6. 0 (C)	Recommende d	cp055448 .exe	new

	MR216i-o, MR408i-o, MR216i-p Gen10P and Gen11 controller driver for Microsoft Windows 2022 edition					
Driver - Storage Controller	HPE ProLiant Gen10 Smart Array and Gen10 Plus and Gen11 Smart RAID Controller Driver for VMware vSphere 8.0 (Driver Component).	3	2023.04 .01	Recommende d	cp055512 .zip	new
Driver - Storage Controller	HPE ProLiant Gen10, Gen10Plus and Gen11 Smart Array Controller (64-bit) Driver for SUSE LINUX Enterprise Server 15 (64-bit)	1	2.1.20- 035 (C)	Recommende d	smartpqi- kmp- default- 2.1.20- 035.sles15 sp4.x86_6 4.rpm smartpqi- kmp- default- 2.1.20- 035.sles15 sp3.x86_6 4.rpm	update
Driver - Storage Controller	HPE ProLiant Gen10 Smart Array and Gen10 Plus and Gen11 Smart RAID Controller	2	2023.04 .01	Recommende d	cp055511 .zip	new

	Driver for VMware vSphere 7.0 (Driver Component).					
Driver - Storage Controller	HPE MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p Gen10P and Gen11 controller Driver for Microsoft Windows 2019 edition	8	7.722.6. 0 (C)	Recommende d	cp055447 .exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 Emulex Storport Driver for Microsoft Windows Server 2022	3	14.0.53 4.0 (b)	Recommende d	cp054344 .exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 QLogic Storport Driver for Microsoft Windows Server 2022	5	9.4.6.20 (b)	Recommende d	cp054361 .exe	new
Driver - Storage Fibre Channel and	Red Hat Enterprise Linux 9	7	14.0.49 9.31	Recommende d	kmod-elx- lpfc- 14.0.499.3	new

Fibre Channel Over Ethernet	Update 1 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters				1- 1.rhel9u1. x86_64.rp m	
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 9 Update 1 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	7	10.02.0 8.01-k1	Recommende d	kmod- qlgc- qla2xxx- 10.02.08.0 1_k1- 1.rhel9u1. x86_64.rp m	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 7 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	7	14.0.49 9.31	Recommende d	kmod-elx- lpfc- 14.0.499.3 1- 1.rhel8u7. x86_64.rp m	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 QLogic Storport Driver for Microsoft Windows Server 2019	6	9.4.6.20 (b)	Recommende d	cp054360 .exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 7 Server Fibre	6	10.02.0 8.01-k1	Recommende d	kmod- qlgc- qla2xxx- 10.02.08.0 1_k1-	new

	Channel Driver Kit for HPE QLogic Host Bus Adapters				1.rhel8u7. x86_64.rp m	
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 9 Update 0 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	7	14.0.49 9.31	Recommende d	kmod-elx- lpfc- 14.0.499.3 1- 1.rhel9u0. x86_64.rp m	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 6 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapter	5	10.02.0 7.01-k1	Recommende d	kmod- qlgc- qla2xxx- 10.02.07.0 1_k1- 2.rhel8u6. x86_64.rp m	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SuSE Linux Enterprise Server 15 Service Pack 4 Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	6	10.02.0 7.01-k1	Recommende d	qlgc- qla2xxx- kmp- default- 10.02.07.0 1_k1_k5.1 4.21_1504 00.22- 2.sles15sp 4.x86_64.r pm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SuSE Linux Enterprise Server 15 Service Pack 4 Fibre Channel Driver Kit for	8	14.0.49 9.31	Recommende d	elx-lpfc- kmp- default- 14.0.499.3 1_k5.14.21 _150400.2 2- 1.sles15sp	new

	HPE Emulex Host Bus Adapters				4.x86_64.r pm	
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 9 Update 0 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	7	10.02.0 7.01-k1	Recommende d	kmod- qlgc- qla2xxx- 10.02.07.0 1_k1- 2.rhel9u0. x86_64.rp m	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 Emulex Storport Driver for Microsoft Windows Server 2019	3	14.0.53 4.0 (b)	Recommende d	cp054343 .exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 6 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	6	14.0.49 9.31	Recommende d	kmod-elx- lpfc- 14.0.499.3 1- 1.rhel8u6. x86_64.rp m	new
Driver - System Management	iLO 6 Channel Interface Driver for Microsoft Windows Server 2022	4	4.7.1.0 (B)	Recommende d	cp054301 .exe	new

Driver - System Management	iLO 6 Automatic Server Recovery Driver for Microsoft Windows Server 2022	4	4.7.1.0 (B)	Recommende d	cp054302 .exe	new
Driver - System Management	iLO 6 Channel Interface Driver for Microsoft Windows Server 2019	4	4.7.1.0 (B)	Recommende d	cp054299 .exe	new
Driver - System Management	iLO 6 Automatic Server Recovery Driver for Microsoft Windows Server 2019	4	4.7.1.0 (B)	Recommende d	cp054300 .exe	new
Driver - Chipset	Identifiers for AMD EPYC Genoa Processors for Microsoft Windows Server 2019	1	4.11.28. 151	Recommende d	cp055530 .exe	new
Driver - Chipset	Identifiers for AMD EPYC Genoa Processors for Microsoft Windows Server 2022	1	4.11.28. 151	Recommende d	cp055531 .exe	new
Driver - Chipset	Identifiers for Intel Xeon Scalable Processors (Fourth	5	10.1.19 263.834 4	Recommende d	cp053816 .exe	new

	Generation) for Microsoft Windows					
Driver - Security	Intel QuickAssist Technology driver for Microsoft Windows	3	2.0.40.3	Recommende d	cp056005 .exe	new
Driver - Video	Matrox G200eH3 Video Controller Driver for Microsoft Windows Server 2019 and 2022	3	9.15.1.2 48	Recommende d	cp054298 .exe	new
Firmware - System	Firmware Package - UBM5 Backplane PIC PLDM Firmware for Gen11 servers usage	76	1.06	Recommende d	HPE_UBM 5_1.06_A.f wpkg	new
Firmware - System	Firmware Package - UBM4 Backplane PIC PLDM Firmware for Gen10/Gen10 P/Gen11 servers usage	4	1.24 (F)	Recommende d	HPE_UBM 4_1.24_F.f wpkg	new
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS)	3	06.00.0 4.033.0	Recommende d	firmware- u63_me- 06.00.04.0 33.0- 1.1.x86_64 .rpm	new

	Firmware for HPE ProLiant DL320/ML11 0 Gen11					
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE ProLiant DL360/DL38 0/ML350 Gen11 Servers	3	06.00.0 4.033.0	Recommende d	SC_U54_ ME_06.00. 04.033.0.f wpkg	new
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS) Firmware for HPE ProLiant DL110 Gen11 Servers	28	06.00.0 4.033.0	Recommende d	firmware- u62_me- 06.00.04.0 33.0- 1.1.x86_64 .rpm	new
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS) Firmware for HPE ProLiant DL360/DL38 0/ML350 Gen11	3	06.00.0 4.033.0	Recommende d	firmware- u54_me- 06.00.04.0 33.0- 1.1.x86_64 .rpm	new

Firmware - System	Firmware Package - UBM3 Backplane PIC PLDM Firmware for Gen10/Gen10 P/Gen11 servers usage	7	1.24 (E)	Recommende d	HPE_UBM 3_1.24_E.f wpkg	new
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform Services (SPS) Firmware for HPE Alletra 4110/Alletra 4120/ProLian t DL380a Gen11 Servers	3	06.00.0 4.033.0	Recommende d	cp056090 .exe	new
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE Alletra 4110/Alletra 4120/ProLian t DL380a Gen11 Servers	3	06.00.0 4.033.0	Recommende d	SC_U58_ ME_06.00. 04.033.0.f wpkg	new
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS)	26	06.00.0 4.033.0	Recommende d	firmware- u59_me- 06.00.04.0 33.0- 1.1.x86_64 .rpm	new

	Firmware for HPE ProLiant DL560 Gen11 Servers					
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform Services (SPS) Firmware for HPE ProLiant DL560 Gen11 Servers	27	06.00.0 4.033.0	Recommende d	cp051699 .exe	new
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform Services (SPS) Firmware for HPE ProLiant DL360/DL38 0/ML350 Gen11	3	06.00.0 4.033.0	Recommende d	cp056085 .exe	new
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE ProLiant DL560	26	06.00.0 4.033.0	Recommende d	SC_U59_ ME_06.00. 04.033.0.f wpkg	new

	Gen11 Servers					
Firmware - System	Firmware Package - UBM6 Backplane PIC PLDM Firmware for Gen10/Gen10 P/Gen11 servers usage	4	1.02 (E)	Recommende d	HPE_UBM 6_1.02_E.f wpkg	new
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE ProLiant DL110 Gen11 Servers	33	06.00.0 4.033.0	Recommende d	SC_U62_ ME_06.00. 04.033.0.f wpkg	new
Firmware - System	Firmware Package - UBM2 Backplane PIC PLDM Firmware for Gen11 Servers	4	1.20 (D)	Recommende d	HPE_UBM 2_1.20_D.f wpkg	new
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform Services (SPS) Firmware for HPE ProLiant	3	06.00.0 4.033.0	Recommende d	cp056093 .exe	new

	DL320/ML11 0 Gen11					
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS) Firmware for HPE Alletra 4110/Alletra 4120/ProLian t DL380a Gen11 Servers	3	06.00.0 4.033.0	Recommende d	firmware- u58_me- 06.00.04.0 33.0- 1.1.x86_64 .rpm	new
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE ProLiant DL320/ML11 0 Gen11 Servers	3	06.00.0 4.033.0	Recommende d	SC_U63_ ME_06.00. 04.033.0.f wpkg	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB006000J YDNF and MB008000J YDPC Drives	1	HPD2 (C)	Recommende d	cp053345 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component	2	HPG1 (B)	Recommende d	cp053002 .exe	new

	for Windows (x64) - MB010000G YDKP, MB012000G YCJL, MB014000G YCJT, MB016000G YDKQ and MB018000G YDKR Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB002000J YDNE and MB004000J YDPB Drives	3	HPD2 (C)	Recommende d	firmware- hdd- d4be2ae cbb- HPD2- 3.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000600J WEBH and EG000300J WEBF Drives	2	HPD5 (D)	Recommende d	cp052980 .exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EO000400PX DBQ, EO000800PX DCK, EO001600PX	1	HPD3 (C)	Recommende d	cp052991 .exe	new

	DCH, MO000800P XDBP, MO001600P XDCC, MO003200P XDCD, MO006400P XDCE, VO000960P XDBN, VO001920P XDBR, VO003840P XDBT, VO007680P XDBU and VO015300P XDBV Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000600J WEBH and EG000300J WEBF Drives	2	HPD5 (E)	Recommende d	firmware- hdd- aa9e2895 24-HPD5- 5.1.x86_64 .rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO000960R WUEV, VO001920R WUFA, VO003840R WUFB, VO007680R WUFC, VO000960R	3	HPD7	Recommende d	firmware- hdd- 8fafc9efb 2-HPD7- 1.1.x86_64 .rpm	new

	WUFD, VO001920R WUFE and VO003840R WUFF Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB006000J YDNF and MB008000J YDPC Drives	3	HPD2 (C)	Recommende d	firmware- hdd- b04df66fe 9-HPD2- 3.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB016000J WXKH Drive	6	HPDA	Recommende d	firmware- hdd- 8a0371a4 25-HPDA- 1.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EO000400PX DBQ, EO000800PX DCK, EO001600PX DCH, MO000800P XDBP, MO001600P XDCC, MO003200P XDCD, MO006400P XDCE,	4	HPD3 (C)	Recommende d	CP053486 .zip	new

	VO000960P XDBN, VO001920P XDBR, VO003840P XDBT, VO007680P XDBU and VO015300P XDBV Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB014000J WUDB Drive	2	HPD3 (E)	Recommende d	firmware- hdd- cfd7436fc c-HPD3- 5.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB002000J YDNE and MB004000J YDPB Drives	1	HPD2 (C)	Recommende d	cp053350 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB014000J WUDB Drive	2	HPD3 (D)	Recommende d	cp052951 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi -	7	HPDA	Recommende d	CP053443 .zip	new

	MB016000J WXKH Drive					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000600J WEBH and EG000300J WEBF Drives	3	HPD5 (D)	Recommende d	CP053464 .zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB010000J WZHA, MB012000J WZHB, MB014000J WZHC and MB016000J WZHE Drives	1	HPD4	Recommende d	cp053848 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000600J WJNP, EG001200J WJNQ, EG000600JX LVV, EG001200JX LWA and EG001200M XJQU Drives	2	HPD8	Recommende d	cp055388 .exe	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO000960J WZJF, VO001920J WZJH, VO003840J WZJK, VO007680J WZJL and VO015360J WZJN Drives	3	HPD4 (E)	Recommende d	firmware- hdd- 35fd24601 f-HPD4- 5.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB014000J WUDB Drive	3	HPD3 (D)	Recommende d	CP053406 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000600J WJNP, EG001200J WJNQ, EG000600JX LVV, EG001200JX LWA and EG001200M XJQU Drives	5	HPD8	Recommende d	CP055387 .zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware	2	HPD8	Recommende d	CP053890 .zip	new

	ESXi - MB008000J WWQP and MB006000J WWQN Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO000960R WUEV, VO001920R WUFA, VO003840R WUFB, VO007680R WUFC, VO000960R WUFD, VO001920R WUFD, VO001920R WUFD, VO001920R WUFE and VO003840R WUFF Drives	11	HPD7	Recommende d	CP053869 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000JFJ TH Drive	1	HPD5 (B)	Recommende d	cp052957 .exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000J WWQP and MB006000J	1	HPD8	Recommende d	cp053891 .exe	new

	WWQN Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000J WWQP and MB006000J WWQN Drives	1	HPD8 (B)	Recommende d	firmware- hdd- ae6b41e8 55-HPD8- 2.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB010000J WZHA, MB012000J WZHB, MB014000J WZHC and MB016000J WZHE Drives	4	HPD4	Recommende d	firmware- hdd- cf0b6cab e1-HPD4- 1.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO000960J WZJF, VO001920J WZJH, VO003840J WZJK, VO007680J WZJL and VO015360J WZJN Drives	1	HPD4 (D)	Recommende d	cp053722 .exe	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000J WRTD Drive	3	HPD2 (D)	Recommende d	CP053398 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000J WDFD Drive	3	HPD3 (E)	Recommende d	firmware- hdd- aaf1014e de-HPD3- 5.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO000960J WZJF, VO001920J WZJH, VO003840J WZJK, VO007680J WZJL and VO015360J WZJN Drives	4	HPD4 (D)	Recommende d	CP053720 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000J WRTD Drive	3	HPD2 (E)	Recommende d	firmware- hdd- 8b26d1ef 02-HPD2- 5.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash	1	HPD4 (D)	Recommende d	cp052937 .exe	new

	Component for Windows (x64) - MB002000J WFVN and MB004000J WFVP Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000600J WJNP, EG001200J WJNQ, EG000600JX LVV, EG001200JX LWA and EG001200M XJQU Drives	3	HPD8	Recommende d	firmware- hdd- bdfb8e99 d9-HPD8- 1.1.x86_64 .rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000J WRTD Drive	2	HPD2 (D)	Recommende d	cp052945 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO000960R WUEV, VO001920R WUFA, VO003840R WUFB, VO007680R	2	HPD7	Recommende d	cp053870 .exe	new

	WUFC, VO000960R WUFD, VO001920R WUFE and VO003840R WUFF Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB010000G YDKP, MB012000G YCJL, MB014000G YCJT, MB016000G YDKQ and MB018000G YDKR Drives	4	HPG1 (B)	Recommende d	CP053502 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000JEF RB and MM2000JEF RC Drives	4	HPDA (B)	Recommende d	firmware- hdd- b04257b7 7b-HPDA- 2.1.x86_64 .rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB010000J YDKK, MB012000J YCJF,	6	HPD1	Recommende d	CP053994 .zip	new

	MB014000J YCJV, MB016000J YDKL and MB018000J YDKN Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB016000J XLBA and MB018000J XLAU Drives	3	HPD2 (D)	Recommende d	firmware- hdd- d5505233 65-HPD2- 4.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EO000400PX DBQ, EO000800PX DCK, EO001600PX DCH, MO000800P XDBP, MO001600P XDCC, MO003200P XDCD, MO006400P XDCD, MO006400P XDCE, VO000960P XDBN, VO001920P XDBR, VO003840P XDBT, VO007680P XDBU and	3	HPD3 (C)	Recommende	firmware- hdd- 42aff4675 b-HPD3- 3.1.x86_64 .rpm	new

	VO015300P XDBV Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000JEF RB and MM2000JEF RC Drives	2	HPDA (B)	Recommende d	cp052956 .exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH000300J WCPK, EH000600J WCPL and EH000900J WCPN Drives	5	HPD9	Recommende d	CP053495 .zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB016000J WXKH Drive	7	HPDA	Recommende d	cp055195 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB002000J YDNE and	4	HPD2 (C)	Recommende d	CP053343 .zip	new

	MB004000J YDPB Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB006000J YDNF and MB008000J YDPC Drives	5	HPD2 (C)	Recommende d	CP053342 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB002000J WFVN and MB004000J WFVP Drives	5	HPD4 (D)	Recommende d	CP053384 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000J WWQB and MB002000J WWQA Drives	1	HPD8	Recommende d	cp053940 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000JFJ TH Drive	4	HPD5 (B)	Recommende d	firmware- hdd- fa46c607 d6-HPD5- 2.1.x86_64 .rpm	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB016000J XLBA and MB018000J XLAU Drives	4	HPD2 (C)	Recommende d	CP053456 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB010000J YDKK, MB012000J YCJF, MB014000J YCJV, MB016000J YDKL and MB018000J YDKN Drives	2	HPD1	Recommende d	firmware- hdd- 8173816d 98-HPD1- 1.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB016000J XLBA and MB018000J XLAU Drives	1	HPD2 (C)	Recommende d	cp052977 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) -	1	HPD3 (D)	Recommende d	cp052959 .exe	new

	MB012000J WDFD Drive					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000JEF RB and MM2000JEF RC Drives	6	HPDA (B)	Recommende d	CP053416 .zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB010000J YDKK, MB012000J YCJF, MB014000J YCJV, MB016000J YDKL and MB018000J YDKN Drives	1	HPD1	Recommende d	cp053995 .exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG001800J WJNR, EG002400J WJNT, EG001800JX LWB, EG002400JX LWB, EG002400JX LWC and EG002400M XJQT Drives	1	HPDA (B)	Recommende d	firmware- hdd- b1c9eaf7 4c-HPDA- 2.1.x86_64 .rpm	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000J WWQB and MB002000J WWQA Drives	2	HPD8	Recommende d	CP053939 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB010000J WZHA, MB012000J WZHB, MB014000J WZHC and MB016000J WZHE Drives	7	HPD4	Recommende d	CP053847 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH000300J WCPK, EH000600J WCPL and EH000900J WCPN Drives	2	HPD9	Recommende d	cp055383 .exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi -	4	HPDA (B)	Recommende d	CP055733 .zip	update

	EG001800J WJNR, EG002400J WJNT, EG001800JX LWB, EG002400JX LWC and EG002400M XJQT Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000J WWQB and MB002000J WWQA Drives	1	HPD8 (B)	Recommende d	firmware- hdd- adb3ab8 147- HPD8- 2.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000JFJ TH Drive	4	HPD5 (B)	Recommende d	CP053418 .zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB010000G YDKP, MB012000G YCJL, MB014000G YCJT, MB016000G YDKQ and MB018000G	4	HPG1 (B)	Recommende d	firmware- hdd- 4fbb6d96 e5-HPG1- 2.1.x86_64 .rpm	new

	YDKR Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB002000J WFVN and MB004000J WFVP Drives	3	HPD4 (E)	Recommende d	firmware- hdd- d7af557f4 7-HPD4- 5.1.x86_64 .rpm	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000J WDFD Drive	3	HPD3 (D)	Recommende d	CP053422 .zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH000300J WCPK, EH000600J WCPL and EH000900J WCPN Drives	2	HPD9	Recommende d	firmware- hdd- 3d977591 11-HPD9- 1.1.x86_64 .rpm	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG001800J WJNR, EG002400J	1	HPDA (B)	Recommende d	cp055734 .exe	update

	WJNT, EG001800JX LWB, EG002400JX LWC and EG002400M XJQT Drives					
Firmware - Storage Controller	HPE D3600B/D37 00B/D3610B/ D3710B 12Gb SAS Disk Enclosure ROM Flash Component for Linux (x64)	3	6.0	Recommende d	firmware- d3000- 6.0- 1.1.x86_64 .rpm	new
Firmware - Storage Controller	HPE D3600B/D37 00B/D3610B/ D3710B 12Gb SAS Disk Enclosure ROM Flash Component for Windows (x64)	3	6.0	Recommende d	cp054694 .exe	new
Firmware - Storage Controller	Firmware Package - HPE MR216i-o Gen11 Tri Mode Controller	2	52.22.3- 4650 (C)	Recommende d	HPE_MR2 16i- o_Gen11 _52.22.3- 4650_C.f wpkg	new
Firmware - Storage Controller	Firmware Package - HPE MR416i-o Gen11 Tri Mode Controller	2	52.22.3- 4650 (C)	Recommende d	HPE_MR4 16i- o_Gen11 _52.22.3- 4650_C.f wpkg	new

		ı	T			
Firmware - Storage Controller	Firmware Package - HPE Gen11 Boot Controller NS204i-u, NS204i-d and HPE Gen10 Plus Boot Controller NS204i-p, NS204i-d, NS204i-t, NS204i-t,	8	1.2.14.1 009	Recommende d	HPE_NS20 4i_Gen10 P_Gen11_ 1.2.14.100 9_A.fwpk g	new
Firmware - Storage Controller	HPE D3600/D370 0/D3610/D37 10 12Gb SAS Disk Enclosure ROM Flash Component for Linux (x64)	6	5.04 (F)	Recommende d	firmware- d3000- 5.04- 6.1.x86_64 .rpm	new
Firmware - Storage Controller	HPE D3600/D370 0/D3610/D37 10 12Gb SAS Disk Enclosure ROM Flash Component for Windows (x64)	4	5.04 (F)	Recommende d	cp054932 .exe	new
Firmware - Storage Controller	Firmware Package - HPE Smart Array P408i- p, P408e-p, P408i-a, P408i-c, E208i-p, E208e-p, E208i-c, E208i-a,	7	5.61 (B)	Recommende d	HPE_SR_G en10_5.61 _B.fwpkg	new

	P408e-m, P204i-c and P816i-a SR Gen10 and Gen11 controllers					
Firmware - Storage Controller	Firmware Package - HPE MR416i-p Gen11 Tri Mode Controller	3	52.22.3- 4650 (C)	Recommende d	HPE_MR4 16i- p_Gen11 _52.22.3- 4650_C.f wpkg	new
Firmware - Storage Controller	Firmware Package - HPE MR408i-o Gen11 Tri Mode Controller	3	52.22.3- 4650 (C)	Recommende d	HPE_MR4 08i- o_Gen11 _52.22.3- 4650_C.f wpkg	new
Firmware - Storage Controller	Firmware Package - HPE SR932i- p Gen10 Plus /SR416i-a Gen10 Plus/SR932i- p Gen11/SR41 6ie-m Gen11 Controllers	14	03.01.1 7.056 (B)	Recommende d	HPE_SR41 6_SR932_ Gen10P_ Gen11_03 .01.17.056 _B.fwpkg	new
Firmware - Storage Controller	Firmware Package - HPE MR216i-p Gen11 Tri Mode Controller	2	52.22.3- 4650 (C)	Recommende d	HPE_MR2 16i- p_Gen11 _52.22.3- 4650_C.f wpkg	new
Firmware - Lights-Out Management	Online ROM Flash Component for Linux -	20	1.30	Optional	firmware- ilo6-1.30- 1.1.x86_64 .rpm	new

	HPE Integrated Lights-Out 6					
Firmware - Lights-Out Management	Online ROM Flash Component for Windows x64 - HPE Integrated Lights-Out 6	20	1.30	Optional	cp054723 .exe	new
Firmware - Lights-Out Management	Online ROM Flash Firmware Package - HPE Integrated Lights-Out 6	22	1.30	Optional	ilo6_130.f wpkg	new
Firmware - Power Management	ROM Flash Firmware Package - Advanced Power Capping Microcontroll er Firmware for HPE Gen11 Servers	5	1.0.2	Recommende d	PICGen11 -1.0.2- 1.fwpkg	new
Firmware - Power Management	Online ROM Flash for Linux - Advanced Power Capping Microcontroll er Firmware for HPE Gen11 Servers	5	1.0.2	Recommende d	firmware- powerpic -gen11- 1.0.2- 1.1.x86_64 .rpm	new
Firmware - Power Management	Online ROM Flash for Windows x64	5	1.0.2	Recommende d	cp054490 .exe	new

	- Advanced Power Capping Microcontroll er Firmware for HPE Gen11 Servers					
Firmware - Network	Intel Online Firmware Upgrade Utility for Windows Server x64 Editions	2	5.3.3.0	Recommende d	cp055492 .exe	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Eth ernet 100Gb 2-port QSFP56 PCIe4 x16 MCX653106 A-ECAT Adapter: HPE part numbers P23666-B21 and P23666-H21	2	20.36.1 010	Recommende d	20_36_101 0- MCX6531 06A- ECA_HPE _Ax.pldm. fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A- CCAT Adapter:	3	16.35.1 012	Recommende d	16_35_101 2- MCX515A - CCA_HPE _Ax.pldm. fwpkg	new

	HPE part numbers P31246-B21 and P31246- H21					
Firmware - Network	Intel Online Firmware Upgrade Utility for Linux x86_64	3	1.27.0	Recommende d	firmware- nic-is- intel- 1.27.0- 1.1.x86_64 .rpm	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Etherne t 200Gb 1- port QSFP56 PCIe4 x16 MCX653105 A-HDAT Adapter: HPE part numbers P23664-B21 and P23664-H21	2	20.36.1 010	Recommende d	20_36_101 0- MCX6531 05A- HDA_HPE _Ax.pldm. fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for Mellanox MCX623106 AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE	6	22.35.1 012	Recommende d	22_35_101 2- MCX6231 06AS- CDA_Ax. pldm.fwp kg	new
Firmware - Network	Intel Firmware	2	4.10	Recommende d	HPE_E810 _XXVDA2	new

	Package For E810- XXVDA2 Ethernet 10/25Gb 2- port SFP28 OCP3 Adapter				_SD_OCP _4p10_N CSIWPLD MOMCTP_ 8001518D .fwpkg	
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE OPA adapters	2	1.12.0 (A)	Recommende d	firmware- nic- cornelis- opa-hfi- 1.12.0- 2.1.x86_64 .rpm	update
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Etherne t 200Gb 2- port QSFP56 PCIe4 x16 MCX653106 A-HDAT Adapter: HPE part numbers P31324-B21 and P31324-H21	2	20.36.1 010	Recommende d	20_36_101 0- MCX6531 06A- HDA_HPE _Ax.pldm. fwpkg	new
Firmware - Network	Intel Firmware Package For E810- 2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter	2	4.10	Recommende d	HPE_E810 _2CQDA2 _O_SEC_4 p10_PLD MoMCTP_ 8001518B. fwpkg	new

Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Eth ernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105 A-ECAT Adapter: HPE part numbers P23665-B21 and P23665-H21	2	20.36.1 010	Recommende d	20_36_101 0- MCX6531 05A- ECA_HPE _Ax.pldm. fwpkg	new
Firmware - Network	Broadcom Firmware Package for BCM5750x adapters	6	224.1.1 02.0	Recommende d	bcm224.1 .102.0_Th or.pup.fw pkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for Mellanox MCX623105 AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE	7	22.35.1 012	Recommende d	22_35_101 2- MCX6231 05AS- VDA_Ax.p Idm.fwpk g	new
Firmware - Network	Broadcom NX1 Online Firmware Upgrade Utility for Linux x86_64	8	2.32.3	Recommende d	firmware- nic-bcm- open- 2.32.3- 1.1.x86_64 .rpm	new

Firmware - Network	Broadcom NX1 Online Firmware Upgrade Utility for Windows Server x64 Editions	8	5.3.3.0	Recommende d	cp054669 .exe	new
Firmware - Network	Intel Firmware Package For E810- XXVDA4 Ethernet 10/25Gb 4- port SFP28 MCLK Adapter	1	4.10	Recommende d	HPE_E810 _XXV4T_O _SEC_4p1 0_PLDMo MCTP_80 015189.fw pkg	new
Firmware - Network	Broadcom Firmware Package for BCM5741x adapters	7	224.1.1 02.0	Recommende d	bcm224.1 .102.0.pu p.fwpkg	new
Firmware - Network	Intel Firmware Package For E810- XXVDA2 Ethernet 10/25Gb 2- port SFP28 Adapter	3	4.10	Recommende d	HPE_E810 _XXVDA2 _SD_4p10 _PLDMoM CTP_8001 5188.fwpk	new
Firmware - Network	Mellanox Firmware Package (FWPKG) - Mellanox MCX631102 AS-ADAT Ethernet 10/25Gb 2- port SFP28	7	26.35.1 012	Recommende d	26_35_101 2- MCX6311 02AS- ADA_Ax. pldm.fwp kg	new

	Adapter for HPE					
Firmware - Network	Intel Firmware Package For E810- CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter	3	4.10	Recommende d	HPE_E810 _CQDA2_ OCP_4p1 0_NCSIwP LDMOMC TP_800151 90.fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Etherne t 200Gb 2- port QSFP56 PCIe4 x16 OCP3 MCX653436 A-HDAI Adapter: HPE part numbers P31348-B21 and P31348-H21	2	20.36.1 010	Recommende d	20_36_101 0- MCX6534 36A- HDA_HPE _Ax.pldm. fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand NDR 1-port OSFP PCIe5 x16 MCX75310A AS-NEAT Adapter: HPE part numbers	3	28.36.1 010	Recommende d	28_36_101 0- MCX7531 0AAS- NEAT_HPE _Ax.pldm. fwpkg	new

	P45641-B21 and P45641- H21					
Firmware - Network	Intel Firmware Package For E810- CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter	4	4.10	Recommende d	HPE_E810 _CQDA2_ 4p10_PLD MoMCTP_ 8001518E. fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Etherne t 200Gb 1- port QSFP56 PCIe4 x16 OCP3 MCX653435 A-HDAI Adapter: HPE part numbers P31323-B21 and P31323-H21	2	20.36.1 010	Recommende d	20_36_101 0- MCX6534 35A- HDA_HPE _Ax.pldm. fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) - Mellanox MCX631432 AS-ADAI Ethernet 10/25Gb 2- port SFP28 OCP3 Adapter for HPE	5	26.35.1 012	Recommende d	26_35_101 2- MCX6314 32AS- ADA_Ax. pldm.fwp kg	new

Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand NDR200 1- port OSFP PCIe5 x16 MCX75310A AS-HEAT Adapter: HPE part numbers P45642-B21 and P45642-H21	2	28.36.1 010	Recommende d	28_36_101 0- MCX7531 0AAS- HEAT_HPE _Ax.pldm. fwpkg	new
Firmware - Network	Intel Online Firmware Upgrade Utility for VMware	4	3.20.0	Recommende d	CP055491 .zip	new
Firmware - Network	Broadcom NX1 Online Firmware Upgrade Utility for VMware	20	1.33.2	Recommende d	CP054668 .zip	new
Firmware - Network	Intel Firmware Package For E810- XXVDA4 Ethernet 10/25Gb 4- port SFP28 Adapter	4	4.10	Recommende d	HPE_E810 _XXVDA4 _FH_4p10 _PLDMoM CTP_8001 518F.fwpk	new
Firmware - Network	Intel Firmware Package For E810- XXVDA4 Ethernet	2	4.10	Recommende d	HPE_E810 _XXV4_O CP_4p10_ NCSIWPL DMOMCT	new

	10/25Gb 4- port SFP28 OCP3 Adapter				P_800151 8A.fwpkg	
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - EO000400K YDKV and EO000800K YDLA Drives	5	4IASH PK3	Recommende d	firmware- hdd- 6758a46e b7- 4IASHPK3- 1.1.x86_64 .rpm	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - MZXLR800 HBHQ- 000H3, MZXLR1T6 HBJR- 000H3, MZXLR3T2 HBLS- 000H3, MZXLR6T4 HALA- 000H3, MZXLR12T HALA- 000H3, MZXLR12T HALA- 000H3, MZXLR12T HALA- 000H3, MZXLR17 HBJR- 000H3, MZXLR1T9	2	MPK76 25Q (C)	Recommende	firmware- hdd- 951aefd6 3e- MPK7625 Q- 3.1.x86_64 .rpm	new

	HALA- 000H3 and MZXLR15T HALA- 000H3 Drive					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - EO000400K YDKV and EO000800K YDLA Drives	9	4IASH PK3	Recommende d	CP053791 .zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - VO001920K YDMT, VO003840K YDMV, MO001600K YDMU, MO003200K YDNC, MO006400K YDND, VO007680K YDNA and VO015360K YDNB Drives	2	HPK2	Recommende d	firmware- hdd- a27c9566 3d-HPK2- 1.1.x86_64 .rpm	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - MZXLR800 HBHQ-	1	MPK76 25Q (C)	Recommende d	cp053727 .exe	new

	000H3, MZXLR1T6 HBJR- 000H3, MZXLR3T2 HBLS- 000H3, MZXLR6T4 HALA- 000H3, MZXLR12T HALA- 000H3, MZXLR1960 HBHQ- 000H3, MZXLR1T9 HBJR- 000H3, MZXLR1T9 HBJR- 000H3, MZXLR3T8 HBLS- 000H3, MZXLR3T8 HBLS- 000H3, MZXLR3T8 HBLS- 000H3, MZXLR1T5 HALA-					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - VO001920K YDMT, VO003840K YDMV, MO001600K YDMU, MO003200K YDNC, MO006400K YDND, VO007680K YDNA and VO015360K	1	НРК2	Recommende d	cp054553 .exe	new

	YDNB Drives					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - EO000400K YDKV and EO000800K YDLA Drives	4	4IASH PK3	Recommende d	cp053792 .exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - MZXLR800 HBHQ- 000H3, MZXLR1T6 HBJR- 000H3, MZXLR3T2 HBLS- 000H3, MZXLR6T4 HALA- 000H3, MZXLR12T HALA- 000H3, MZXLR12T HALA- 000H3, MZXLR12T HALA- 000H3, MZXLR179 HBJR- 000H3, MZXLR1T9 HBJR- 000H3, MZXLR3T8 HBLS- 000H3, MZXLR7T6 HALA- 000H3 and	4	MPK76 25Q (C)	Recommende	CP053726 .zip	new

	MZXLR15T HALA-000H Drive					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - VO001920K YDMT, VO003840K YDMV, MO001600K YDMU, MO003200K YDNC, MO006400K YDND, VO007680K YDNA and VO015360K YDNB Drives	5	HPK2	Recommende d	CP054552 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB014000G WUDA Drive	3	HPG2 (H)	Recommende d	CP053404 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK000480G WXFF, MK000960G WXFH, MK001920G WXFK and	3	HPG2 (D)	Recommende d	firmware- hdd- 8e1e8083 c5-HPG2- 4.1.x86_64 .rpm	new

	MK003840G WXFL Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240G XAWE, VK000480G XAWK, VK000960G XAWL, VK001920G XAWN, VK003840G XAWP, VK007680G XAWP, VK007680G XAWP, MK000480G XAWF, MK000960G XAWF, MK000960G XAWR, MK003840G XAWR, MK003840G XAWR, MK003840G XAWR, MK003840G XAWR, MK003840G XAWT, VR000240G XBBL, MR000480G XBGH And MR000960G XBGK Drives	1	HPG1 (D)	Recommende	cp052976 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000G WKGV Drive	7	HPG1 (H)	Recommende d	CP053386 .zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB001000G WFWK and MB002000G WFWL Drives	4	HPG6 (H)	Recommende d	CP053380 .zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB001000G WJAN, MB002000G WFWA and MB004000G WFWB Drives	4	HPG1 (H)	Recommende d	CP053382 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240G WTSV, VK000480G WTTA, VK000960G WTTB, VK001920G WTTC, VK003840G WTTD, MK000480G WTTH, MK000960G WTTH, MK000960G WTTK, MK001920G WTTL and	3	HPG6 (F)	Recommende d	firmware- hdd- c566d63c a0-HPG6- 6.1.x86_64 .rpm	new

	MK003840G WTTN Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM2000GE FRA Drive	4	HPG9 (B)	Recommende d	CP053412 .zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB014000G WUDA Drive	2	HPG2 (H)	Recommende d	firmware- hdd- 41cdb1c9 da-HPG2- 8.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB001000G WFWK and MB002000G WFWL Drives	1	HPG6 (G)	Recommende d	cp052935 .exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000G WWQH, MB002000G WWQF and MB001000G	3	HPG5 (B)	Recommende d	firmware- hdd- 12304c1a ca-HPG5- 2.1.x86_64 .rpm	new

	WWQE Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000G WWQH, MB002000G WWQF and MB001000G WWQE Drives	1	HPG5 (B)	Recommende d	cp052963 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB016000G WXKK Drive	3	HPG4	Recommende d	firmware- hdd- e4f147cd d2-HPG4- 1.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000G WDFE Drive	6	HPG3 (D)	Recommende d	CP053400 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK000480G WSSC, MK000960G WSSD, MK001920G	5	HPG3 (E)	Recommende d	CP053430 .zip	new

	WSSE and MK003840G WSSF Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB016000G WXKK Drive	3	HPG4	Recommende d	CP053446 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB001000G WJAN, MB002000G WFWA and MB004000G WFWB Drives	2	HPG1 (I)	Recommende d	firmware- hdd- d39e7a7e 75-HPG1- 9.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM2000GE FRA Drive	4	HPG9 (B)	Recommende d	firmware- hdd- ec908c36 50-HPG9- 2.1.x86_64 .rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB012000G WTFE and MB014000G WTFF Drives	1	HPG8	Recommende d	cp054182 .exe	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB012000G WDFE Drive	1	HPG3 (D)	Recommende d	cp052947 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000G WKGV Drive	1	HPG1 (G)	Recommende d	cp052938 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB016000G WXKK Drive	6	HPG4	Recommende d	cp055196 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB006000G WKGR Drive	2	HPG1 (H)	Recommende d	firmware- hdd- 7f2a26e6 d0-HPG1- 8.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000GFJ TE Drive	4	HPG6 (B)	Recommende d	firmware- hdd- 95af9a55 5e-HPG6- 2.1.x86_64 .rpm	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240G XAWE, VK000480G XAWK, VK000960G XAWL, VK001920G XAWN, VK003840G XAWP, VK007680G XAWP, VK007680G XAWP, VK007680G XAWP, VK007680G XAWY, MK000960G XAWF, MK000960G XAXB,MK0 01920GXAW R, MK003840G XAWT, VR000240G XBBL, MR000480G XBGH and MR000960G XBGK Drives	5	HPG1 (D)	Recommende	CP053453 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK000480G WSSC, MK000960G WSSD, MK001920G WSSE and MK003840G WSSF Drives	3	HPG3 (F)	Recommende d	firmware- hdd- f693ccc1 38-HPG3- 6.1.x86_64 .rpm	new

	1	T	T	T	T	
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK000480G WXFF, MK000960G WXFH, MK001920G WXFK and MK003840G WXFL Drives	5	HPG2 (C)	Recommende d	CP053458 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000480G ZCNE, VK000960G ZCNF, VK001920G ZCNH and VK003840G ZCNK Drives	6	HPG2 (C)	Recommende d	CP053478 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000G WTFE and MB014000G WTFF Drives	4	HPG8	Recommende d	CP054181 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux	3	HPG1 (H)	Recommende d	firmware- hdd- ca21e169 e2-HPG1-	new

	(x64) - MB004000G WKGV Drive				8.1.x86_64 .rpm	
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000480G ZCNE, VK000960G ZCNF, VK001920G ZCNH and VK003840G ZCNK Drives	1	HPG2 (C)	Recommende d	cp052985 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000G WWQH, MB002000G WWQF and MB001000G WWQE Drives	3	HPG5 (B)	Recommende d	CP053428 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB014000G WUDA Drive	1	HPG2 (G)	Recommende d	cp052949 .exe	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240G WSRQ, VK000480G WSRR, VK000960G WSRT, VK001920G WSRU and VK003840G WSRV Drives	3	HPG4 (F)	Recommende d	firmware- hdd- db687966 b4-HPG4- 6.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB001000G WFWK and MB002000G WFWL Drives	2	HPG6 (H)	Recommende d	firmware- hdd- bfc4af697 b-HPG6- 8.1.x86_64 .rpm	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000GFJ TE Drive	1	HPG6 (B)	Recommende d	cp052955 .exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB006000G WKGR Drive	7	HPG1 (H)	Recommende d	CP053392 .zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000G WDFE Drive	3	HPG3 (E)	Recommende d	firmware- hdd- 059b8654 a6-HPG3- 5.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000G WTFE and MB014000G WTFF Drives	3	HPG8	Recommende d	firmware- hdd- b78255e1 46-HPG8- 1.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000480G ZCNE, VK000960G ZCNF, VK001920G ZCNH and VK003840G ZCNK Drives	3	HPG2 (D)	Recommende d	firmware- hdd- befd42bd 64-HPG2- 4.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000G WRTC Drive	3	HPG1 (G)	Recommende d	cp052944 .exe	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB006000G WKGR Drive	2	HPG1 (G)	Recommende d	cp052941 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB001000G WJAN, MB002000G WFWA and MB004000G WFWB Drives	1	HPG1 (G)	Recommende d	cp052936 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM2000GE FRA Drive	1	HPG9 (B)	Recommende d	cp052954 .exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240G WSRQ, VK000480G WSRR, VK000960G WSRT, VK001920G WSRU and VK003840G	1	HPG4 (E)	Recommende d	cp052965 .exe	new

	WSRV Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MK000480G WSSC, MK000960G WSSD, MK001920G WSSE and MK003840G WSSF Drives	1	HPG3 (E)	Recommende d	cp052964 .exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000G WRTC Drive	4	HPG1 (H)	Recommende d	CP053396 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240G WTSV, VK000480G WTTA, VK000960G WTTB, VK001920G WTTC, VK003840G WTTD, MK000480G WTTH, MK000960G WTTH, MK000960G	4	HPG6 (E)	Recommende d	CP053424 .zip	new

	WTTL and MK003840G WTTN Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000G WRTC Drive	3	HPG1 (H)	Recommende d	firmware- hdd- 82894b9e 0a-HPG1- 8.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000GFJ TE Drive	4	HPG6 (B)	Recommende d	CP053414 .zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240G WSRQ, VK000480G WSRR, VK000960G WSRT, VK001920G WSRU, VK003840G WSRV Drives	4	HPG4 (E)	Recommende d	CP053432 .zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) -	1	HPG2 (C)	Recommende d	cp052978 .exe	new

	MK000480G WXFF, MK000960G WXFH, MK001920G WXFK and MK003840G WXFL Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240G XAWE, VK000480G XAWK, VK000960G XAWL, VK001920G XAWN, VK003840G XAWP, VK007680G XAWP, MK000480G XAWF, MK0003840G XAWT, VR000240G XBBL, MR000480G XBGH And MR000960G XBGK Drives	3	HPG1 (E)	Recommende	firmware- hdd- 8f9bf2330 6-HPG1- 5.1.x86_64 .rpm	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component	1	HPG6 (E)	Recommende d	cp052961 .exe	new

	for Windows (x64) - VK000240G WTSV, VK000480G WTTA, VK000960G WTTB, VK001920G WTTC, VK003840G WTTD, MK000480G WTTH, MK000960G WTTK, MK001920G WTTK, MK001920G WTTL and MK003840G WTTL and MK003840G WTTN Drives					
Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex 32Gb and 64Gb Fibre Channel Host Bus Adapters	3	14.0.49 9.29	Recommende d	P14.0.499. 29_heade r.pldm.fw pkg	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters - Linux (x86_64)	1	2023.04	Recommende d	firmware- fc-qlogic- 2023.04.0 1- 1.1.x86_64 .rpm	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 8.0	2	2023.04 .01	Recommende d	CP054986 .zip	new

Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 7.0	2	2023.04	Recommende d	CP054985 .zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters - Microsoft Windows Server 2019/2022 (x86_64)	2	2023.04 .01	Recommende d	cp054988 .exe	new
Operating System - Enhancements	AMD PSHED Plugin service for Microsoft Windows Server 2019	1	1.0.0.49 (B)	Recommende d	cp055810 .exe	new
Operating System - Enhancements	AMD PSHED Plug- in service for Microsoft Windows Server 2022	1	1.0.0.49 (B)	Recommende d	cp055811 .exe	new
Software - Storage Fibre Channel	HPE Emulex Smart SAN Enablement Kit for Linux	2	1.0.0.0- 4 (b)	Optional	hpe- emulex- smartsan- enablem ent-kit- 1.0.0.0- 4.x86_64.r pm	new
Software - Storage Fibre Channel	HPE QLogic Smart SAN Enablement	4	1.0.0.1 (b)	Optional	cp054362 .exe	new

	Kit for Fibre Channel Host Bus Adapter for Microsoft Windows Server 2022 (x86_64)					
Software - Storage Fibre Channel	HPE QLogic Fibre Channel driver component for VMware vSphere 8.0	6	2023.03 .01	Recommende d	cp054352 .zip	new
Software - Storage Fibre Channel	HPE Emulex Fibre Channel Enablement Kit for Host Bus Adapters for Red Hat Enterprise Linux 8 Server	4	14.0.49 9.28	Recommende d	HPE-CNA- FC- Emulex- Enablem ent-Kit- 14.0.499.2 8- 1.rhel8.x8 6_64.rpm	new
Software - Storage Fibre Channel	HPE Emulex Fibre Channel Smart SAN Enablement Kit for Host Bus Adapters for Microsoft Windows Server 2022 (x86_64)	4	1.0.0.1 (b)	Optional	cp054345 .exe	new
Software - Storage Fibre Channel	Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux - Red Hat Enterprise	2	4.2-1 (b)	Optional	fibreutils- 4.2- 1_rhel.x86 _64.rpm	new

	Linux (RHEL)					
Software - Storage Fibre Channel	HPE QLogic Smart SAN Enablement kit for Linux	4	3.3-3 (b)	Optional	hpe- qlogic- smartsan- enablem ent-kit- 3.3- 3.x86_64.r pm	new
Software - Storage Fibre Channel	HPE Emulex Fibre Channel Enablement Kit for Host Bus Adapters for SuSE Linux Enterprise Server 15	4	14.0.49 9.28	Recommende d	HPE-CNA-FC-Emulex-Enablement-Kit-14.0.499.28-1.sles15sp4.x86_64.rpm	new
Software - Storage Fibre Channel	HPE QLogic Fibre Channel Enablement Kit for Host Bus Adapter for Linux	6	6.0.0.0- 18 (b)	Optional	HPE-CNA- FC- hpeqlgc- Enablem ent-Kit- 6.0.0.0- 18.noarch .rpm	new
Software - Storage Fibre Channel	HPE QLogic Smart SAN Enablement Kit for Fibre Channel Host Bus Adapter for Microsoft Windows Server 2019 (x86_64)	4	1.0.0.1 (b)	Optional	cp054363 .exe	new
Software - Storage Fibre Channel	HPE Storage Emulex Fibre Channel driver	3	2023.03	Recommende d	cp054347 .zip	new

	component for VMware vSphere 7.0					
Software - Storage Fibre Channel	HPE Emulex Fibre Channel Smart SAN Enablement Kit for Host Bus Adapters for Microsoft Windows Server 2019 (x86_64)	5	1.0.0.1 (b)	Optional	cp054346 .exe	new
Software - Storage Fibre Channel	Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux - SuSE Linux Enterprise Server(SLES)	2	4.2-1 (b)	Optional	fibreutils- 4.2- 1_sles.x86 _64.rpm	new
Software - Storage Fibre Channel	HPE QLogic Fibre Channel driver component for VMware vSphere 7.0	5	2023.03 .01	Recommende d	cp054353 .zip	new
Software - System Management	Agentless Management Service (iLO5, iLO 6) for SUSE Linux Enterprise Server 15	7	3.3.0	Optional	amsd- 3.3.0- 1773.7.sle s15.x86_6 4.rpm	update
Software - System Management	HPE Gen11 Agentless Management Service for	15	3.30.0.0	Optional	cp054819 .exe	new

	Microsoft Windows x64					
Software - System Management	HPE MegaRAID Storage Administrator StorCLI for Windows 64- bit (for Gen10P and Gen11 Controllers)	7	7.22.7.0 (C)	Recommende d	cp055450 .exe	new
Software - System Management	HPE MegaRAID Storage Administrator StorCLI for Linux 64-bit (for Gen10P and Gen11 Controllers)	14	007.220 7.0000. 0000 (C)	Optional	storcli- 007.2207. 0000.0000 - 1.noarch. rpm	new
Software - System Management	Smart Storage Administrator Diagnostic Utility (SSADU) CLI for Windows 64- bit for Gen10/Gen10 Plus/Gen11 Controllers	4	6.15.11. 0 (C)	Recommende d	cp055523 .exe	new
Software - System Management	Smart Storage Administrator Diagnostic Utility (SSADU) CLI for Linux 64-bit for Gen10/Gen10	2	6.15.11. 0 (C)	Recommende d	ssaducli- 6.15- 11.0.x86_6 4.rpm	new

	Plus/Gen11 Controllers					
Software - System Management	Smart Storage Administrator (SSA) for Windows 64- bit for Gen10/Gen10 Plus/Gen11 Controllers	2	6.15.11. 0 (C)	Recommende d	cp055522 .exe	new
Software - System Management	Agentless Management Service (iLO 5, iLO 6) for Red Hat Enterprise Linux 9 Server	7	3.3.0	Optional	amsd- 3.3.0- 1773.7.rhe 19.x86_64.r pm	new
Software - System Management	HPE MegaRAID Storage Administrator for Linux 64- bit (HPE MRSA for Gen10P and Gen11 Controllers)	6	8.2.19.0 (C)	Recommende d	MRStorag eAdminist rator- 008.002.0 19.000- 00.x86_64. rpm	new
Software - System Management	Smart Storage Administrator (SSA) CLI for Linux 64- bit for Gen10/Gen10 Plus/Gen11 Controllers	2	6.15.11. 0 (C)	Recommende d	ssacli- 6.15- 11.0.x86_6 4.rpm	new
Software - System Management	Agentless Management Service (iLO5, iLO	23	3.3.0	Optional	amsd- 3.3.0- 1773.23.rh	new

	6) for Red Hat Enterprise Linux 8 Server				el8.x86_64 .rpm	
Software - System Management	Smart Storage Administrator (SSA) CLI for Windows 64-bit for Gen10/Gen10 Plus Controllers	2	6.15.11. 0 (C)	Recommende d	cp055518 .exe	new
Software - System Management	Smart Storage Administrator (SSA) for Linux 64-bit for Gen10/Gen10 Plus/Gen11 Controllers	2	6.15.11. 0 (C)	Recommende d	ssa-6.15- 11.0.x86_6 4.rpm	new
Software - System Management	HPE MegaRAID Storage Administrator for Windows 64-bit (HPE MRSA for Gen10P and Gen11 Controllers)	4	8.2.19.0 (C)	Recommende d	cp055453 .exe	new
Software - Lights-Out Management	HPE Lights- Out Online Configuration Utility for Linux (AMD64/EM 64T)	6	6.0.0-0	Optional	hponcfg- 6.0.0- 0.x86_64.r pm	update

Software - Lights-Out Management	HPE Lights- Out Online Configuration Utility for Windows x64 Editions	6	6.0.0.0	Optional	cp049814 .exe	update
Software - Management	HPE Fiber Channel and Storage Enablement Bundle Smart Component for ESXi 8.0	14	2022.09	Recommende d	cp051152 .zip	new
Software - Management	HPE Fiber Channel and Storage Enablement Bundle Smart Component for ESXi 7.0	8	2022.09	Recommende d	cp050934 .zip	new
Software - Management	HPE iLO Driver Bundle Smart Component for ESXi 7.0	13	2022.09	Recommende d	cp050763 .zip	new
Software - Management	Smart Storage Administrator (SSA) CLI Smart Component for ESXi 8.0 for Gen10/Gen10 Plus/Gen11 Controllers	2	2023.04 .01	Recommende d	cp055513 .zip	new
Software - Management	Smart Storage Administrator (SSA) CLI Smart Component	2	2023.04	Recommende d	cp055515 .zip	new

	for ESXi 7.0 for Gen10/Gen10 Plus/Gen11 Controllers					
Software - Management	HPE Agentless Management Bundle Smart Component on ESXi for Gen11 Servers	13	2023.04	Recommende d	cp054826 .zip	new
Software - Storage Controller	HPE MegaRAID Storage Administrator StorCLI for VMware7.0 (For Gen10P and Gen11 Controllers)	8	2023.04 .01	Recommende d	cp055452 .zip	new

There are 335 items in this table.