Gen11 Service Pack for ProLiant version 2023.02.00.00 Contents

Product Category	Description	Build #	Version	Upgrade Requirement	Filename	Release Status
Application - System Management	Integrated Smart Update Tools for Windows x64	11	4.0.0.0	Recommended	cp051727.exe	update
Application - System Management	Integrated Smart Update Tools 4.0.0 for ESXi 7.0	8	2022.11.0	Recommended	cp051748.zip	new
Application - System Management	Integrated Smart Update Tools for Linux x64	22	4.0.0.0	Recommended	sut-4.0.0- 22.linux.x86_6 4.rpm	update
Application - System Management	Integrated Smart Update Tools 4.0.0 for ESXi 8.0	10	2022.11.0	Recommended	cp051794.zip	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant ML350/DL360/DL380 Gen11 (U54) Servers	1	1.22_01- 18-2023	Recommended	cp055894.exe	new
BIOS - System ROM	ROM Flash Universal Firmware Package - HPE ProLiant DL365/DL385 Gen11 (A55) Servers	7	1.20_01- 06-2023	Recommended	A55_1.20_01_0 6_2023.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant ML350/DL360/DL380 Gen11 (U54) Servers	1	1.22_01- 18-2023	Recommended	firmware- system-u54- 1.22_2023_01_ 18- 1.1.x86_64.rp m	new
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant DL320 Gen11 (U63) Servers	3	1.22_01- 18-2023	Recommended	U63_1.22_01_1 8_2023.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL325/DL345 Gen11 (A56) Servers	6	1.20_01- 06-2023	Recommended	firmware- system-a56- 1.20_2023_01_ 06-	new

		1	T	T		1
					1.1.x86_64.rp m	
BIOS - System ROM	Online ROM Flash Component for Linux - HPE Alletra 4110/Alletra 4120/HPE ProLiant DL380a Gen11 (U58) Servers	2	1.22_01- 18-2023	Recommended	firmware- system-u58- 1.22_2023_01_ 18- 1.1.x86_64.rp m	new
BIOS - System ROM	ROM Flash Universal Firmware Package - HPE ProLiant DL325/DL345 Gen11 (A56) Servers	10	1.20_01- 06-2023	Recommended	A56_1.20_01_0 6_2023.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL325/DL345 Gen11 (A56) Servers	9	1.20_01- 06-2023	Recommended	cp054874.exe	new
BIOS - System ROM	ROM Flash Firmware Package - HPE Alletra 4110/Alletra 4120/ProLiant DL380a Gen11 (U58) Servers	3	1.22_01- 18-2023	Recommended	U58_1.22_01_1 8_2023.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL365/DL385 Gen11 (A55) Servers	6	1.20_01- 06-2023	Recommended	cp054869.exe	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL365/DL385 Gen11 (A55) Servers	6	1.20_01- 06-2023	Recommended	firmware- system-a55- 1.20_2023_01_ 06- 1.1.x86_64.rp m	new
BIOS - System ROM	Online ROM Flash Component for Linux - HPE ProLiant DL320 Gen11 (U63) Servers	2	1.22_01- 18-2023	Recommended	firmware- system-u63- 1.22_2023_01_ 18- 1.1.x86_64.rp m	new

BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE Alletra 4110/Alletra 4120/HPE ProLiant DL380a Gen11 (U58) Servers	2	1.22_01- 18-2023	Recommended	cp055879.exe	new
BIOS - System ROM	ROM Flash Firmware Package - HPE ProLiant ML350/DL360/DL380 Gen11 (U54) Servers	1	1.22_01- 18-2023	Recommended	U54_1.22_01_1 8_2023.fwpkg	new
BIOS - System ROM	Online ROM Flash Component for Windows x64 - HPE ProLiant DL320 Gen11 (U63) Servers	1	1.22_01- 18-2023	Recommended	cp055904.exe	new
Driver - Storage Controller	HPE MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p Gen11 controller Driver for Microsoft Windows 2019 edition	8	7.722.6.0 (B)	Recommended	cp054207.exe	new
Driver - Storage Controller	HPE Smart Array Gen11 Controller Driver for Windows Server 2019 and Windows Server 2022	13	1010.52.0 .1012	Recommended	cp053653.exe	update
Driver - Storage Controller	HPE ProLiant Gen10, Gen10P and Gen11 Smart Array Controller (64-bit) Driver for Red Hat Enterprise Linux 9 (64-bit)	13	2.1.20- 035	Recommended	kmod- smartpqi- 2.1.20- 035.rhel9u0.x8 6_64.rpm	new
Driver - Storage Controller	HPE MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p Gen11 controller (64-bit) Driver for vSphere 7.0	8	2022.11.0 1 (B)	Recommended	cp054206.zip	new
Driver - Storage Controller	HPE ProLiant Gen10, Gen10Plus and Gen11 Smart Array Controller (64-bit) Driver for SUSE LINUX Enterprise Server 15 (64-bit)	12	2.1.20- 035 (B)	Recommended	smartpqi-kmp- default-2.1.20- 035.sles15sp3.x8 6_64.rpm smartpqi-kmp- default-2.1.20- 035.sles15sp4.x8 6_64.rpm	update

Driver - Storage Controller	HPE ProLiant Gen11 Smart RAID Controller Driver for VMware vSphere 8.0 (Driver Component).	14	2023.01.0	Recommended	cp054371.zip	new
Driver - Storage Controller	HPE MR416i-p, MR416i-o, MR216i-o, MR408i-o, MR216i-p Gen11 controller driver for Microsoft Windows 2022 edition	6	7.722.6.0 (B)	Recommended	cp054208.exe	new
Driver - Storage Controller	HPE ProLiant Gen11 Smart RAID Controller Driver for VMware vSphere 7.0 (Driver Component).	9	2023.01.0	Recommended	cp054370.zip	new
Driver - Storage Controller	HPE ProLiant Gen10, Gen10P and Gen11 Smart Array Controller (64-bit) Driver for Red Hat Enterprise Linux 8 (64-bit)	9	2.1.20- 035	Recommended	kmod- smartpqi- 2.1.20- 035.rhel8u6.x8 6_64.rpm	new
Driver - Network	HPE Intel iavf Drivers for SUSE Linux Enterprise Server 15	5	4.5.3-1 (B)	Recommended	hp-iavf-kmp- default- 4.5.3_k5.14.21 _150400.22- 1.sles15sp4.x8 6_64.rpm	update
Driver - Network	HPE Intel igb Drivers for SUSE Linux Enterprise Server 15	7	6.11.4-1 (B)	Recommended	hp-igb-kmp- default- 6.11.4_k5.14.2 1_150400.22- 1.sles15sp4.x8 6_64.rpm	update
Driver - Network	Broadcom NX1 1Gb Driver for Windows Server x64 Editions	5	221.0.4.0 (B)	Recommended	cp053061.exe	new
Driver - Network	Mellanox ConnectX-4, ConnectX-5 and ConnectX-6 "nmlx5_en" Driver Component for VMware ESXi 7.0 Update 2 and Update 3	2	2021.04.2 1 (D)	Recommended	cp054406.zip	new

Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) ConnectX-4, ConnectX-5 and ConnectX-6 Driver for SUSE LINUX Enterprise Server 15 SP4 (AMD64/EM64T)	1	5.7 (A)	Recommended	mlnx- ofa_kernel- 5.7- OFED.5.7.1.0.2 .1.sles15sp4.x8 6_64.rpm mlnx- ofa_kernel- kmp-default- 5.7_k5.14.21_1 50400.22- OFED.5.7.1.0.2 .1.sles15sp4.x8 6_64.rpm	new
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for SUSE Linux Enterprise Server 15	12	3.139i-2	Recommended	tg3-kmp- default- 3.139i_k5.14.2 1_150400.22- 2.sles15sp4.x8 6_64.rpm	update
Driver - Network	Mellanox CX5 and CX6DX Driver for Microsoft Windows Server 2019	2	3.0.25668 .0 (B)	Recommended	cp054506.exe	new
Driver - Network	Intel ice Drivers for Red Hat Enterprise Linux 8	5	1.9.11-1 (C)	Recommended	kmod-ice- 1.9.11- 1.rhel8u6.x86_ 64.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 8 Update 6.	6	223.0.162	Recommended	libbnxt_re- 223.0.162.0- rhel8u6.x86_64 .rpm	new
Driver - Network	Intel ice Drivers for SUSE Linux Enterprise Server 15	6	1.9.11-1 (B)	Recommended	ice-kmp- default- 1.9.11_k5.14.2 1_150400.22- 1.sles15sp4.x8 6_64.rpm	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) ConnectX-4, ConnectX-5 and ConnectX-6 Driver for Red	3	5.7	Recommended	kmod-mlnx- ofa_kernel- 5.7- OFED.5.7.1.0.2 .1.2022092803	new

	Hat Enterprise Linux 9 Update 0 (x86_64)				25.rhel9u0.x86 _64.rpm mlnx- ofa_kernel- 5.7- OFED.5.7.1.0.2 .1.rhel9u0.x86_ 64.rpm	
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for Red Hat Enterprise Linux 9 Update 0.	9	223.0.162	Recommended	libbnxt_re- 223.0.162.0- rhel9u0.x86_64 .rpm	new
Driver - Network	HPE Broadcom NetXtreme-E RoCE Library for SUSE Linux Enterprise Server 15 SP4	7	223.0.162	Recommended	libbnxt_re- 223.0.162.0- sles15sp4.x86_ 64.rpm	new
Driver - Network	Intel icea Driver for Microsoft Windows Server 2022	8	1.12.144. 0 (B)	Recommended	cp054094.exe	new
Driver - Network	HPE Mellanox RoCE (RDMA over Converged Ethernet) ConnectX-4, ConnectX-5 and ConnectX-6 Driver for Red Hat Enterprise Linux 8 Update 6 (x86_64)	1	5.7 (A)	Recommended	mlnx- ofa_kernel- 5.7- OFED.5.7.1.0.2 .1.rhel8u6.x86_ 64.rpm kmod-mlnx- ofa_kernel- 5.7- OFED.5.7.1.0.2 .1.rhel8u6.x86_ 64.rpm	new
Driver - Network	Broadcom NetXtreme-E Driver for Microsoft Windows Server 2019	7	223.0.157 .0	Recommended	cp053062.exe	new
Driver - Network	Broadcom NetXtreme-E Driver for Microsoft Windows Server 2022	8	223.0.157	Recommended	cp053063.exe	new
Driver - Network	HPE Intel iavf Drivers for Red Hat Enterprise Linux 8	5	4.5.3-1 (B)	Recommended	kmod-hp-iavf- 4.5.3- 1.rhel8u6.x86_ 64.rpm	new
	1	1	1	1	1	<u>. </u>

Driver - Network	HPE Broadcom NetXtreme-E Drivers for SUSE Linux Enterprise Server 15	9	1.10.2- 223.0.162 .0	Recommended	bnxt_en-kmp- default- 1.10.2_k5.14.2 1_150400.22- 223.0.162.0.sle s15sp4.x86_64. rpm	update
Driver - Network	Mellanox CX5 and CX6DX Driver for Microsoft Windows Server 2022	2	3.0.25668 .0 (B)		cp054507.exe	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for VMware vSphere 7.0	5	2022.12.0	Recommended	cp053755.zip	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for Red Hat Enterprise Linux 9	10	1.10.2- 223.0.162 .0	Recommended	kmod- bnxt_en- 1.10.2- 223.0.162.0.rh el9u0.x86_64.r pm	new
Driver - Network	Intel i350 Driver for Windows Server 2022	9	13.0.13.0 (B)	Recommended	cp052339.exe	new
Driver - Network	Intel iavf Driver for Windows Server 2022	10	1.13.8.0 (C)	Recommended	cp052340.exe	new
Driver - Network	HPE Intel iavf Drivers for Red Hat Enterprise Linux 9	6	4.5.3-2 (B)	Recommended	kmod-hp-iavf- 4.5.3- 2.rhel9u0.x86_ 64.rpm	new
Driver - Network	HPE Intel igb Drivers for Red Hat Enterprise Linux 9	5	5.11.4-2 (B)	Recommended	kmod-hp-igb- 5.11.4- 2.rhel9u0.x86_ 64.rpm	new
Driver - Network	HPE Intel igbn Driver for VMware vSphere 7.0	11	2023.01.0	Recommended	cp052337.zip	new
Driver - Network	Intel icen Driver for VMware vSphere 7.0	5	2023.01.0	Recommended	cp054525.zip	new

						,
Driver - Network	Intel ice Drivers for Red Hat Enterprise Linux 9	12	1.9.11-2 (B)	Recommended	kmod-ice- 1.9.11- 2.rhel9u0.x86_ 64.rpm	new
Driver - Network	Intel i350 Driver for Windows Server 2019	7	12.18.13. 0 (B)	Recommended	cp052338.exe	new
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 9	12	3.139i-1	Recommended	kmod-tg3- 3.139i- 1.rhel9u0.x86_ 64.rpm	new
Driver - Network	Intel icea Driver for Windows Server 2019	8	1.12.144. 0 (B)	Recommended	cp054093.exe	new
Driver - Network	HPE Broadcom tg3 Ethernet Drivers for Red Hat Enterprise Linux 8	13	3.139i-1	Recommended	kmod-tg3- 3.139i- 1.rhel8u6.x86_ 64.rpm	new
Driver - Network	HPE Intel igb Drivers for Red Hat Enterprise Linux 8	6	6.11.4-1 (B)	Recommended	kmod-hp-igb- 6.11.4- 1.rhel8u6.x86_ 64.rpm	new
Driver - Network	HPE Broadcom NetXtreme-E Drivers for Red Hat Enterprise Linux 8	8	1.10.2- 223.0.162 .0	Recommended	kmod- bnxt_en- 1.10.2- 223.0.162.0.rh el8u6.x86_64.r pm	new
Driver - Network	Intel iavf Driver for Windows Server 2019	6	1.13.8.0 (C)	Recommended	cp054095.exe	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 Emulex Storport Driver for Microsoft Windows Server 2022	3	14.0.534. 0 (b)	Recommended	cp054344.exe	new
Driver - Storage	HPE Storage Fibre Channel Adapter Kit for the x64	5	9.4.6.20 (b)	Recommended	cp054361.exe	new

Fibre Channel and	QLogic Storport Driver for Microsoft Windows Server					
Fibre Channel Over Ethernet	2022					
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 9 Update 1 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	7	14.0.499. 31	Recommended	kmod-elx-lpfc- 14.0.499.31- 1.rhel9u1.x86_ 64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 9 Update 1 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	7	10.02.08. 01-k1	Recommended	kmod-qlgc- qla2xxx- 10.02.08.01_k1 - 1.rhel9u1.x86_ 64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 7 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	7	14.0.499. 31	Recommended	kmod-elx-lpfc- 14.0.499.31- 1.rhel8u7.x86_ 64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 7 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	6	10.02.08. 01-k1	Recommended	kmod-qlgc- qla2xxx- 10.02.08.01_k1 - 1.rhel8u7.x86_ 64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 QLogic Storport Driver for Microsoft Windows Server 2019	6	9.4.6.20 (b)	Recommended	cp054360.exe	new

	T	1	1	T	T	
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 9 Update 0 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	7	14.0.499. 31	Recommended	kmod-elx-lpfc- 14.0.499.31- 1.rhel9u0.x86_ 64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 6 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapter	5	10.02.07. 01-k1	Recommended	kmod-qlgc- qla2xxx- 10.02.07.01_k1 - 2.rhel8u6.x86_ 64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SuSE Linux Enterprise Server 15 Service Pack 4 Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	6	10.02.07. 01-k1	Recommended	qlgc-qla2xxx- kmp-default- 10.02.07.01_k1 _k5.14.21_150 400.22- 2.sles15sp4.x8 6_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	SuSE Linux Enterprise Server 15 Service Pack 4 Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	8	14.0.499. 31	Recommended	elx-lpfc-kmp- default- 14.0.499.31_k5 .14.21_150400. 22- 1.sles15sp4.x8 6_64.rpm	new
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	HPE Storage Fibre Channel Adapter Kit for the x64 Emulex Storport Driver for Microsoft Windows Server 2019	3	14.0.534. 0 (b)	Recommended	cp054343.exe	new
Driver - Storage Fibre Channel and Fibre	Red Hat Enterprise Linux 9 Update 0 Server Fibre Channel Driver Kit for HPE QLogic Host Bus Adapters	7	10.02.07. 01-k1	Recommended	kmod-qlgc- qla2xxx- 10.02.07.01_k1 -	new

Channel Over Ethernet					2.rhel9u0.x86_ 64.rpm	
Driver - Storage Fibre Channel and Fibre Channel Over Ethernet	Red Hat Enterprise Linux 8 Update 6 Server Fibre Channel Driver Kit for HPE Emulex Host Bus Adapters	6	14.0.499. 31	Recommended	kmod-elx-lpfc- 14.0.499.31- 1.rhel8u6.x86_ 64.rpm	new
Driver - System Management	iLO 6 Channel Interface Driver for Microsoft Windows Server 2022	4	4.7.1.0 (B)	Recommended	cp054301.exe	new
Driver - System Management	iLO 6 Automatic Server Recovery Driver for Microsoft Windows Server 2022	4	4.7.1.0 (B)	Recommended	cp054302.exe	new
Driver - System Management	iLO 6 Channel Interface Driver for Microsoft Windows Server 2019	4	4.7.1.0 (B)	Recommended	cp054299.exe	new
Driver - System Management	iLO 6 Automatic Server Recovery Driver for Microsoft Windows Server 2019	4	4.7.1.0 (B)	Recommended	cp054300.exe	new
Driver - Chipset	Identifiers for AMD EPYC Genoa Processors for Microsoft Windows Server 2019	1	4.11.28.1 51	Recommended	cp055530.exe	new
Driver - Chipset	Identifiers for AMD EPYC Genoa Processors for Microsoft Windows Server 2022	1	4.11.28.1 51	Recommended	cp055531.exe	new
Driver - Chipset	Identifiers for Intel Xeon Scalable Processors (Fourth Generation) for Microsoft Windows	5	10.1.1926 3.8344	Recommended	cp053816.exe	new
Driver - Video	Matrox G200eH3 Video Controller Driver for	3	9.15.1.24 8	Recommended	cp054298.exe	new

	Τ					
	Microsoft Windows Server 2019 and 2022					
Driver - Security	Intel QuickAssist Technology driver for Microsoft Windows	16	2.0.10.18	Recommended	cp049982.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB006000JYDNF and MB008000JYDPC Drives	1	HPD2 (C)	Recommended	cp053345.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB010000GYDKP, MB012000GYCJL, MB014000GYCJT, MB016000GYDKQ and MB018000GYDKR Drives	2	HPG1 (B)	Recommended	cp053002.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB002000JYDNE and MB004000JYDPB Drives	3	HPD2 (C)	Recommended	firmware-hdd- d4be2aecbb- HPD2- 3.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000600JWEBH and EG000300JWEBF Drives	2	HPD5 (D)	Recommended	cp052980.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EO000400PXDBQ, EO000800PXDCK, EO001600PXDCH, MO000800PXDBP, MO001600PXDCC, MO003200PXDCD, MO006400PXDCE, VO000960PXDBN, VO001920PXDBR, VO003840PXDBT, VO007680PXDBU and VO015300PXDBV Drives	1	HPD3 (C)	Recommended	cp052991.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO000960RWUEV, VO001920RWUFA,	3	HPD7	Recommended	firmware-hdd- 8fafc9efb2- HPD7-	new

		•	,			,
	VO003840RWUFB, VO007680RWUFC, VO000960RWUFD, VO001920RWUFE and VO003840RWUFF Drives				1.1.x86_64.rp m	
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB006000JYDNF and MB008000JYDPC Drives	3	HPD2 (C)	Recommended	firmware-hdd- b04df66fe9- HPD2- 3.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB016000JWXKH Drive	3	HPD9 (E)	Recommended	firmware-hdd- 8a0371a425- HPD9- 5.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EO000400PXDBQ, EO000800PXDCK, EO001600PXDCH, MO000800PXDBP, MO001600PXDCC, MO003200PXDCD, MO006400PXDCE, VO000960PXDBN, VO001920PXDBN, VO001920PXDBT, VO007680PXDBU and VO015300PXDBV Drives	4	HPD3 (C)	Recommended	CP053486.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB014000JWUDB Drive	2	HPD3 (E)	Recommended	firmware-hdd- cfd7436fcc- HPD3- 5.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB002000JYDNE and MB004000JYDPB Drives	1	HPD2 (C)	Recommended	cp053350.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EH000300JWCPK, EH000600JWCPL and EH000900JWCPN Drives	1	HPD8 (C)	Recommended	cp052996.exe	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB014000JWUDB Drive	2	HPD3 (D)	Recommended	cp052951.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000600JWEBH and EG000300JWEBF Drives	3	HPD5 (D)	Recommended	CP053464.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB010000JWZHA, MB012000JWZHB, MB014000JWZHC and MB016000JWZHE Drives	1	HPD4	Recommended	cp053848.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB016000JWXKH Drive	1	HPD9 (D)	Recommended	cp052971.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VO000960JWZJF, VO001920JWZJH, VO003840JWZJK, VO007680JWZJL and VO015360JWZJN Drives	3	HPD4 (E)	Recommended	firmware-hdd- 35fd24601f- HPD4- 5.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB014000JWUDB Drive	3	HPD3 (D)	Recommended	CP053406.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000JWWQP and MB006000JWWQN Drives	2	HPD8	Recommended	CP053890.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO000960RWUEV, VO001920RWUFA, VO003840RWUFB, VO007680RWUFC, VO000960RWUFD, VO001920RWUFE and VO003840RWUFF Drives	11	HPD7	Recommended	CP053869.zip	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000JFJTH Drive	1	HPD5 (B)	Recommended	cp052957.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000JWWQP and MB006000JWWQN Drives	1	HPD8	Recommended	cp053891.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000JWWQP and MB006000JWWQN Drives	1	HPD8 (B)	Recommended	firmware-hdd- ae6b41e855- HPD8- 2.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB010000JWZHA, MB012000JWZHB, MB014000JWZHC and MB016000JWZHE Drives	4	HPD4	Recommended	firmware-hdd- cf0b6cabe1- HPD4- 1.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO000960JWZJF, VO001920JWZJH, VO003840JWZJK, VO007680JWZJL and VO015360JWZJN Drives	1	HPD4 (D)	Recommended	cp053722.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000JWRTD Drive	3	HPD2 (D)	Recommended	CP053398.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000JWDFD Drive	3	HPD3 (E)	Recommended	firmware-hdd- aaf1014ede- HPD3- 5.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000600JWEBH and EG000300JWEBF Drives	2	HPD5 (E)	Recommended	firmware-hdd- aa9e289524- HPD5- 5.1.x86_64.rp m	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VO000960JWZJF, VO001920JWZJH, VO003840JWZJK, VO007680JWZJL and VO015360JWZJN Drives	4	HPD4 (D)	Recommended	CP053720.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000JWRTD Drive	3	HPD2 (E)	Recommended	firmware-hdd- 8b26d1ef02- HPD2- 5.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB002000JWFVN and MB004000JWFVP Drives	1	HPD4 (D)	Recommended	cp052937.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG000600JWJNP, EG001200JWJNQ, EG000600JXLVV, EG001200JXLWA and EG001200MXJQU Drives	4	HPD7	Recommended	firmware-hdd- bdfb8e99d9- HPD7- 1.1.x86_64.rp m	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000JWRTD Drive	2	HPD2 (D)	Recommended	cp052945.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EH000300JWCPK, EH000600JWCPL and EH000900JWCPN Drives	3	HPD8 (D)	Recommended	firmware-hdd- 3d97759111- HPD8- 4.1.x86_64.rp m	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB010000GYDKP, MB012000GYCJL, MB014000GYCJT, MB016000GYDKQ and MB018000GYDKR Drives	4	HPG1 (B)	Recommended	CP053502.zip	new

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000JEFRB and MM2000JEFRC Drives	4	HPDA (B)	Recommended	firmware-hdd- b04257b77b- HPDA- 2.1.x86_64.rp m	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VO000960RWUEV, VO001920RWUFA, VO003840RWUFB, VO007680RWUFC, VO000960RWUFD, VO001920RWUFE and VO003840RWUFF Drives	2	HPD7	Recommended	cp053870.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB016000JXLBA and MB018000JXLAU Drives	3	HPD2 (D)	Recommended	firmware-hdd- d550523365- HPD2- 4.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB016000JWXKH Drive	4	HPD9 (D)	Recommended	CP053442.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EO000400PXDBQ, EO000800PXDCK, EO001600PXDCH, MO000800PXDBP, MO001600PXDCC, MO003200PXDCD, MO006400PXDCE, VO000960PXDBN, VO001920PXDBN, VO001920PXDBR, VO003840PXDBT, VO007680PXDBU and VO015300PXDBV Drives	3	HPD3 (C)	Recommended	firmware-hdd- 42aff4675b- HPD3- 3.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000JEFRB and MM2000JEFRC Drives	2	HPDA (B)	Recommended	cp052956.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG001800JWJNR,	1	HPD9	Recommended	cp054045.exe	update

	EG002400JWJNT, EG001800JXLWB, EG002400JXLWC and EG002400MXJQT Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - EG000600JWJNP, EG001200JWJNQ, EG000600JXLVV, EG001200JXLWA and EG001200MXJQU Drives	2	HPD7	Recommended	cp054019.exe	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB002000JYDNE and MB004000JYDPB Drives	4	HPD2 (C)	Recommended	CP053343.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB006000JYDNF and MB008000JYDPC Drives	5	HPD2 (C)	Recommended	CP053342.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB002000JWFVN and MB004000JWFVP Drives	5	HPD4 (D)	Recommended	CP053384.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000JWWQB and MB002000JWWQA Drives	1	HPD8	Recommended	cp053940.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000JFJTH Drive	4	HPD5 (B)	Recommended	firmware-hdd- fa46c607d6- HPD5- 2.1.x86_64.rp m	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB016000JXLBA and MB018000JXLAU Drives	4	HPD2 (C)	Recommended	CP053456.zip	new

	т		Т	T		
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB010000JYDKK, MB012000JYCJF, MB014000JYCJV, MB016000JYDKL and MB018000JYDKN Drives	2	HPD1	Recommended	firmware-hdd- 8173816d98- HPD1- 1.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB016000JXLBA and MB018000JXLAU Drives	1	HPD2 (C)	Recommended	cp052977.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - EG001800JWJNR, EG002400JWJNT, EG001800JXLWB, EG002400JXLWC and EG002400MXJQT Drives	3	HPD9	Recommended	firmware-hdd- b1c9eaf74c- HPD9- 1.1.x86_64.rp m	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB012000JWDFD Drive	1	HPD3 (D)	Recommended	cp052959.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000JEFRB and MM2000JEFRC Drives	6	HPDA (B)	Recommended	CP053416.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB010000JYDKK, MB012000JYCJF, MB014000JYCJV, MB016000JYDKL and MB018000JYDKN Drives	1	HPD1	Recommended	cp053995.exe	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000JWWQB and MB002000JWWQA Drives	2	HPD8	Recommended	CP053939.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB010000JWZHA, MB012000JWZHB,	7	HPD4	Recommended	CP053847.zip	new

	T	1	1			,
	MB014000JWZHC and MB016000JWZHE Drives					
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG000600JWJNP, EG001200JWJNQ, EG000600JXLVV, EG001200JXLWA and EG001200MXJQU Drives	6	HPD7	Recommended	CP054018.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000JWWQB and MB002000JWWQA Drives	1	HPD8 (B)	Recommended	firmware-hdd- adb3ab8147- HPD8- 2.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EG001800JWJNR, EG002400JWJNT, EG001800JXLWB, EG002400JXLWC and EG002400MXJQT Drives	4	HPD9	Recommended	CP054027.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000JFJTH Drive	4	HPD5 (B)	Recommended	CP053418.zip	update
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB010000GYDKP, MB012000GYCJL, MB014000GYCJT, MB016000GYDKQ and MB018000GYDKR Drives	4	HPG1 (B)	Recommended	firmware-hdd- 4fbb6d96e5- HPG1- 2.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB002000JWFVN and MB004000JWFVP Drives	3	HPD4 (E)	Recommended	firmware-hdd- d7af557f47- HPD4- 5.1.x86_64.rp m	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - EH000300JWCPK, EH000600JWCPL and EH000900JWCPN Drives	4	HPD8 (C)	Recommended	CP053494.zip	update

Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB010000JYDKK, MB012000JYCJF, MB014000JYCJV, MB016000JYDKL and MB018000JYDKN Drives	6	HPD1	Recommended	CP053994.zip	new
Firmware - SAS Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000JWDFD Drive	3	HPD3 (D)	Recommended	CP053422.zip	new
Firmware - Storage Controller	Firmware Package - HPE MR216i-o Gen11 Tri Mode Controller	6	52.22.3- 4650 (B)	Recommended	HPE_MR216i- o_Gen11_52.2 2.3- 4650_B.fwpkg	new
Firmware - Storage Controller	Firmware Package - HPE SR932i-p Gen11/SR416i-o Gen11/SR416ie-m Gen11 Controllers	11	03.01.17. 056	Recommended	HPE_SR416_SR 932_Gen11_0 3.01.17.056_A. fwpkg	new
Firmware - Storage Controller	Firmware Package - HPE Gen10 E208e-p controller for Gen11 servers	12	5.61	Recommended	HPE_E208e- p_Gen11_5.61 _A.fwpkg	new
Firmware - Storage Controller	Firmware Package - HPE Gen11 Boot Controller NS204i-u, NS204i-d and Gen10P Boot Controller NS204i-p for Gen11 Servers	2	1.2.14.10 04 (B)	Recommended	HPE_NS204i_G en11_1.2.14.1 004_B.fwpkg	new
Firmware - Storage Controller	Firmware Package - HPE MR216i-p Gen11 Tri Mode Controller	5	52.22.3- 4650 (B)	Recommended	HPE_MR216i- p_Gen11_52.2 2.3- 4650_B.fwpkg	new
Firmware - Storage Controller	Firmware Package - HPE MR416i-o Gen11 Tri Mode Controller	5	52.22.3- 4650 (B)	Recommended	HPE_MR416i- o_Gen11_52.2 2.3- 4650_B.fwpkg	new
Firmware - Storage Controller	Firmware Package - HPE MR416i-p Gen11 Tri Mode Controller	6	52.22.3- 4650 (B)	Recommended	HPE_MR416i- p_Gen11_52.2 2.3- 4650_B.fwpkg	new

	1	,			1	
Firmware - Storage Controller	Firmware Package - HPE MR408i-o Gen11 Tri Mode Controller	8	52.22.3- 4650 (B)	Recommended	HPE_MR408i- o_Gen11_52.2 2.3- 4650_B.fwpkg	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB016000GWXKK Drive	3	HPG3 (E)	Recommended	firmware-hdd- e4f147cdd2- HPG3- 5.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB014000GWUDA Drive	3	HPG2 (H)	Recommended	CP053404.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK000480GWXFF, MK000960GWXFH, MK001920GWXFK and MK003840GWXFL Drives	3	HPG2 (D)	Recommended	firmware-hdd- 8e1e8083c5- HPG2- 4.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240GXAWE, VK000480GXAWK, VK000960GXAWL, VK001920GXAWN, VK003840GXAWP, VK007680GXAWP, VK007680GXAWP, MK000480GXAWF, MK000960GXAXB, MK001920GXAWR, MK003840GXAWT, VR000240GXBBL, MR000480GXBGH and MR000960GXBGK Drives	1	HPG1 (D)	Recommended	cp052976.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000GWKGV Drive	7	HPG1 (H)	Recommended	CP053386.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB001000GWFWK and MB002000GWFWL Drives	4	HPG6 (H)	Recommended	CP053380.zip	update

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB001000GWJAN, MB002000GWFWA and MB004000GWFWB Drives	4	HPG1 (H)	Recommended	CP053382.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240GWTSV, VK000480GWTTA, VK000960GWTTB, VK001920GWTTC, VK003840GWTTD, MK000480GWTTH, MK000960GWTTK, MK001920GWTTL and MK003840GWTTN Drives	3	HPG6 (F)	Recommended	firmware-hdd- c566d63ca0- HPG6- 6.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM2000GEFRA Drive	4	HPG9 (B)	Recommended	CP053412.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB014000GWUDA Drive	2	HPG2 (H)	Recommended	firmware-hdd- 41cdb1c9da- HPG2- 8.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB001000GWFWK and MB002000GWFWL Drives	1	HPG6 (G)	Recommended	cp052935.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000GWWQH, MB002000GWWQF and MB001000GWWQE Drives	3	HPG5 (B)	Recommended	firmware-hdd- 12304c1aca- HPG5- 2.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000GWWQH, MB002000GWWQF and MB001000GWWQE Drives	1	HPG5 (B)	Recommended	cp052963.exe	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB016000GWXKK Drive	1	HPG3 (D)	Recommended	cp052972.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000GWDFE Drive	6	HPG3 (D)	Recommended	CP053400.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK000480GWSSC, MK000960GWSSD, MK001920GWSSE and MK003840GWSSF Drives	5	HPG3 (E)	Recommended	CP053430.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB001000GWJAN, MB002000GWFWA and MB004000GWFWB Drives	2	HPG1 (I)	Recommended	firmware-hdd- d39e7a7e75- HPG1- 9.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM2000GEFRA Drive	4	HPG9 (B)	Recommended	firmware-hdd- ec908c3650- HPG9- 2.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB012000GWTFE and MB014000GWTFF Drives	1	HPG8	Recommended	cp054182.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB012000GWDFE Drive	1	HPG3 (D)	Recommended	cp052947.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB004000GWKGV Drive	1	HPG1 (G)	Recommended	cp052938.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB006000GWKGR Drive	2	HPG1 (H)	Recommended	firmware-hdd- 7f2a26e6d0- HPG1-	new

					8.1.x86_64.rp m	
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MM1000GFJTE Drive	4	HPG6 (B)	Recommended	firmware-hdd- 95af9a555e- HPG6- 2.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240GXAWE, VK000480GXAWK, VK000960GXAWL, VK001920GXAWN, VK003840GXAWP, VK007680GXAWP, VK007680GXAWP, MK000480GXAWF, MK000960GXAXB,MK0019 20GXAWR, MK003840GXAWT, VR000240GXBBL, MR000480GXBGH and MR000960GXBGK Drives	5	HPG1 (D)	Recommended	CP053453.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MK000480GWSSC, MK000960GWSSD, MK001920GWSSE and MK003840GWSSF Drives	3	HPG3 (F)	Recommended	firmware-hdd- f693ccc138- HPG3- 6.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MK000480GWXFF, MK000960GWXFH, MK001920GWXFK and MK003840GWXFL Drives	5	HPG2 (C)	Recommended	CP053458.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000480GZCNE, VK000960GZCNF, VK001920GZCNH and VK003840GZCNK Drives	6	HPG2 (C)	Recommended	CP053478.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB012000GWTFE	4	HPG8	Recommended	CP054181.zip	new

	and MB014000GWTFF Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB004000GWKGV Drive	3	HPG1 (H)	Recommended	firmware-hdd- ca21e169e2- HPG1- 8.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000480GZCNE, VK000960GZCNF, VK001920GZCNH and VK003840GZCNK Drives	1	HPG2 (C)	Recommended	cp052985.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB004000GWWQH, MB002000GWWQF and MB001000GWWQE Drives	3	HPG5 (B)	Recommended	CP053428.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB014000GWUDA Drive	1	HPG2 (G)	Recommended	cp052949.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240GWSRQ, VK000480GWSRR, VK000960GWSRT, VK001920GWSRU and VK003840GWSRV Drives	3	HPG4 (F)	Recommended	firmware-hdd- db687966b4- HPG4- 6.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB001000GWFWK and MB002000GWFWL Drives	2	HPG6 (H)	Recommended	firmware-hdd- bfc4af697b- HPG6- 8.1.x86_64.rp m	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM1000GFJTE Drive	1	HPG6 (B)	Recommended	cp052955.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB006000GWKGR Drive	7	HPG1 (H)	Recommended	CP053392.zip	new

Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000GWDFE Drive	3	HPG3 (E)	Recommended	firmware-hdd- 059b8654a6- HPG3- 5.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB012000GWTFE and MB014000GWTFF Drives	3	HPG8	Recommended	firmware-hdd- b78255e146- HPG8- 1.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB016000GWXKK Drive	4	HPG3 (D)	Recommended	CP053445.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000480GZCNE, VK000960GZCNF, VK001920GZCNH and VK003840GZCNK Drives	3	HPG2 (D)	Recommended	firmware-hdd- befd42bd64- HPG2- 4.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB008000GWRTC Drive	3	HPG1 (G)	Recommended	cp052944.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB006000GWKGR Drive	2	HPG1 (G)	Recommended	cp052941.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MB001000GWJAN, MB002000GWFWA and MB004000GWFWB Drives	1	HPG1 (G)	Recommended	cp052936.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MM2000GEFRA Drive	1	HPG9 (B)	Recommended	cp052954.exe	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240GWSRQ, VK000480GWSRR,	1	HPG4 (E)	Recommended	cp052965.exe	new

	VK000960GWSRT, VK001920GWSRU and VK003840GWSRV Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MK000480GWSSC, MK000960GWSSD, MK001920GWSSE and MK003840GWSSF Drives	1	HPG3 (E)	Recommended	cp052964.exe	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MB008000GWRTC Drive	4	HPG1 (H)	Recommended	CP053396.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240GWTSV, VK000480GWTTA, VK000960GWTTB, VK001920GWTTC, VK003840GWTTD, MK000480GWTTH, MK000960GWTTK, MK001920GWTTL and MK003840GWTTN Drives	4	HPG6 (E)	Recommended	CP053424.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - MB008000GWRTC Drive	3	HPG1 (H)	Recommended	firmware-hdd- 82894b9e0a- HPG1- 8.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - MM1000GFJTE Drive	4	HPG6 (B)	Recommended	CP053414.zip	update
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for VMware ESXi - VK000240GWSRQ, VK000480GWSRR, VK000960GWSRT, VK001920GWSRU, VK003840GWSRV Drives	4	HPG4 (E)	Recommended	CP053432.zip	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - MK000480GWXFF,	1	HPG2 (C)	Recommended	cp052978.exe	new

		•	,		1	,
	MK000960GWXFH, MK001920GWXFK and MK003840GWXFL Drives					
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Linux (x64) - VK000240GXAWE, VK000480GXAWK, VK000960GXAWL, VK001920GXAWN, VK003840GXAWP, VK007680GXAWQ, MK000480GXAWF, MK000960GXAXB, MK001920GXAWR, MK001920GXAWR, MK003840GXAWT, VR000240GXBBL, MR000480GXBGH and MR000960GXBGK Drives	3	HPG1 (E)	Recommended	firmware-hdd- 8f9bf23306- HPG1- 5.1.x86_64.rp m	new
Firmware - SATA Storage Disk	Online HDD/SSD Flash Component for Windows (x64) - VK000240GWTSV, VK000480GWTTA, VK000960GWTTB, VK001920GWTTC, VK003840GWTTD, MK000480GWTTH, MK000960GWTTK, MK001920GWTTL and MK003840GWTTN Drives	1	HPG6 (E)	Recommended	cp052961.exe	new
Firmware - Network	Broadcom NX1 Online Firmware Upgrade Utility for Windows Server x64 Editions	14	5.3.2.0	Recommended	cp053058.exe	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for Mellanox MCX623106AS-CDAT Ethernet 100Gb 2-port QSFP56 Adapter for HPE	2	22.34.100	Recommended	22_34_1002- MCX623106AS - CDA_Ax.pldm .fwpkg	new
Firmware - Network	Broadcom Firmware Package for BCM5750x adapters	9	223.1.96. 0	Recommended	bcm223.1.96. 0_Thor.pup.fw pkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 2-port QSFP56 PCIe4	5	20.35.101	Recommended	20_35_1012- MCX653106A-	new

	T		1	1	I	1
	x16 MCX653106A-ECAT Adapter : HPE part numbers P23666-B21 and P23666-H21				ECA_HPE_Ax. pldm.fwpkg	
Firmware - Network	Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 MCLK Adapter	3	4.00 (C)	Recommended	HPE_E810_XXV 4T_O_SEC_4p 01_PLDMoMC TP_800135E7.f wpkg	new
Firmware - Network	Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter	2	4.00 (B)	Recommended	HPE_E810_CQ DA2_4p01_PL DMoMCTP_80 0135E8.fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) - Mellanox MCX631432AS-ADAI Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter for HPE	2	26.34.100 2	Recommended	26_34_1002- MCX631432AS - ADA_Ax.pldm .fwpkg	new
Firmware - Network	Online Firmware Upgrade Utility (Linux x86_64) for HPE OPA adapters	2	1.12.0 (A)	Recommended	firmware-nic- cornelis-opa- hfi-1.12.0- 2.1.x86_64.rp m	update
Firmware - Network	Intel Firmware Package For E810-2CQDA2 Ethernet 100Gb 2-port QSFP28 Adapter	2	4.00 (B)	Recommended	HPE_E810_2C QDA2_O_SEC _4p01_PLDMo MCTP_800135 E6.fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 MCX653106A-HDAT Adapter: HPE part numbers P31324-B21 and P31324-H21	3	20.35.101	Recommended	20_35_1012- MCX653106A- HDA_HPE_Ax. pldm.fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) - Mellanox MCX631102AS-ADAT Ethernet 10/25Gb 2-port SFP28 Adapter for HPE	2	26.34.100 2	Recommended	26_34_1002- MCX631102AS - ADA_Ax.pldm .fwpkg	new

Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand NDR 1-port OSFP PCIe5 x16 MCX75310AAS- NEAT Adapter: HPE part numbers P45641-B21 and P45641-H21	3	28.35.101	Recommended	28_35_1012- MCX75310AA S- NEAT_HPE_Ax. pldm.fwpkg	new
Firmware - Network	Intel Online Firmware Upgrade Utility for VMware	14	3.19.0	Recommended	CP054539.zip	new
Firmware - Network	Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 Adapter	3	4.00 (B)	Recommended	HPE_E810_XXV DA4_FH_4p01 _PLDMoMCTP _800135E3.fw pkg	new
Firmware - Network	Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 Adapter	2	4.00 (B)	Recommended	HPE_E810_XXV DA2_SD_4p01 _PLDMoMCTP _800135EC.fw pkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 OCP3 MCX653435A- HDAI Adapter: HPE part numbers P31323-B21 and P31323-H21	3	20.35.101	Recommended	20_35_1012- MCX653435A- HDA_HPE_Ax. pldm.fwpkg	new
Firmware - Network	Intel Online Firmware Upgrade Utility for Windows Server x64 Editions	6	5.3.2.0	Recommended	cp054540.exe	new
Firmware - Network	Broadcom NX1 Online Firmware Upgrade Utility for Linux x86_64	12	2.31.0	Recommended	firmware-nic- bcm-open- 2.31.0- 1.1.x86_64.rp m	new
Firmware - Network	Intel Firmware Package For E810-CQDA2 Ethernet 100Gb 2-port QSFP28 OCP3 Adapter	3	4.00 (B)	Recommended	HPE_E810_CQ DA2_OCP_4p 01_NC\$IwPLD MoMCTP_800 135E9.fwpkg	new

Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE Ethernet 100Gb 1-port QSFP28 PCIe3 x16 MCX515A-CCAT Adapter: HPE part numbers P31246-B21 and P31246-H21	3	16.35.101	Recommended	16_35_1012- MCX515A- CCA_HPE_Ax. pldm.fwpkg	new
Firmware - Network	Broadcom Firmware Package for BCM5741x adapters	9	223.1.96. 0	Recommended	bcm223.1.96. 0.pup.fwpkg	new
Firmware - Network	Broadcom NX1 Online Firmware Upgrade Utility for VMware	25	1.32.0	Recommended	CP053057.zip	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR100/Ethernet 100Gb 1-port QSFP56 PCIe4 x16 MCX653105A-ECAT Adapter: HPE part numbers P23665-B21 and P23665-H21	4	20.35.101	Recommended	20_35_1012- MCX653105A- ECA_HPE_Ax. pldm.fwpkg	new
Firmware - Network	Intel Online Firmware Upgrade Utility for Linux x86_64	3	1.26.0	Recommended	firmware-nic- is-intel-1.26.0- 1.1.x86_64.rp m	new
Firmware - Network	Intel Firmware Package For E810-XXVDA4 Ethernet 10/25Gb 4-port SFP28 OCP3 Adapter	3	4.00 (B)	Recommended	HPE_E810_XXV 4_OCP_4p01_ NCSIWPLDMo MCTP_800135 EB.fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 2-port QSFP56 PCIe4 x16 OCP3 MCX653436A- HDAI Adapter: HPE part numbers P31348-B21 and P31348-H21	3	20.35.101	Recommended	20_35_1012- MCX653436A- HDA_HPE_Ax. pldm.fwpkg	new
Firmware - Network	Intel Firmware Package For E810-XXVDA2 Ethernet 10/25Gb 2-port SFP28 OCP3 Adapter	2	4.00 (B)	Recommended	HPE_E810_XXV DA2_SD_OCP _4p01_NCSIW PLDMoMCTP_ 800135E5.fwp kg	new

Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand HDR/Ethernet 200Gb 1-port QSFP56 PCIe4 x16 MCX653105A-HDAT Adapter: HPE part numbers P23664-B21 and P23664-H21	3	20.35.101	Recommended	20_35_1012- MCX653105A- HDA_HPE_Ax. pldm.fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for Mellanox MCX623105AS-VDAT Ethernet 200Gb 1-port QSFP56 Adapter for HPE	2	22.34.100	Recommended	22_34_1002- MCX623105AS - VDA_Ax.pldm .fwpkg	new
Firmware - Network	Mellanox Firmware Package (FWPKG) for HPE InfiniBand NDR200 1-port OSFP PCIe5 x16 MCX75310AAS-HEAT Adapter: HPE part numbers P45642-B21 and P45642-H21	3	28.35.101	Recommended	28_35_1012- MCX75310AA S- HEAT_HPE_Ax. pldm.fwpkg	new
Firmware - System	Firmware Package - UBM3 Backplane PIC PLDM Firmware for Gen11 servers usage	3	1.24 (D)	Recommended	HPE_UBM3_1.2 4_D.fwpkg	new
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS) Firmware for HPE ProLiant DL320 Gen11	31	06.00.04. 031.0	Recommended	firmware- u63_me- 06.00.04.031.0 - 1.1.x86_64.rp m	new
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE Alletra 4110/Alletra 4120/ProLiant DL380a Gen11 Servers	33	06.00.04. 031.0	Recommended	SC_U58_ME_0 6.00.04.031.0.f wpkg	new
Firmware - System	Firmware Package - UBM4 Backplane PIC PLDM Firmware for Gen11 servers usage	3	1.24 (E)	Recommended	HPE_UBM4_1.2 4_E.fwpkg	new
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform Services	39	06.00.04. 031.0	Recommended	cp051715.exe	new

		<u> </u>		T	Τ	T
	(SPS) Firmware for HPE ProLiant DL320 Gen11					
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS) Firmware for HPE ProLiant DL360/DL380/ML350 Gen11	30	06.00.04. 031.0	Recommended	firmware- u54_me- 06.00.04.031.0 - 1.1.x86_64.rp m	new
Firmware - System	Online ROM Flash Component for Windows x64 - Server Platform Services (SPS) Firmware for HPE ProLiant DL360/DL380/ML350 Gen11	30	06.00.04. 031.0	Recommended	cp051691.exe	new
Firmware - System	Online ROM Flash for Linux - Server Platform Services (SPS) Firmware for HPE Alletra 4110/Alletra 4120/ProLiant DL380a Gen11 Servers	31	06.00.04. 031.0	Recommended	firmware- u58_me- 06.00.04.031.0 - 1.1.x86_64.rp m	new
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE ProLiant DL320 Gen11 Servers	33	06.00.04. 031.0	Recommended	SC_U63_ME_0 6.00.04.031.0.f wpkg	new
Firmware - System	Firmware Package - UBM2 Backplane PIC PLDM Firmware for Gen11 Servers	4	1.20 (D)	Recommended	HPE_UBM2_1.2 0_D.fwpkg	new
Firmware - System	Firmware Package - UBM6 Backplane PIC PLDM Firmware for Gen11 servers usage	6	1.02 (D)	Recommended	HPE_UBM6_1.0 2_D.fwpkg	new
Firmware - System	ROM Flash Firmware Package - Server Platform Services (SPS) Firmware for HPE ProLiant DL360/DL380/ML350 Gen11 Servers	34	06.00.04. 031.0	Recommended	SC_U54_ME_0 6.00.04.031.0.f wpkg	new
Firmware - System	Online ROM Flash Component for Windows x64	33	06.00.04. 031.0	Recommended	cp051796.exe	new

	1	T	T	T	T	
	- Server Platform Services (SPS) Firmware for HPE Alletra 4110/Alletra 4120/ProLiant DL380a Gen11 Servers					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - EO000400KYDKV and EO000800KYDLA Drives	5	4IASHP K3	Recommended	firmware-hdd- 6758a46eb7- 4IASHPK3- 1.1.x86_64.rp m	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - MZXLR800HBHQ-000H3, MZXLR1T6HBJR-000H3, MZXLR3T2HBLS-000H3, MZXLR6T4HALA-000H3, MZXLR12THALA-000H3, MZXLR179HBJR-000H3, MZXLR3T8HBLS-000H3, MZXLR3T8HBLS-000H3, MZXLR7T6HALA-000H3 and MZXLR15THALA-000H3 Drive	2	MPK762 5Q (C)	Recommended	firmware-hdd- 951aefd63e- MPK7625Q- 3.1.x86_64.rp m	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - EO000400KYDKV and EO000800KYDLA Drives	9	4IASHP K3	Recommended	CP053791.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Linux (x64) - VO001920KYDMT, VO003840KYDMV, MO001600KYDMU, MO003200KYDNC, MO006400KYDND, VO007680KYDNA and VO015360KYDNB Drives	2	НРК2	Recommended	firmware-hdd- a27c95663d- HPK2- 1.1.x86_64.rp m	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - MZXLR800HBHQ- 000H3, MZXLR1T6HBJR- 000H3, MZXLR3T2HBLS- 000H3, MZXLR6T4HALA- 000H3, MZXLR12THALA- 000H3, MZXLR12THALA-	1	MPK762 5Q (C)	Recommended	cp053727.exe	new

	000H3, MZXLR1T9HBJR- 000H3, MZXLR3T8HBLS- 000H3, MZXLR7T6HALA- 000H3 and MZXLR15THALA-0 Drives					
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - VO001920KYDMT, VO003840KYDMV, MO001600KYDMU, MO003200KYDNC, MO006400KYDND, VO007680KYDNA and VO015360KYDNB Drives	1	НРК2	Recommended	cp054553.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for Windows (x64) - EO000400KYDKV and EO000800KYDLA Drives	4	4IASHP K3	Recommended	cp053792.exe	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - MZXLR800HBHQ- 000H3, MZXLR1T6HBJR- 000H3, MZXLR3T2HBLS- 000H3, MZXLR6T4HALA- 000H3, MZXLR12THALA- 000H3, MZXLR1960HBHQ- 000H3, MZXLR1T9HBJR- 000H3, MZXLR3T8HBLS- 000H3, MZXLR7T6HALA- 000H3 and MZXLR15THALA-000H Drive	4	MPK762 5Q (C)	Recommended	CP053726.zip	new
Firmware - PCIe NVMe Storage Disk	Online NVMe SSD Flash Component for VMware ESXi - VO001920KYDMT, VO003840KYDMV, MO001600KYDMU, MO003200KYDNC, MO006400KYDND, VO007680KYDNA and VO015360KYDNB Drives	5	HPK2	Recommended	CP054552.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 7.0	9	2023.03.0	Recommended	CP054354.zip	new

Firmware - Storage Fibre Channel	HPE Firmware Flash for Emulex 32Gb and 64Gb Fibre Channel Host Bus Adapters	3	14.0.499. 29	Recommended	P14.0.499.29_ header.pldm.f wpkg	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters - Linux (x86_64)	7	2023.03.0	Recommended	firmware-fc- qlogic- 2023.03.01- 1.7.x86_64.rp m	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters for VMware vSphere 8.0	8	2023.03.0	Recommended	CP054355.zip	new
Firmware - Storage Fibre Channel	HPE Firmware Flash for QLogic Fibre Channel Host Bus Adapters - Microsoft Windows Server 2019/2022 (x86_64)	5	2023.03.0	Recommended	cp054357.exe	new
Firmware - Lights-Out Management	Online ROM Flash Component for Windows x64 - HPE Integrated Lights-Out 6	24	1.20	Optional	cp053777.exe	new
Firmware - Lights-Out Management	Online ROM Flash Firmware Package - HPE Integrated Lights-Out 6	26	1.20	Optional	ilo6_120.fwpk g	new
Firmware - Lights-Out Management	Online ROM Flash Component for Linux - HPE Integrated Lights-Out 6	25	1.20	Optional	firmware-ilo6- 1.20- 1.1.x86_64.rp m	new
Firmware - Power Management	ROM Flash Firmware Package - Advanced Power Capping Microcontroller Firmware for HPE Gen11 Servers	5	1.0.2	Recommended	PICGen11- 1.0.2-1.fwpkg	new
Firmware - Power Management	Online ROM Flash for Linux - Advanced Power Capping Microcontroller Firmware for HPE Gen11 Servers	5	1.0.2	Recommended	firmware- powerpic- gen11-1.0.2- 1.1.x86_64.rp m	new

Firmware - Power Management	Online ROM Flash for Windows x64 - Advanced Power Capping Microcontroller Firmware for HPE Gen11 Servers	5	1.0.2	Recommended	cp054490.exe	new
Operating System - Enhancemen ts	AMD PSHED Plug-in service for Microsoft Windows Server 2022	1	1.0.0.49	Recommended	cp054499.exe	new
Operating System - Enhancemen ts	AMD PSHED Plug-in service for Microsoft Windows Server 2019	2	1.0.0.49	Recommended	cp053846.exe	new
Software - Storage Fibre Channel	HPE Emulex Smart SAN Enablement Kit for Linux	2	1.0.0.0-4 (b)	Optional	hpe-emulex- smartsan- enablement- kit-1.0.0.0- 4.x86_64.rpm	new
Software - Storage Fibre Channel	HPE QLogic Smart SAN Enablement Kit for Fibre Channel Host Bus Adapter for Microsoft Windows Server 2022 (x86_64)	4	1.0.0.1 (b)	Optional	cp054362.exe	new
Software - Storage Fibre Channel	HPE QLogic Fibre Channel driver component for VMware vSphere 8.0	6	2023.03.0	Recommended	cp054352.zip	new
Software - Storage Fibre Channel	HPE Emulex Fibre Channel Enablement Kit for Host Bus Adapters for Red Hat Enterprise Linux 8 Server	4	14.0.499. 28	Recommended	HPE-CNA-FC- Emulex- Enablement- Kit- 14.0.499.28- 1.rhel8.x86_64. rpm	new
Software - Storage Fibre Channel	HPE Emulex Fibre Channel Smart SAN Enablement Kit for Host Bus Adapters for Microsoft Windows Server 2022 (x86_64)	4	1.0.0.1 (b)	Optional	cp054345.exe	new

						,
Software - Storage Fibre Channel	HPE QLogic Smart SAN Enablement kit for Linux	4	3.3-3 (b)	Optional	hpe-qlogic- smartsan- enablement- kit-3.3- 3.x86_64.rpm	new
Software - Storage Fibre Channel	HPE Emulex Fibre Channel Enablement Kit for Host Bus Adapters for SuSE Linux Enterprise Server 15	4	14.0.499. 28	Recommended	HPE-CNA-FC- Emulex- Enablement- Kit- 14.0.499.28- 1.sles15sp4.x8 6_64.rpm	new
Software - Storage Fibre Channel	HPE QLogic Fibre Channel Enablement Kit for Host Bus Adapter for Linux	6	6.0.0.0-18 (b)	Optional	HPE-CNA-FC- hpeqlgc- Enablement- Kit-6.0.0.0- 18.noarch.rp m	new
Software - Storage Fibre Channel	HPE QLogic Smart SAN Enablement Kit for Fibre Channel Host Bus Adapter for Microsoft Windows Server 2019 (x86_64)	4	1.0.0.1 (b)	Optional	cp054363.exe	new
Software - Storage Fibre Channel	HPE Storage Emulex Fibre Channel driver component for VMware vSphere 7.0	3	2023.03.0	Recommended	cp054347.zip	new
Software - Storage Fibre Channel	HPE Emulex Fibre Channel Smart SAN Enablement Kit for Host Bus Adapters for Microsoft Windows Server 2019 (x86_64)	5	1.0.0.1 (b)	Optional	cp054346.exe	new
Software - Storage Fibre Channel	Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux - Red Hat Enterprise Linux (RHEL)	2	4.2-1 (b)	Optional	fibreutils-4.2- 1_rhel.x86_64.r pm	new
Software - Storage Fibre Channel	Fibreutils for HPE Storage Fibre Channel Host Bus Adapters for Linux - SuSE Linux Enterprise Server(SLES)	2	4.2-1 (b)	Optional	fibreutils-4.2- 1_sles.x86_64.r pm	new

Software - Storage Fibre Channel	HPE QLogic Fibre Channel driver component for VMware vSphere 7.0	5	2023.03.0	Recommended	cp054353.zip	new
Software - System Management	HPE MegaRAID Storage Administrator for Linux 64- bit (HPE MRSA for Gen11 Controllers)	2	8.2.19.0 (B)	Recommended	MRStorageAd ministrator- 008.002.019.00 0- 00.x86_64.rpm	new
Software - System Management	HPE MegaRAID Storage Administrator StorCLI for Linux 64-bit (for Gen11 Controllers)	8	007.2207. 0000.000 0 (B)	Optional	storcli- 007.2207.0000. 0000- 1.noarch.rpm	new
Software - System Management	Agentless Management Service (iLO 5, iLO 6) for Red Hat Enterprise Linux 9 Server	1	3.2.0	Optional	amsd-3.2.0- 1745.1.rhel9.x8 6_64.rpm	new
Software - System Management	Smart Storage Administrator (SSA) CLI for Linux 64-bit for Gen11 Controllers	6	6.15.11.0	Recommended	ssacli-6.15- 11.0.x86_64.rp m	new
Software - System Management	Smart Storage Administrator (SSA) CLI for Windows 64- bit for Gen11 Controllers	7	6.15.11.0	Recommended	cp054519.exe	new
Software - System Management	Smart Storage Administrator Diagnostic Utility (SSADU) CLI for Linux 64-bit for Gen11 Controllers	7	6.15.11.0	Recommended	ssaducli-6.15- 11.0.x86_64.rp m	new
Software - System Management	Smart Storage Administrator (SSA) for Windows 64-bit for Gen11 Controllers	8	6.15.11.0	Recommended	cp054518.exe	new
Software - System Management	Agentless Management Service (iLO5, iLO 6) for SUSE Linux Enterprise Server 15	1	3.2.0	Optional	amsd-3.2.0- 1745.1.sles15.x 86_64.rpm	update
Software - System Management	Agentless Management Service (iLO5, iLO 6) for Red Hat Enterprise Linux 8 Server	1	3.2.0	Optional	amsd-3.2.0- 1745.1.rhel8.x8 6_64.rpm	new

						,
Software - System Management	HPE MegaRAID Storage Administrator StorCLI for Windows 64-bit (for Gen11 Controllers)	5	7.22.7.0 (B)	Recommended	cp054204.exe	new
Software - System Management	Smart Storage Administrator (SSA) for Linux 64-bit for Gen11 Controllers	6	6.15.11.0	Recommended	ssa-6.15- 11.0.x86_64.rp m	new
Software - System Management	HPE MegaRAID Storage Administrator for Windows 64-bit (HPE MRSA for Gen11 Servers)	6	8.2.19.0 (B)	Recommended	cp054205.exe	new
Software - System Management	HPE Gen11 Agentless Management Service for Microsoft Windows x64	10	3.20.0.0	Optional	cp053688.exe	new
Software - System Management	Smart Storage Administrator Diagnostic Utility (SSADU) CLI for Windows 64-bit for Gen11 Controllers	8	6.15.11.0	Recommended	cp054520.exe	new
Software - Lights-Out Management	HPE Lights-Out Online Configuration Utility for Windows x64 Editions	6	6.0.0.0	Optional	cp049814.exe	update
Software - Lights-Out Management	HPE Lights-Out Online Configuration Utility for Linux (AMD64/EM64T)	6	6.0.0-0	Optional	hponcfg- 6.0.0- 0.x86_64.rpm	update
Software - Management	HPE Fiber Channel and Storage Enablement Bundle Smart Component for ESXi 7.0	8	2022.09.0	Recommended	cp050934.zip	new
Software - Management	Smart Storage Administrator (SSA) CLI Smart Component for ESXi 7.0 for Gen11 Controllers	7	2023.02.0	Recommended	cp054521.zip	new
Software - Management	HPE Fiber Channel and Storage Enablement Bundle Smart Component for ESXi 8.0	14	2022.09.0	Recommended	cp051152.zip	new
	i.				·	

Software - Management	HPE iLO Driver Bundle Smart Component for ESXi 7.0	13	2022.09.0	Recommended	cp050763.zip	new
Software - Management	HPE Agentless Management Bundle Smart Component on ESXi for Gen11 Servers	7	2023.02.0	Recommended	cp054510.zip	new
Software - Management	Smart Storage Administrator (SSA) CLI Smart Component for ESXi 8.0 for Gen11 Controllers	7	2023.02.0	Recommended	cp054522.zip	new
Software - Storage Controller	HPE MegaRAID Storage Administrator StorCLI for VMware7.0 (For Gen11 Controllers)	4	2022.10.0 0 (C)	Recommended	cp054794.zip	new