

MRPL — EQUIPMENT INSPECTION REPORT

Report No: MRPL/INSP/2026/0412
Unit: CDU-II

Date: 12-Sep-2026

EQUIPMENT

Tag No	Description	Design Pressure	Status
TK-4102	Crude Storage Tank	Atmospheric	IN SERVICE
PSV-2041	Safety Relief Valve	12.5 barg	DEVIATION
P-4110A	Crude Transfer Pump	18.0 barg	IN SERVICE

OBSERVATIONS

- 1. Shell plate thickness course-1 = 11.2 mm (nominal 12.0 mm).
- 2. PSV-2041 set pressure 12.5 barg vs SOP-114 spec 14.0 barg.
- 3. Minor external corrosion near nozzle N-3, no through-wall loss.
- 4. Foundation grouting intact, no settlement recorded.

RECOMMENDATION

- Re-rate TK-4102 per API 653 or restore thickness at shutdown.
- Bench test PSV-2041 and reset to 14.0 barg before restart.

Inspected by: R. Nair (API 510 #48112)