

Unit 33 - Diesel Hydrodesulphuriser (DHDS) - NIGHT SHIFT LOG

22:05 Took over charge. Unit stable at 78% throughput.

V-3302 level 51%, pressure 54.8 barg.

01:55 P-3320B tripped on HIGH VIBRATION.

Vibration recorded 9.4 mm/s RMS at DE bearing.

Trip setpoint is 8 mm/s RMS.

Standby pump P-3320A started immediately.

No process upset. Throughput maintained.

03:20 TK-3340 slop tank level 48%.

Routine transfer lined up. No abnormality.

05:40 Handover to day shift. P-3320B REMAINS OUT

OF SERVICE pending vibration investigation.

SIGNED: N. PILLAI, SHIFT IN-CHARGE UNIT 33