Chapter 1

User Interface

- 1.1 Introduction
- 1.2 Design Process
- 1.2.1 User Requirements
 - 1. Display weight data on app.
 - 2. App must have interface for manual data.
 - 3. Other data should be automated (time, location).
 - 4. Data must be saved to Excel spreadsheet (and stored on cloud).

1.2.2 Functional Requirements

- 1. Establish connection between smart scale (Arduino) and phone (via Bluetooth or Wi-Fi)
- 1.2.3 Acceptance Test Procedures
- 1.3 Design Process
- 1.4 Final Design
- 1.5 Testing
- 1.6 Conclusion

Bibliography

Glossary