

Meridian Fabrication Works -- Receiving Dock

Visit date: 2026-09-12 Checklist: Safety & Compliance Walk

Demo data: this facility, its field notes, and its photos are entirely synthetic, generated by `scripts/generate_synthetic_data.py`. No real facility's data is used.

Executive Summary

4 critical/high-severity finding(s) from this safety & compliance walk, led by 'Machine Guarding' (3 occurrence(s)). 6 finding(s) total across Meridian Fabrication Works -- Receiving Dock. Top priority: Stop-the-line priority -- address before the next shift starts. See the prioritized action list below for the full sequence.

(Synthesis method: template)

Findings

[CRITICAL] Machine Guarding (x3)

3 instance(s) matched 'Machine Guarding' (missing or bypassed machine guard, exposed pinch point, or exposed moving parts at operator height). Field notes: Right where the roller conveyor meets the sorter there's an exposed pinch point, no guard around it at all; Checked again on the other side of the dock, same conveyor line further down, another spot where the guard removed -- looks like it was taken off for maintenance and never put back. Photo evidence: `c03_pinch_point.png`.

[CRITICAL] Emergency Egress / Fire Safety (x3)

3 instance(s) matched 'Emergency Egress / Fire Safety' (blocked or obstructed emergency exit, fire extinguisher, or fire lane; expired extinguisher inspection tag). Field notes: Two pallets are stacked directly in front of the east-wall emergency exit door, essentially an obstructed exit that wouldn't fully open if someone needed it; Fire extinguisher near the dock office has an inspection tag showing the extinguisher expired six months ago. Photo evidence: `c06_exit_blocked.png`.

[CRITICAL] PPE Compliance (x3)

3 instance(s) matched 'PPE Compliance' (personnel working without required ppe -- safety glasses, hearing protection, gloves, hard hats, high-visibility vests -- for the task or zone). Field notes: A couple of the dock workers unloading the trailer this morning had no gloves on despite the posted PPE requirement for that zone; Saw at least one person on the dock without safety glasses near the strapping area, that's a required PPE zone too.

Escalation: Escalated: at least one supporting note independently read as a safety issue.

[CRITICAL] Housekeeping / Slip-Trip-Fall (x3)

3 instance(s) matched 'Housekeeping / Slip-Trip-Fall' (spills, loose cabling, uneven flooring, or debris in a walkway creating a slip or trip hazard). Field notes: Noticed a frayed cord running across the main walkway near the scale, definitely a trip hazard and an electrical one; There's a spill near the dock plate, looked like hydraulic fluid, hasn't been cleaned up or marked off.

Escalation: Escalated: at least one supporting note independently read as a safety issue. Escalated: this finding recurred across 3 separate notes (threshold: 3).

[MEDIUM] Documentation & Signage (x2)

2 instance(s) matched 'Documentation & Signage' (missing or outdated required signage (chemical labeling, evacuation map, machine lockout instructions)). Field notes: Evacuation map posted near the office door looks outdated, references a layout that doesn't match the current dock configuration; A couple of chemical containers near the wash station don't have current labels on them, an unlabeled chemical situation.

Escalation: Escalated: at least one supporting note independently read as a safety issue.

[LOW] Ergonomics (x2)

2 instance(s) matched 'Ergonomics' (repeated awkward lifting, reaching, or bending that a simple fix (lift assist, adjustable table, staging change) could resolve). Field notes: Watched someone repeatedly doing an awkward lift straight from the trailer floor to a pallet, no lift table staged there; No lift assist available anywhere near the dock for the heavier cases, seems like an ergonomics gap.

Prioritized Action List

#	Finding	Severity	Recommended Action
1	Machine Guarding	CRITICAL	Stop-the-line priority -- address before the next shift starts.
2	Emergency Egress / Fire Safety	CRITICAL	Stop-the-line priority -- address before the next shift starts.
3	PPE Compliance	CRITICAL	Stop-the-line priority -- address before the next shift starts.
4	Housekeeping / Slip-Trip-Fall	CRITICAL	Stop-the-line priority -- address before the next shift starts.
5	Documentation & Signage	MEDIUM	Schedule a fix within the next 30 days.
6	Ergonomics	LOW	Fold into the next

			routine standard-work update.
--	--	--	-------------------------------

Methodology & Scope

Checklist: Safety & Compliance Walk (safety_compliance). 16 voice note(s) and 2 photo(s) processed; 2 note(s)/photo(s) did not match any checklist item confidently and were excluded from findings rather than force-fit.

This checklist is swappable -- the same pipeline can run a Lean 5S audit, a Theory of Constraints constraint walk, or a safety & compliance walk from the same field-note and photo inputs, depending on which YAML config is selected (or recommended).

Appendix: Note-to-Finding Traceability

Note ID	Type	Matched Finding	Detail
C01	text	Machine Guarding	Right where the roller conveyor meets the sorter there's an exposed pinch point, no guard around it at all.
C02	text	Machine Guarding	Checked again on the other side of the dock, same conveyor line further down, another spot where the guard removed -- looks like it was take
C03	photo	Machine Guarding	Close-up of the conveyor transfer point showing the guard panel missing, chain and rollers exposed at hand height.
C04	text	Emergency Egress / Fire Safety	Two pallets are stacked directly in front of the east-wall emergency exit door, essentially an obstructed exit that wouldn't fully open if s

C05	text	Emergency Egress / Fire Safety	Fire extinguisher near the dock office has an inspection tag showing the extinguisher expired six months ago.
C06	photo	Emergency Egress / Fire Safety	Emergency exit signage at the east wall dock door, view partially obstructed by stacked pallets in the foreground.
C07	text	PPE Compliance	A couple of the dock workers unloading the trailer this morning had no gloves on despite the posted PPE requirement for that zone.
C08	text	PPE Compliance	Saw at least one person on the dock without safety glasses near the strapping area, that's a required PPE zone too.
C09	text	PPE Compliance	Forklift operator wasn't wearing a hard hat while under the mezzanine overhang, that's marked as a hard-hat zone.
C10	text	Housekeeping / Slip-Trip-Fall	Noticed a frayed cord running across the main walkway near the scale, definitely a trip hazard and an electrical one.
C11	text	Housekeeping / Slip-Trip-Fall	There's a spill near the dock plate, looked like hydraulic fluid, hasn't been cleaned up or marked off.
C12	text	Housekeeping / Slip-Trip-Fall	Cabling for the label printer runs straight across the walkway by receiving desk 2,

			another trip hazard.
C15	text	Documentation & Signage	Evacuation map posted near the office door looks outdated, references a layout that doesn't match the current dock configuration.
C16	text	Documentation & Signage	A couple of chemical containers near the wash station don't have current labels on them, an unlabeled chemical situation.
C13	text	Ergonomics	Watched someone repeatedly doing an awkward lift straight from the trailer floor to a pallet, no lift table staged there.
C14	text	Ergonomics	No lift assist available anywhere near the dock for the heavier cases, seems like an ergonomics gap.