Simulation Results

PID control for transfer function 1/s^2 +2s +1



P=20 , I=5 (UNDERDAMPED)



Results

ERROR SCOPE



CONTROLLER O/P SCOPE



PLANT O/P SCOPE



P=1 , D=5(OVERDAMPED)



Results

ERROR SCOPE



CONTROLLER O/P SCOPE



PLANT O/P SCOPE



P=8 I=2 D=1



Results

ERROR SCOPE



CONTROLLER O/P SCOPE



PLANT O/P SCOPE