
Gis to Cad Tool using DLS - Key

- Gis to Cad Tool folder location and subfolders :




- DWG Cad File Output Folder: the location in which you save your output Drawing Cad file.

- DLS_Connection.gdb: the connection geodatabase which contain the feature classes used as input layers in the modelbuilder.

- Subset_layers.gdb: the default and scratch file Geodatabase in which the intermediate data will be saved.

- Gis to Cad File.tbx:

  - Gis to Cad File Tool: modelbuilder tool to convert from ArcGis data to AutoCad DWG Cad File using **DLS_Key** Field.




-Prerequisites:

1-connect to database, each one with his own user.

2-Inside the Tool:

- Modify the tool environments (scratch and default Workspaces) from:
  Start edit a model…from (model) menu select (model properties) then click Environment tab…go to Workspace and put the path of (Scratchworkspace.gdb).



Gis To Cad File Tool in ModelBuilder