
1
2 10.4V/
4.480ms
2.000ms/
Auto
1 20.0V
KEYSIGHT TECHNOLOGIES
Cursors
Mode
Off
To turn on cursors, press the [Cursors] key on the front panel.
FFT
2
+58.7500V
DC BW 10.0:1
+17.5500V
DC BW 10.0:1


1
2 10.4V/
4.480ms
2.000ms/
Auto
1 20.0V
KEYSIGHT TECHNOLOGIES
Cursors
Mode
Off
To turn on cursors, press the [Cursors] key on the front panel.
FFT
2
+58.7500V
DC BW 10.0:1
+17.5500V
DC BW 10.0:1