


Board dimensions (top view) Scale 3:1 Connector callouts (bottom view) Scale 3:1 3 Isometric view Scale 3:1





5 Actual size Scale 1:1

To get the specified scale, select 100% in print settings. 1.

2. Drill location tolerance: ±0.1 [±5]. 3.

Board edge tolerance: ±0.3 [±10].

