

E3

Multimeter: Mostek MA830B

Oporniki R_1, R_2 :

$$R_1 = 10,5 \Omega$$

$$R_2 = 10,5 \Omega$$

$$T_0 = 22^\circ\text{C}$$

Zmierzone multimetrem:

Zmierzone opornicą dekadową

$$R_{0PT} = 108,9 \Omega$$

$$109 \Omega$$

$$R_{0Ni} = 112,8 \Omega$$

$$113 \Omega$$

$$R_{0C} = 100,2 \Omega$$

$$100 \Omega$$

$$R_{0Ni} + R_{0C} = 213 \Omega$$

$$214 \Omega$$

$$R_{0C} + R_{0PT} = 209 \Omega$$

$$210 \Omega$$

$$R_{0Ni} + R_{0PT} = 221 \Omega$$

$$223 \Omega$$

$$\frac{1}{R_{0C}} + \frac{1}{R_{0PT}} = \frac{1}{52,4 \Omega}$$

$$\frac{1}{52 \Omega}$$

$$\frac{1}{R_{0C}} + \frac{1}{R_{0Ni}} = \frac{1}{53,3 \Omega}$$

$$\frac{1}{53 \Omega}$$

$$\frac{1}{R_{0PT}} + \frac{1}{R_{0Ni}} = \frac{1}{55,6 \Omega}$$

$$\frac{1}{56 \Omega}$$

$$\frac{1}{R_{0PT}} + \frac{1}{R_{0C}} + \frac{1}{R_{0Ni}} = \frac{1}{35,9 \Omega}$$

$$\frac{1}{36 \Omega}$$

Temperatura [°C]	R_L [Ω]	R_{Ni} [Ω]	R_{Pt} [Ω]
20			
21			
22	100	114	109
23	100		
24		115	
25			110
26	100		
27		117	
28			112
29	100		
30		119	
31			113
32	100		
33		121	
34			114
35	100		
36		123	
37			115
38	100		

Temperatura [°C]	R_c [Ω]	R_{Ni} [Ω]	R_{Pt} [Ω]
39		124	
40			117
41	100		
42		126	
43			118
44	100		
45		127	
46			119
47	100		
48		129	
49			120
50	100		
51		131	
52			121
53	100		
54		133	
55			122
56	100		
57		135	

Temperatura [°C]	R_L [Ω]	R_{Ni} [Ω]	R_{PT} [Ω]
58			123
59	100		
60		136	
61			124
62	100		
63		139	
64			125
65	100		
66		141	
67			126
68	100		
69		143	
70			127
71	100		
72		145	
73			128
74	101		
75		146	
76			130

Temperatura [°C]	R_L [Ω]	R_{Ni} [Ω]	R_{Pt} [Ω]
77	100		
78		148	
79			131
80	100		
81		151	
82			132
83	100		
84		153	
85			134
86	100		
87		155	
88			135
89	100		
90		157	
91			136
92	100		
93		159	
94			137
95	100		

Temperatura [°C]	R_L [Ω]	R_{Ni} [Ω]	R_{PT} [Ω]
96			
97			
98			
99			
100			

CHTODZENIE

100			
99			
98			
97			
96			
95	100		
94		159	
93			137
92	100		
91		158	
90			136
89	100		

Temperatura [°C]	R_L [Ω]	R_{Ni} [Ω]	R_{PT} [Ω]
88		156	
87			139
86	100		
85		154	
84			133
83	100		
82		151	
81			132
80	100		
79		149	
78			131
77	100		
76		147	
75			130
74	100		
73		145	
72			129
71	100		
70		143	

Temperatura [°C]	R_L [Ω]	R_{Ni} [Ω]	R_{PT} [Ω]
69			127
68	100		
67		141	
66			126
65	100		
64		139	
63			125
62	100		
61		137	
60			124
59	100		
58		135	
57			123
56	100		
55		133	
54			122
53	100		
52		131	
51			121

Temperatura [°C]	R_L [Ω]	R_{Ni} [Ω]	R_{Pt} [Ω]
50	100		
49		129	
48			119
47	100		
46		127	
45			118
44	100		
43		125	
42			117
41	100		
40		124	
39			116
38	100		
37		122	
36			115
35	100		
34		120	
33			113
32	100		

Temperatura [°C]	R_L [Ω]	R_{Ni} [Ω]	R_{PT} [Ω]
31		119	
30			112
29	100		