

Report Details

Report ID	FR-2026-004
Location	Hayes Valley - 430 Hayes St
Machine	CBM-001 Siemens EQ.9 Plus Connect
Serial No	SIE-EQ9-20210315-001
Date	2026-06-28
Reported by	Priya K. (Location Manager)

Fault Description

Fault code E-11 (Steam Wand Blockage). Milk steaming was intermittently failing. Resolved the same day by TECH-01 via a manual flush and steam-path clear. No recurrence since 28 Jun 2026.

Requested Action / Technician Notes

- No action required. Logged for maintenance history.
- Monitor for recurrence at the next routine visit.