

Report Details

Report ID	FR-2026-007
Location	Haight - 1601 Haight St
Machine	CBM-004 DeLonghi Maestosa
Serial No	DEL-MAE-20220105-004
Date	2026-07-14
Reported by	Nina T. (Location Manager)

Group-Head Temperature - Morning Samples



Fault Description

Fault code T-05 (Boiler Temperature Instability). Group-head temperature is swinging +/- 4 C around the 93 C setpoint, producing inconsistent extractions. Baristas report visibly uneven crema through the morning rush. Suspected failing temperature probe or scale buildup on the heating element.

Requested Action / Technician Notes

- Inspect and likely replace the temperature probe (DEL-MAE-TPROBE).
- Descale the boiler; water hardness in this district is high.
- Medium priority - quality impact but machine remains operational.