

Sunny Bay Roastery - Fault Report

Report Details

Report ID:	FR-2026-004
Location:	Hayes Valley - 430 Hayes St
Machine:	CBM-001 Siemens EQ.9 Plus Connect
Serial No:	SIE-EQ9-20210315-001
Date:	2026-06-28
Reported by:	Priya K. (Location Manager)
Priority:	CLOSED - Resolved

Fault Description

Fault code E-11 (Steam Wand Blockage). Milk steaming intermittently failing. Resolved same day by TECH-01 (manual flush). No recurrence since 28 Jun 2026.

Requested Action / Technician Notes

No action required. Logged for maintenance history. Monitor for recurrence at next routine visit.