ASSIMANG MANGANESE BLACK BOOK MANG OPEN	MATCHE	CAS Project TMM hazard rating and risk assessment Data and limitations statement	
Item#	Item	Description	
1	Date	All data included in this Hazard rating and risk assessment is based on data available to TerreSauver on 20 October 2024.	
2	Incidents	As of the above date, no BRMO incident data had been received from BRMO.	
3	TMM L7, L8 & L9 list	The CAS level rating list was compiled by BRMO (based on the BRMO risk assessment methodology) in 2019 and approved by the CAS Project Steerco #2 on 20 February 2020. (see Steerco #2 extract to the right)	
4	Visibility diagrams	Visibility risk is determined from "practical experience" and visibility diagrams. Visibility diagrams available as of the above date are included under the TMM type in the relevant worksheets within this document. No other visibility diagrams appear to be available within the BRMO archives.	
5	Procedures	Scaler has 13 related procedures. For a proper risk assessment to be conducted all mine procedures related to TMM operations must be analysed. It is assumed that some 200 procedures would have to be reviewed and this has not been done due to time constraints.	
6	Human discretionary decision making	The hazard and risk assessment rating excludes any discretionary decision making made by operators, pedestrians, supervisors or mine management.	
7	Enforcement	The hazard and risk assessment rating excludes any mine leadership enforcement of procedural discipline and the effectiveness thereof.	
8	Observation	The hazard and risk assessment rating excludes any long term observation of actual operations of each TMM type and the operations that it performs.	

CAS - Background & Context

Steerco meeting #2 - 20th Feb 2020

Compliance with Mine Health & Safety Act (MHSA)







MM	Pedestrian interaction	Vehicle interaction
rills	Level 9	Level 7
oofbolters	Level 9	Level 7
HD's	Level 9	Level 9 (Crawl)
umptrucks	Level 9	Level 9 (Crawl)
caler	Level 9	Level 9 (Crawl)
rader	Level 9	Level 9 (Crawl)
ozers	Level 9	Level 9 (Crawl)
obcat	Level 9	Level 9 (Crawl)
tanitou	Level 9	Level 9 (Crawl)
00%	Level 9	Level 7
V's	Level 9	Level 9 (Crawl)
roto land cruiser-LDV	Level 7	Level 7
merzency vehicles - Ambulance land cruiser	none	none



 Traffic flow analysis

- Activity analysis
- Mine layout
- Traffic management planning
- · Event analysis and improvement

ASSMANG



We 'Connect' to Drive Performance Excellence.







BLACK ROCK MINE OPERATIONS

BRMO CAS implementation Project - TMM type fitment

27th October 2022



Two TMM types that require return to OEM for CAS upgrade:

- Manitou three models to be returned to factory (14 weeks) after each model has been upgraded then the remaining models can be upgraded on site.
- Aard three models must be returned to factory (3 months) for upgrade cannot be upgraded on site.
 - Note: the above does not include TMMs that after inspection reveal that they are in a poor operational state and need to be brought back to OEM specification prior to upgrade.









Data and limitations Page 1