

Weekly Engineering Report

Week 6
04 August 2025 to 10 August
2025



Logo



INDEX

- 1 Departmental Overview (HEAL)
- 2 Shafts & Winders Performance
- 3 Gloria Performance Overview
- 4 Nchwaning 2 Performance Overview
- 5 Nchwaning 3 Performance Overview
- 6 BEV Performance Overview

DEPARTMENTAL OVERVIEW (HEAL)

↗ Highlights

- ✓ [N3] Consistent improvement trend on BEVs, week-on-week.
- ✓ [Gloria] Strong FL & RT availability.
- ✓ [N2] Good overall fleet availability, above target.

↘ Lowlights

- ⚠ [Gloria] Production loss: CV0051 torn for 25m (Wed-Fri outage).
- ⚠ [N2] Plant stoppages and availability of scalers.
- ⚠ [N3] Production targets not met.

🕒 Emerging Issues

- 🕒 [N2] Grader on breakdown (brakes); utility section efficiency concerns.
- 🕒 [Gloria] Labour shortages; relief staffing covering critical roles.
- 🕒 [N3] Scaler OEM deviations noted; Epiroc spares availability critical.

🔑 Priorities

- ⚙ [N2] Install RT50 transmission and commission new scalers.
- ⚙ [Gloria] 9 West dam redesign; submit chute capital (await updated quote).
- ⚙ [N3] Install scaler doors and correct deviations.

Shafts & Winders Performance

Weekly Tons/Hr

Target: 523

394

Weekly RW Availability (%)

Target: 95%

97%

✓ Highlights

- Safewind Control Systems Completed Loadcell Installation in Nch2 + Nch3 Headgear
- 1 x Winder Filter Started

⚠ Lowlights

- Employee Engagement/Resignations Engagement with SGM due to Culture Issues Identified in Section
- Issues with lamp room - PP360, findings from DMR/HQ audits



🕒 Emerging Issues

- Low compliment of Fitters and Riggers in Mechanical Section is still putting pressure on the Section
- Massive impact of providing full Maintenance of Changehouses of all 3 x Shafts
- No Budget Provision for New Changehouse Maintenance Scope

🔑 Priorities

- Nch2 Main Fan No.1 impeller/bearings replacement; address WTW audit findings
- Shaft repairs with Solrock (Wk 6) and prep for DMPR audit (12 Aug 2025)
- Implement NLT FAC recommendations; close lamproom audit findings; employee engagement follow-ups

Nchwaning 3 Weekly Availability Trend




Nchwaning 3 Performance Overview

✓ Safety
Clear

Weekly Avg.
86.14%
(Target: 85%)

⚙ Compliance
SR fleet at 80%
compliance with HD0050
not in service.

Equipment Availability



Key Breakdowns

HD

- Water coolant issues
- Weld hose frame problems

RT

- Drill rig no power

DT Diesel

- Overspeed
- Oil leak
- Gears fault

Nchwaning 2 Weekly Availability Trend




Nchwaning 2 Performance Overview

✓ Safety
Clear

Weekly Avg.
86%
(Target: 85%)

⚙ Compliance
DT, FL, HD, RT, SR fleets
at 100% compliance;
Support Equipment at
89%.

Equipment Availability



Key Breakdowns



FL

- FL66 front propshaft
- FL86 engine cut off

SR

- SR27 wiring
- SR42 boom

Gloria Weekly Availability Trend




Gloria Performance Overview

✓ Safety
Clear

Weekly Avg.
89%
(Target: 85%)

⚙ Compliance
HD fleet at 50%
compliance, other fleets at
100%.

Equipment Availability



Key Breakdowns

FL0083

- Line boring

BEV Fleet

📦 BEV Availability (Wk 6)

- DT BEV: 89% (Above Target)
- FL BEV: 79% (Below Target)

⚡ BEV Service Compliance

- DT BEV: 100%
- FL BEV: 100%

BEV Availability by Equipment Type

DT BEV

Target: 85%

89%

FL BEV

Target: 85%

79%

Key BEV & Battery Themes

Key Breakdowns:

- **FL0098:** EMS error (reported Aug 8 & 9) - critical battery/electrical system issue.
- **FL0107:** Oil leak (Aug 8) impacting operations post-bucket replacement.
- **FL0101:** Tyre damage (Aug 9) taking unit out of service.
- **DT0150:** Park brake engaging due to faulty door switch (initially suspected Strata/CAS issue).

Key Battery Themes:

- FL BEV Availability Root Causes: EMS/electrical faults (FL0098) and hydraulic oil leaks (FL0107) were primary drivers.
- Persistent Battery Charging Issues: DT0150 & DT0163 both required intervention for charging, impacting overall fleet readiness.
- Maintenance Interplay: While scheduled work (bucket replacements) was completed, emergent issues on other units negated availability gains.