

Weekly Engineering Report

Week 2
08 July 2025 to 14 July
2025



 Logo



INDEX

- 1 Departmental Overview (HEAL)
- 2 Shafts & Winders Performance
- 3 Gloria Performance Overview
- 4 Nchwaning 2 Performance Overview
- 5 Nchwaning 3 Performance Overview
- 6 BEV Performance Overview

DEPARTMENTAL OVERVIEW (HEAL)

📈 Highlights

- ✅ **[Gloria]** TMM Availability improved to 83%.
- ✅ **[N2]** Successful DMRE inspection with no major findings.
- ✅ **[N3]** HD availability improved.
- ✅ **[N3]** Major repair on DT 0147 completed, addressing system faults.

📉 Lowlights

- ⚠️ **[Gloria]** TMM availability low (Scaler 62%, FL 64%).
- ⚠️ **[N2]** RT performance below 85% & low Logistics TMM availability.
- ⚠️ **[N3]** Diesel DT availability low due to Strata issues.
- ⚠️ **[N3]** Schedule compliance at monthly low.

🕒 Emerging Issues

- ⚠️ **[Gloria]** HR delay on Shift Foreman recommendation.
- ⚠️ **[N2]** Plant Fitter staffing issues (1 resignation, 1 suspension).
- ⚠️ **[N2]** Feeder damaged from oversized rocks.
- ⚠️ **[N3]** RT outrigger cylinder failures & parts shortages.

🔑 Priorities

- 🔧 **[Gloria]** Expedite parts for SR0037 & line boring for FL0083.
- 🔧 **[N2]** Finalize Main sub breaker installation & update DB legends.
- 🔧 **[N3]** Improve DT maintenance response for Strata issues.
- 🔧 **[N3]** Resolve RT outrigger repairs & parts procurement.

Shafts & Winders Performance

Weekly Tons/Hr

Target: 525

284

Weekly RW Availability (%)

Target: 95%

98.16%

✓ Highlights

- Positives Identified during the DMPR Audit

⚠ Lowlights

- Employee engagement/resignations due to culture issues.
- Lamproom findings from DMPR audit.












🕒 Emerging Issues

- Low compliment of Fitters and Riggers in Mechanical Section

🔧 Priorities

- Fill critical Fitter & Rigger positions.
- Complete shaft repair work with Solrock.
- Address all DMPR audit findings.
- Improve employee engagement culture (with SGM).

Nchwaning 3 Weekly Availability Trend



Nchwaning 3 Performance Overview



Safety

Clear

Weekly Avg.

86%

(Target: 85%)



Compliance

Maintenance compliance
at 95%.

Equipment Availability

HD

91%



RT

85%



SR

89%



DT Diesel

79%



FL Diesel

86%



Key Breakdowns












DT Diesel

- DT0161: Gearbox issues
- DT0160: Brakes & fire suppression
- Ongoing Strata system challenges

HD

- HD0056: Starting issues
- HD0052: Operator/cable availability

Nchwaning 2 Weekly Availability Trend



Nchwaning 2 Performance Overview



Safety

Clear

Weekly Avg.

87.4%

(Target: 85%)



Compliance

Clear

Equipment Availability

HD

96%



RT

81%



SR

88%



DT

82%



FL

90%



Key Breakdowns












DT

- DT120 & DT159: Door sensor faulty

RT

- RT40: Not starting / feed lever
- RT43: Percussion system failure

Gloria Weekly Availability Trend




Gloria Performance Overview

✓ Safety
Clear

Weekly Avg.
86%
(Target: 85%)

⚙ Compliance
Clear

Equipment Availability



Key Breakdowns

SR

- SR0037: E-frame failure

FL

- FL0083: Bucket movement issues

BEV Performance Overview (Nchwaning 3)



Safety

Clear

BEV Availability (Wk 2)

- DT BEV: 77% (Below Target)
- FL BEV: 89% (Above Target)



BEV Service Compliance

- DT BEV: 67%
- FL BEV: 100%

BEV Availability by Equipment Type

DT BEV

Target: 85%

77%

FL BEV

Target: 85%

89%

Key BEV & Battery Themes

DT BEV Breakdowns:

- **DT BEV:** DT0147: Split drive, DT0146: Strata comms, DT0145: Tyre bay issue, Red stop lamp error, Engine cut-off at battery bay
- **FL BEV:** FL0112: Bucket issues, FL0099: Transmission oil leak, No contacting models error, Vehicle sent for repairs

Key Battery Themes:

- Charging & connection errors
- Battery replacement & bay issues
- Critical component failures (split drive, transmission)