





| No. | Quantity | Comment         | Designator | Footprint                                      | Value | Manufacturer Part       | Manufacturer       | Supplier Part | Supplier | LCSC Stock | Mounting Type |
|-----|----------|-----------------|------------|------------------------------------------------|-------|-------------------------|--------------------|---------------|----------|------------|---------------|
| 1   | 2        | 22uF            | C1,C4      | CAP-TH_BD<br>5.0-P2.00-D0<br>.8-FD             | 22uF  | ECR1HPT22<br>0MLL050011 | Jianghai(南通<br>江海) | C216548       | LCSC     |            |               |
| 2   | 2        | 100nF           | C2,C5      | C0402                                          | 100nF | CL05B104KA<br>5NNNC     | SAMSUNG(<br>三星)    | C155422       | LCSC     |            |               |
| 3   | 1        | 1uF             | C3         | C0402                                          | 1uF   | GCM155C71<br>A105KE38D  | muRata(村田<br>)     | C126521       | LCSC     |            |               |
| 4   | 1        | 10uH            | L1         | L1210                                          | 10uH  | NLV32T-100<br>J-PF      | TDK                | C76835        | LCSC     |            |               |
| 5   | 1        | 100kΩ           | R1         | R0603                                          | 100kΩ | HRC0603F1<br>003ENTN    | HC(华橙熊猫<br>)       | C55098343     | LCSC     |            |               |
| 6   | 1        | 10kΩ            | R2         | R0402                                          | 10kΩ  | HP02WAF10<br>02TCE      | UNI-ROYAL(<br>厚声)  | C2759535      | LCSC     |            |               |
| 7   | 1        | 2.2kΩ           | R3         | R0402                                          | 2.2kΩ | RMC1/16SK<br>222FTH     | Walsin(华新<br>科)    | C55260182     | LCSC     |            |               |
| 8   | 1        | BL8034CS8T<br>R | U1         | ESOP-8 L4.<br>9-W3.9-P1.2<br>7-LS6.0-BL-E<br>P |       | BL8034CS8T<br>R         | BL(上海贝岭)           | C511003       | LCSC     |            |               |





