(d) Appropriate equipment shall be issued to the employee prior to startup or at new-hire orientation by the employer. The employee may be required to provide some PPE.

18.13 Training

OSHA requires the company to provide training to each employee who is required to have PPE and to know:

- (a) when PPE is necessary:
- (b) what PPE is necessary;
- (c) how to properly wear, fit, adjust and remove PPE;
- (d) the limitations of the PPE; and
- (e) the proper care, maintenance, useful life and disposal of the PPF

If the company has reason to believe the trained worker does not have the understanding and skill required by the company to use the PPE, the company shall remove the worker from the job until the worker is adequately trained.

Each company is required to certify that each worker has been trained or retrained if there is a job assignment change which presents a new hazard, or the need for retraining is identified. Documentation on the date, type of training and worker's name should be retained as documentation

Figure 18a Date: Additional Control Other* (Specify) STOP SWITCH PROCEDURE CECI May be required to comply with other regulatory and/or company standards LOCKOUT/TAGOUT Prepared By: HOFE COVERINGS SUARIDRAILS/BARRICADES Job: PERSONAL FALL ARREST SYSTEM KNEE GUARDS Feet/Legs PANTS/COVERALLS SAFETY SHOES Head **STHER** Personal Protective Equipment Control (CFR 1910) TAHORAH ORAGNATS JOB HAZARD ASSESSMENT WELDERS JACKET (MAY NOT BE ALL INCLUSIVE) SEEVES HEAT RESISTANT GLOVE Hands/Arms LEATHER GLOVE NEOPRENE GLOVE BUBBER GLOVE SUT RESISTANT GLOVE COLLON WORK GLOVES НЕАВІИС РВОТЕСТІОИ WELDERS HOOD (W/TINTED LENS) Face **EACESHIELD** RESPIRATOR MELDING (GLASSES & GOGGLES) Eyes SAFETY GOGGLES Outside of Car (Landing) Escalator/Moving Walk SAFETY GLASSES W/SIDE SHIELDS CHECK IF APPLICABLE Machine Room Form: SCO. Work Location: Equipment Movement acards Hazards Energized High Voltage Energized Low Voltage Inspecting Controller Overhead Clearances - Space Constraints - Dust/Carbon Dust - Walking Surfaces

· Hazardous Trash

- Housekeeping

Solvents/Oils

- Chemicals

- Temperature Environmental

- De-energized - Use of Meters

Electrical

- Floor Openings

- Projections

Site Conditions

- Paints - Noise

- Stairways

- Ladders

S 2004, NEII, Salem, NY

κi e, 4.

Major Tasks:

Inside of Car

Top of Car

ž

Page 1 of 2

Figure 18b

Inside of Car Machine Boom					MΑ	ĭ	H B	(MAY NOT BE ALL INCLUSIVE)	=	迃	S	Ē						ď	spare	Prepared By:				
				Personal Protective Equipment Control (CFR 1910)	nal P	rotec	tive E	dinb	ment	Cont	rol (6	E.	1910				_			Add	ltion	Additional Control	ntrol	
Work Location:	Н	Eyes	H	Fa	Face	Н		На	Hands/Arms	Arms			완	Head	Feet	Feet/Legs	_			ğ	her*	Other* (Specify)	ify)	
Major Tasks: Steps: 1. 2. 2. 4. 4. 4. 5	CHECK IF APPLICABLE	SAFETY GOGGLES SAFETY GLASSES W/SIDE SHIELDS	WELDING (GLASSES & GOGGLES)	RESPIRELD FACESHIELD	мегревя ноор (м/тіитер Leus)	HEARING PROTECTION	COLTON WORK GLOVES	HUBBER GLOVE	NEOPRENE GLOVE	LEATHER GLOVE	SLEEVES	WELDERS JACKET	TAHGRAH GRAGNATS	язнто	SAFETY SHOES	PANTS/COVERALLS KNEE GUARDS	PERSONAL FALL ARREST SYSTEM	LIFELINE	GUARDRAILS/BARRICADES	HOLE COVERINGS	LOCKOUT/TAGOUT	GFCI STOP SWITCH PROCEDURE		
Site Conditions con't	L					Н	H		Г	\vdash		L		Г	Н	\vdash	H				H	H		
- Falling Objects	H			H		Н	H			Н				П	Н	H	H			П	Н	H		
				H		Н				Н							Н					_		
Mechanical Repairs				H		Н				Н						Н	Н					H		
- Blowers				H		Н				Н						Н	Н					H		
- Welding	L	Е		H		H	H		Н	H	L	L		Г	H	H	H			Г	H	H		
- Soldering	L	Е		H		H	H		Н	H	L	L		Г	H	H	H			Г	H	H		
- Cutting	L	Е		H		Н	H			H	L	L		Г	H	H	H			Г	H	H		
- Hoisting	L			H		Н	H			H	L	L		Г	H	H	H			Г	H	H		
- Grinding	L			H		Н	H		Н	H	L	L		Г	Н	H	L			Г	H	H		
- Sanding/Chiseling				Н		Н	H			Н				П	Н	Н					Н	H		
- Babbitting				H		Н	H							Г	Н	_	_				Н	_		
- Drilling				H		Н	H			Н				П	_	_	_				Н	_		
- Power Accuated Tools	L					Г								Г		_	L							
- Metal Working/Handling						_	_			_				Г		_	_					_		
- Sawing						_	_			_				Г		_	_					_		
- Roping	L					H	L							Г		-	L							
Moving Equipment	L	F				H	H			L				Г		H	L			Г	H	H		
Other (Specify if not all inclusive)	L					H	H			H		L		Г	H	H	L				Н	H		
	Н	П		H		Н	Н		П	Н	Н	Ц		П	Н	Н	Н			П	Н	Н		Ш
		4		\dashv		1	+		1	+	-				+	+	+			T	+	+		
		7		\dashv		+	\dashv		1	\dashv	\dashv	4		1	\forall	\dashv	\dashv	4		1	+	\dashv		
	1	7		+	1	+	+		1	+	+	4		1	+	+	+	4		1	+	+	+	