

Technical data sheet

MULTIline PRO 4.5 mm



Hose liner for the trenchless inner lining of defective, leaking and statically impaired pipes.

Product features		Material features	
Product name	Lateral Repairs MULTIline PRO 4.5 mm	Textile	Polyester
Length	50 m; 100 m / 164 feet; 328 feet	Material	Multi knitted Fleece with One - Sided TPU Coating.
↻ Diameter	70, 80, 100, 125, 150, 200, 225, 250, 300.	Coating	One side TPU
Liner undersized	13 %	Colour	White
Curing techniques	Ambient, Warm (Water / Steam)	Coating colour	Transparent
Negotiating bends	Max. 90°	Storage	Protected from light, dry, 5–30 °C

Features		Length	Resin	Pressure		
Dimension	Bend	L + elongation	kg / m	Inversion (bar)	Curing (bar)	Burst (bar)
DN 70 → 70	Max. 90°	-2 cm/m	on request	0,5	0,4	1,4
DN 70 → 100	Max. 90°	1 cm/m	on request	0,6	0,6	1,4
DN 100 → 100	Max. 90°	-2 cm/m	on request	0,3	0,3	1
DN 100 → 125	Max. 90°	1 cm/m	on request	0,3	0,35	1
DN 100 → 150	Max. 90°	2 cm/m	on request	0,3	0,4	1
DN 125 → 125	Max. 90°	-2 cm/m	on request	0,3	0,3	0,9
DN 125 → 150	Max. 90°	1 cm/m	on request	0,3	0,35	0,9
DN 150 → 150	Max. 90°	-2 cm/m	on request	0,3	0,2	0,8
DN 150 → 200	Max. 90°	1 cm/m	on request	0,25	0,3	0,8
DN 200 → 200	Max. 90°	-2 cm/m	on request	0,3	0,25	0,7
DN 200 → 225	Max. 90°	1 cm/m	on request	0,25	0,3	0,7
DN 200 → 250	Max. 90°	2 cm/m	on request	0,2	0,35	0,7
DN 225 → 225	Max. 90°	-2 cm/m	on request	0,25	0,2	0,6
DN 225 → 250	Max. 90°	1 cm/m	on request	0,2	0,25	0,6
DN 250 → 250	Max. 90°	-2 cm/m	on request	0,25	0,2	0,5
DN 250 → 300	Max. 90°	1 cm/m	on request	0,2	0,25	0,5

Resin quantity — Lateral Repairs app



iPhone
App Store



Android
Google Play

Notice

- Given the diversity of installation conditions and process techniques, the information in this data sheet can only be regarded as non-binding guideline values.
- Length addition: add 5% of the liner length; for bends add the cm value per 45° as listed (on request).
- Final quality depends on the resin system, inversion pressure and curing pressure. We advise against other resin systems or higher pressures and accept no liability.
- All data were determined at 20 °C / 68 °F; bench-scale values that may differ on site.

For further information visit www.lateralrepairs.com or scan the QR codes.

Issue: V2026.1 · 2026.06