Rotation error for each method, best skip Essential Matrix (skip 30) 3.0 Kabsch (skip 60) Kabsch (EM inlers) (skip 20) Kabsch (PnP inliers) (skip 40) 2.5 Magnitude of rotation (radians) PnP (iterative) (skip 30) EPnP (skip 30) 2.0 1.5 1.0 0.5 0.0 360 380 420 440 460 400 +1.455208e9 Time