Rotation error for each method, best skip Essential Matrix (skip 30) 2.5 Kabsch (skip 60) Kabsch (EM inlers) (skip 20) Kabsch (PnP inliers) (skip 40) Magnitude of rotation (radians) 2.0 PnP (iterative) (skip 30) EPnP (skip 30) 1.5 1.0 0.5 0.0 180 200 220 260 280 300 320 240 +1.455208e9 Time