Rotation error for each method, best skip Essential Matrix (skip 30) 3.0 Kabsch (skip 60) Kabsch (EM inlers) (skip 20) Kabsch (PnP inliers) (skip 40) 2.5 Magnitude of rotation (radians) PnP (iterative) (skip 30) EPnP (skip 30) 2.0 1.5 1.0 0.5 0.0 60 20 40 80 +1.4552082e9 Time