Rotation error for each method, best skip Essential Matrix (skip 30) 3.0 Kabsch (skip 60) Kabsch (EM inlers) (skip 20) Kabsch (PnP inliers) (skip 40) 2.5 Magnitude of rotation (radians) PnP (iterative) (skip 30) EPnP (skip 30) 2.0 1.5 1.0 0.5 0.0 250 275 300 350 375 400 425 325 +1.455208e9 Time