

CRAB MODULE HELP

CRAB – something that will bite you in the backside if you don't fix it.

Overview

The term CRAB was created to describe product quality problems. Another way of thinking of this is as a factory non-conformance, a non-conformance that is created by the production department or manifests itself during the build-test-GT process cycle.

It can also be used to track a unit with special circumstances to ensure it is not GT prior to those circumstances being completed, met or an obstruction cleared. This can be special testing requested or needed for engineering, missing documentation, etc.

The CRAB system was created to track defects

- 1) discovered in the production process,
- 2) when the unit is delivered to test or in the testing process, and
- 3) during the final inspection

in order to reduce or prevent recurrence of these problems. This is analogous to a QCPC or turnback system, which are used in many companies.

Process Steps

The flow of the process is as follows

- 1) Anytime during the build process, Production, Test, Engineering or Quality may write and record a non-conformance.
 - a. The Group Leader or Foreman opens the shop page in the intranet, selects ER (Equipment Record) to pull up the unit with a non-conformance.
 - b. Using the lowest tier of blue links, they select the unit CBOM.
 - i. The person can drill down to a package or specific item and write the CRAB against the item related to the problem.
 - ii. the person fills in the CRAB form and clicks the submit button to record the non-conformance
 - c. In the event it involves a material issue, the employee writes and submits an NCR for that item (See NCR Module)
 - d. the employee repeats this procedure for all non-conformances found during the assembly process whether it is related to refrigeration, electrical, sub assembly or mechanical assembly.
- 2) Unit is delivered to test
- 3) Test begins testing the unit
 - a. Any non-conformance (internal or external) is recorded in the form
 - b. Test technicians opens the shop floor homepage and navigates to the unit CBOM
 - c. The technician begins testing the unit and finds a defect
 - i. The technician can drill down to a package or specific part to write the CRAB against

- ii. The technician fills in the CRAB form and clicks submit
- d. The technician repeats this procedure for all non-conformances found during test
- e. When testing is complete, the technician advises assembly, sends the unit returned to assembly as “ready for touch-up”
- 4) Unit is delivered to production for touch up / final assembly
 - a. As CRABs are fixed, the employees who fix the CRABs will sign off the individual CRABs
 - i. Employees will enter their employee number and click the “fixed” button & provide action taken
 - b. As CRABs are fixed, they are inspected by the Group Leader
 - i. The Group Leader will log into the ER through the website
 - ii. The Group Leader will click on the CRAB link
 - iii. The Group Leader will click the “Inspection” link
 - iv. The Group Leader will enter his/her employee number
 - v. The Group Leader will click the submit link
 - c. When all CRABs are inspected, the Group Leader advise Quality the unit is “ready for inspection”
- 5) Unit is inspected by QA
 - a. Quality Assurance enters and writes CRABS as found
 - b. CRABs are fixed and inspected after final inspection, before final run or function check.
 - c. Quality Assurance reviews the online CRAB list to ensure that all CRABs are closed
 - d. Quality Assurance confirms the unit is “ready for final run”
- 6) Unit goes to test for final run
 - a. Any CRABs not able to be inspected during final assembly or QA inspection are inspected at final run (i.e. leaks, where the unit needs to be running to inspect for proper resolution)
 - b. Test technician signs off CRAB as being inspected
 - c. Test technician advises unit is “ready for GT” when the final run is complete
- 7) The QAM will review the CRAB list for closure and officially GT the unit after all CRABS are cleared. *The system will not allow a GT entry without all CRABS completed and accepted for the specific unit.*

Administrative Rights

- The QAM and the PM have admin rights to the entire module.
- Foremen, Group Leaders, Test technicians have access to the module through the website but do not have edit rights
- Direct Employees can only input data

Metrics

Several metrics have been established to monitor and improve product quality to test.


1. CRABs by unit family (i.e. ACU, ASU, GPU)
2. CRABs by department (i.e. Assembly, Electrical, Refrigeration, Purchasing, Sales)

3. CRABs by CRAB code (i.e. 100, 110, etc.)
4. CRABs by model (i.e. ASU-600-270-DDP, ACU-804-CUP, GPU-4090-T-CUP)


These classifications allow us to look at the major groups in manufacturing to target where efforts need to be made to improve product quality. The metrics are taken automatically from the data that is entered at test.

CRABLIST MODULE – WRITING THE CRAB FOR PRODUCTION, TEST OR INSPECTION

CRABS can only be entered initiated in the shop page – no access for entry is in the website



Use the EQUIPMENT RECORD (ER) module link to enter CRABS for the specified unit you are working on.



The ER contains all the information for the unit – serial numbers, GT date, Shipping Date, all record files, etc.

To record the crab you need to know what the issue is, and the system, assembly or part that is causing the issue. Select the CBOM on the LOWER BLUE links below the line.

If you do not know the system or part causing the issue, you must find this first to record the CRAB.

Also note, if the part is to be filed as an NCR, file the NCR first because you will need the number to fill out the CRAB.

Microsoft Internet Explorer

tools Help

shop/autoselect.php?m[0]=cbom&m[1]=view&sn=110652

TLD WINShop Floor Homepage | CBOM

Home | ER | CBOM | BOM | Drawings | NCR | CRAB | EAP | Shop Cams | ISOSoft | Procedures | MSDS

Search CBOM | Multi | Variant Config


CBOM #110652
Home page


Get Schematics


Get Assembly Instructions


Document List

CBOM for 110652 from Company 400 as of


Tips: You can sort the table below by clicking the header titles.

#	PN	Code	Description	Qty
10	1044929-2	IMB	SHEETMETAL PACKAGE, DUAL	1
20	1043872	SPL	TRAILER PACKAGE	1
30	1045816	SPG	ENGINE SYSTEM	1
35	1045941	IEK	BATTERY SYSTEM	1
40	1044350	IMG	FUEL SYSTEM	1
50	1037868	IMG	EXHAUST SYSTEM	1
60	1032817-8	IMK	GENERATOR PKG. (TLD,140KVA)	1
70	1045809-2	SPK	ELECTRICAL BOX ASSEMBLY,DUAL	1
80	1038484-2	SPA	FINAL PREP. PKG. (2)OUT	1
90	1037869		CONSUMABLES PACKAGE	1
170	1044375-1	SPN	KIT, LFWS RED STROBE	1
220	1012389-040	SPK	CABLE ASSEMBLY, AC	2
500	101-09-0030	DCL	DOCUMENT LIST	
1000	1043743	CH0	GPU-4000 MANUAL, CH.0 [en]	
1010	1043744	CH1	GPU-4000 MANUAL, CH.1 [en]	
1020	1043745	CH2	GPU-4000 MANUAL, CH.2 [en]	
1030	1043746	CH3	GPU-4000 MANUAL, CH.3 [en]	

You must select a system package before you can write a CRAB.

For example, if the unit is painted the wrong color, you would select the sheet metal package.
After this entry on the next screen, you may select the sheet metal package by clicking on the word CRAB on the right side of the page.

If it is a particular panel, you would need to continue until you find the panel to which the CRAB applies.



Note after leaving the top level CBOM list, all numbers have CRAB on the right side for you to choose for the issue.

Once you have found the part, assembly or system, select this CRAB link on the right to report it.

This screen appears after selecting CRAB. Now you will write the CRAB.

You must not only fill out the Full Description, but ***you also must enter the Corrective Action that is to be taken to resolve the issue.*** (Either what you do to fix it or what you want done to make it acceptable.)

B - Microsoft Internet Explorer

Tools Help

Search Favorites

3/shop/autoselect.php?m[0]=crab&m[1]=new&pn=1043795

TLD WINShop Floor Homepage\CRAB

[Home](#) | [ER](#) | [CBOM](#) | [BOM](#) | [Drawings](#) | [NCR](#) | [CRAB](#) | [EAP](#) | [Shop Cams](#) | [ISO](#)

WARNING: You are about to create a CRAB for this unit...

Equipment SN#	T23483
Status	IN PRODUCTION
Date Entered	2010-04-26
Type	Ground Power Units
Project#	110652
Model	GPU-4140-T-CUP

Submit CRAB for

Initiator Employee Number

Fill Dept field for Internal CRAB

Stage

Dept

Fill NCR# field for External CRAB

NCR#

New CRAB for 1043795

CRAB Code

Full Description

Corrective Action

Initiator Employee Number: Fill in your employee assigned number.

Stage: Select if it is in Test or Final (Final Inspection)


NCR: Fill in an NCR number if you have filed an NCR for reporting an issue related to this finding. This is for vendor or supplier issues.

CRAB Code: Select the general issue from the dropdown screen. If it is not listed here, use Miscellaneous.

Full Description: write what was the issue you found, where it was found and any other related information that will help employees find and understand the problem.

Corrective Action: write what you do as you fix the issue or what you need done in order solve the problem

After all of this is filled out, you select the **Submit** button at the bottom.



After you select submit, the system will tell you if the CRAB was accepted and recorded.

You may review the crab to check your data if necessary.

General	
CRAB#	5
BU	TLD WIN
Part Number	1043795
Description	Manual box SN label missing
Stage	Final
Who	INTERNAL
Department	Assembly
Code	200

Initiated	
Employee Number, Found By	0
Entered Date	2010-06-24 11:33:36

Fixed	
Employee Number, Fixed By	0
Signed Date	0000-00-00 00:00:00

Inspected	
Employee Number, Inspected By	0
Inspected By	
Signed Date	0000-00-00 00:00:00

Information is now available to see, get fixed and have it inspected by a supervisor or team leader to complete the finding.

Reporting the CRAB as completed or “FIXED”

Note: All CRABS to be fixed or recorded must be entered through the shop floor page. No entry is available through the website page.

ge\ER\SN:T23483 - Microsoft Internet Explorer

111.1.189/shop/autoselect.php?m[0]=er&m[1]=view&id=23483

TLD WIN Shop Floor Homepage | ER\SN:T23483

Home | ER | CBOM | CBOM | Drawings | NCR | CRAB | EAP | Shop Cams | ISOSoft | Procedures | M

General | **CRAB** | Component List | Submit SN | CBOM

NOTE: To create a CRAB, use the CBOM to navigate to the affected part and hit the CRAB link next to the part.

General

Equipment ID#	23483
Equipment SN#	T23483
Status	IN PRODUCTION
Date Entered	2010-04-26
ESR ID#	0
Customer Asset#	
Type	Ground Power Units
Model	GPU-4140-T-CUP
Batch Qty	1
Hour meter	0
Manufacturer location	TLD WIN
Airport	
Unit Location Short	TBA
Description of Installed Options	GPU-4140-T-CUP (2EA) - 2/0 AC cable, 90 KVA rated, 40 feet long with aircraft plug Low fuel shutdown, with warning (red, flashing)
SOR Line#	12790
SOR Unit ID#	9465
Sales Organization	TLD AME
Sales Rep Email	DE LA LLANA, Rene
Agent Name	
MFG Comments	
MFG Project#	110652
MFG SO#	552395
Estimated Green Tag Date	2010-06-24
Actual Green Tag Date	0000-00-00
Actual Ship Date	0000-00-00
Date, Revenue Recognition, SSO	0000-00-00
Date, Revenue Recognition, Factory	0000-00-00
CBOM Manual Publishable	Y
Length (in mm)	3962
Width (in mm)	1524
Height (in mm)	1930
Weight (in Kg)	2604

Select the ER on the shop floor homepage on the top line of the blue links and enter the unit serial number

To see and find the CRABS you want to report completed select the blue CRAB link on the bottom line.



shop/autoselect.php?m[0]=er&m[1]=view&m[2]=crabs&id=23483

TLD WIN\Shop Floor Homepage\ER\SN:T23483

Project# or SN#: Search
[Home](#) | [ER](#) | [CBOM](#) | [BOM](#) | [Drawings](#) | [NCR](#) | [CRAB](#) | [EAP](#) | [Shop Cams](#) | [ISOsoft](#) | [Procedures](#) | [MSDS](#)
[General](#) | [CRAB](#) | [Component List](#) | [Submit SN](#) | [CBOM](#)

CRABS

Tips: You can sort the table below by clicking the header titles.

CRAB#	Entered Date	Part Number	Description	Stage	Who	Department	Code	Employee Number, Found By	Employee Number, Fixed By	Signed Date	Fixed
4	2010-06-24 11:32:18	1043795	SN label for manual box missing	Final	INTERNAL	Assembly	200	808		0000-00-00 00:00:00	Fixed
5	2010-06-24 11:33:36	1043795	Manual box SN label missing	Final	INTERNAL	Assembly	200			0000-00-00 00:00:00	Fixed

This will provide you access to all CRABS written on this unit, who fixed them. If you need to go back and "fix" the crab, select the blue link to the right.

The screenshot shows the TLD WIN\Shop Floor Homepage for SN:T27736. The page includes a navigation bar with links like Home, ER, CBOM, BOM, ITEM, Drawings, NCR, CRAB, EAP, Shop Cams, ISOsoft, Procedures, and MSDS. Below the navigation bar, there is a section for CRAB#19206 Fixed Signoff. This section contains a form with fields for Employee Number, Fixed By (808), and Comments (Tightened site glass, no longer leaking). A red circle highlights the Submit button, which has a tooltip that says "verifies required test". Below the form is a table of CRABS. The table has columns for CRAB#, Entered Date, Part Number, Description, Corrective Action, Stage, Who, Department, Code, Employee Number, Found By, Employee Number, Fixed By, Signed Date, and Fixed. The table lists several CRABS, including CRAB#19206, 18768, 18767, 18766, 18709, and 18999. Each row in the table has a blue link in the Fixed column, which is highlighted by a red circle and an arrow pointing to the Submit button in the form above.

CRAB#	Entered Date	Part Number	Description	Corrective Action	Stage	Who	Department	Code	Employee Number, Found By	Employee Number, Fixed By	Signed Date	Fixed
19206	2012-10-15 12:42:47	1044929-2	Leak on oil separator site glass	Tighten site glass and check for leak. If not resolved, replace site glass.	Assy	INTERNAL	Assembly	300	808		0000-00-00 00:00:00	Fixed
18768	2012-10-03 09:16:50	1057803	base structure had lots of white powders.	these white powder need to be clean from the base.	QA	INTERNAL	Vendor	010	3719	988	2012-10-12 09:52:37	Fixed
18767	2012-10-03 09:13:12	1057803	missing white perimeter reflectors	install the white perimeter reflectors to the four are of base corners	QA	INTERNAL	Assembly	190	3719	988	2012-10-03 09:32:52	Fixed
18766	2012-10-03 09:11:56	1057803	brake test to be performed	brake test to be done	QA	INTERNAL	Unknown	091	3719	3719	2012-10-03 14:38:15	Fixed
18709	2012-10-01 10:55:11	1048586-2	wire #175 wired incorrectly to terminal 10 on KB	wire #175 most wired to terminal on KB, if the hour meter installed	Test	INTERNAL	Electrical	130	3773	3757	2012-10-01 10:54:12	Fixed
18999	2012-09-30	1048586-2	gom blows fuse on power	replace gom, notify vendor	Test	EXTERNAL	Vendor	080	389	3537	2012-10-01	Fixed

Selecting the link will provide a field to appear at the top of the page to the left. Enter your employee number, enter the action taken to fix the issue and select the submit button.

CRAB\CRAB#4 - Microsoft Internet Explorer

File Tools Help

Search Favorites

.1.189/shop/autoselct.php?m[0]=crab&m[1]=view&id=4

TLD WIN\Shop Floor Homepage\CRAB\CRAB#4

[Home](#) | [ER](#) | [CBOM](#) | [BOM](#) | [Drawings](#) | [NCR](#) | [CRAB](#) | [EAP](#) | [Shop Cam](#)

[General](#) | [Log](#) | [ER](#)

General

CRAB#	4
BU	TLD WIN
Part Number	1043795
Description	SN label for manual box missing
Stage	Final
Who	INTERNAL
Department	Assembly
Code	200

Initiated

Employee Number, Found By	808
Entered Date	2010-06-24 11:53:24

Fixed

Employee Number, Fixed By	808
Signed Date	2010-06-24 11:53:24

Inspected

Employee Number, Inspected By	0
Inspected By	
Signed Date	0000-00-00 00:00:00

If you select the number to the left, you can see the full reported crab.

This will clear the crab and report it as complete.


After a supervisor checks the work, then enters his approval in the system. **Please note:** any CRABS left unsigned and unresolved will prevent a GT from being completed. All CRABS absolutely MUST be completed and cleared for a unit to achieve GT status.

CRAB Supervisor Signoff



Enter the Website to close out supervisor inspection to confirm all Corrective Actions on the product CRAB list are closed.

Select "SUPPORT" at the top of the page.



In the Product Support home page select the ER (Equipment Record)

Internet Explorer

ites Tools Help

Search Favorites

l-gse.com/en/private/index.php

TLD **www.TLD-GSE.com**

HOME | Account | Calendar | Directory | Corporate | TLD Direct | News | Finance | Sales | Parts | Inventory | Support | Service | Mfg
Personnel | PDC

Support Module\ER

[Home](#) | [Personnel](#) | [PDC](#) | [ER](#) | [WC](#) | [SB](#) | [Pubs](#) | [ODP](#)
[Home](#) | [Search](#) | [By Component](#) | [Reports](#)

Equipment Records Homepage

Search by serial number.

T23199

Recently Shipped Equipment

Tips: You can sort the table below by clicking the header titles.

ID#	SN#	Factory	Customer	Model	Airport Code	Ship Date
23695	T23695	TLD WIN	PIEDMONT AIRLINES (US AIRWAYS EXPRESS)	ASU-600-180-DDP	SAT	2010-07-08
23438	T23438	TLD STL	CASAVIA	JET-16	AJA	2010-07-08
23437	T23437	TLD STL	CASAVIA	JET-16	AJA	2010-07-08
22868	T22868	TLD WIN	GESFA SRL / FIRENZE AIRPORT	GPU-4090-T-CUP-28		2010-07-08
22867	T22867	TLD WIN	GESFA SRL / FIRENZE AIRPORT	GPU-4090-T-CUP-28		2010-07-08
21551	T21551	TLD SHE	Chengdu Airport Cargo Station	TXL-838-WID		2010-07-08
23284	T23284	TLD STL	TURKISH GROUND SERVICES	ABS-580		2010-07-07
23283	T23283	TLD STL	TURKISH GROUND SERVICES	ABS-580		2010-07-07
23282	T23282	TLD STL	TURKISH GROUND SERVICES	ABS-580		2010-07-07
23593	T23593	TLD STL	LUBOR KULHAVY SRO / KOSICE AIRPORT	ABS-580		2010-07-06

Enter the serial number of the unit you have inspected for CRABS.

Internet Explorer

h-gse.com/en/private/index.php

TLD **www.TLD-GSE.com**

HOME | Account | Calendar | Directory | Corporate | TLD Direct | News | Finance | Sales | Parts | Inventory | Support | Service | Mfg | RANGER | HR | MIS
Personnel | PDC | ER | WC | SB | Pubs | ODP

Support Module\ER
[Home](#) | [Personnel](#) | [PDC](#) | [ER](#) | [WC](#) | [SB](#) | [Pubs](#) | [ODP](#)
[Home](#) | [Search](#) | [By Component](#) | [Reports](#)

Equipment by LOCATION, TYPE

TBA

SN#	Asset#	Type	Customer Name	Model	Location
Ground Power Units					
T23199		Ground Power Units	MAP HANDLING LOGISTICS	GPU-4120-T-DUP	TBA

Enter via spyglass link for the unit

Internet Explorer

h-gse.com/en/private/index.php

TLD **www.TLD**

HOME | Account | Calendar | Directory | Corporate | TLD Direct | News | Finance | Sales | Parts | Inventory | Support | Service | Mfg | RANGER | HR | MIS
Personnel | PDC | ER | WC | SB | Pubs | ODP

Support Module\ER\SN:T23199
[Home](#) | [Personnel](#) | [PDC](#) | [ER](#) | [WC](#) | [SB](#) | [Pubs](#) | [ODP](#)
[Home](#) | [Search](#) | [By Component](#) | [Reports](#)
[General](#) | [Tasks](#) | [Customer](#) | [WC](#) | [SN](#) | [SR](#) | [TOC](#) | **CRAB** | [Pubs](#) | [Schem](#) | [Opts](#)

Not shipped yet.
 Mark this unit as AVAILABLE FOR SALE

General

Equipment ID#	23199
Equipment SN#	T23199
Status	IN PRODUCTION
Date Entered	2010-03-16
ESR ID#	0
Customer Asset#	
Type	Ground Power Units
Model	GPU-4120-T-DUP

Confirm you are in the correct unit record, then select CRAB

Internet Explorer

Tools Help

Search Favorites

.com/en/private/index.php

TLD **www.TLD-GSE.com**

HOME | Account | Calendar | Directory | Corporate | TLD Direct | News | Finance | Sales | Parts | Inventory | Support | Service | Mfg | RANGER | HR | MIS
Personnel | PDC | ER | WC | SB | Pubs | ODP

Support Module\ER\SN:T23199

Home | Personnel | PDC | ER | WC | SB | Pubs | ODP
Home | Search | By Component | Reports
General | Tasks | Customer | WC | SN | SR | TOC | CRAB | Pubs | Schem | Opts | Files | Log | Edit | CBOM | SOR Line#12662

CRABs

Tips: You can sort the table below by clicking the header titles.

CRAB#	BU	Status	Entered Date	Part Number	Description	Stage	Who	Department	Code	Found By	Fixed By	Fixed Date	Inspected By	Inspected Name	Inspected Date	Inspected
7	TLD WIN	PENDING	2010-07-08 09:19:36	1031395-0700	TEST CRAB Battery terminals not greased (dielectric, over to protect)	Final	INTERNAL	Electrical	010	808	808	2010-07-08 09:19:36			0000-00-00 00:00:00	Inspected
6	TLD WIN	PENDING	2010-07-08 09:20:20	1046058	TEST CRAB Rust on inner hubs. Clean up, touch up as required.	Final	INTERNAL	Assembly	260	808	808	2010-07-08 09:20:20			0000-00-00 00:00:00	Inspected

This will take you to the list of CRABs for the unit. It shows these have been fixed, so it is ready to close.

After you have physically checked the unit, select the blue INSPECTED link on the right.

Internet Explorer

Tools Help

Search Favorites

.com/en/private/index.php

TLD **www.TLD-GSE.com**

HOME | Account | Calendar | Directory | Corporate | TLD Direct | News | Finance | Sales | Parts | Inventory | Support | Service | Mfg | RANGER | HR | MIS
Personnel | PDC | ER | WC | SB | Pubs | ODP

Manufacturing\QA\CRABS (BETA)\CRAB#7

Home | Personnel | NCR | CPA | SCAR | GT | CRABS(BETA) | Intellex | Procedures
Home | By number | Search | Reports | Maintain CRABS
General | Tasks | Links | Files | Log | Inspected | Edit | ER

WARNING: You are about to signoff CRAB#7 as inspected.
Enter your employee id number to confirm.

*Employee Number, Inspected By

Comments
Checked, crab is closed.

* denotes required field

Employee number


Comments

Select SUBMIT button to close

This screen will warn you are about to close a CRAB, a non-conformance with the product.

Enter your employee number, then enter comments, (i.e., brake test passed, item fixed, etc).

Select the SUBMIT button at the bottom to close.



Manufacturing\QA\CRABS (BETA)\CRAB#7

[Home](#) | [Personnel](#) | [NCR](#) | [CPA](#) | [SCAR](#) | [GT](#) | [CRABS\(BETA\)](#) | [Intelex](#) | [Procedures](#)
[Home](#) | [By number](#) | [Search](#) | [Reports](#) | [Maintain CRABS](#)
[General](#) | [Tasks](#) | [Links](#) | [Files](#) | [Log](#) | [Inspected](#) | [Edit](#) | [ER](#)

SUCCESS: Crab#7 inspection signed off

General

CRAB#	7
BU	TLD WIN
Part Number	1031395-0700
Description	TEST CRAB Battery terminals not greased (dielectric, over to protect)
Stage	Final
Who	INTERNAL
Department	Electrical
Code	010

Initiated

Employee Number, Found By	808
Entered Date	2010-07-08 16:01:12

Fixed

Employee Number, Fixed By	808
Signed Date	2010-07-08 09:19:36

Inspected

Employee Number, Inspected By	808
Inspected By	REIS, Susan
Signed Date	2010-07-08 16:01:12



Support Module\ER\SN:T23199

[Home](#) | [Personnel](#) | [PDC](#) | [ER](#) | [WC](#) | [SB](#) | [Pubs](#) | [ODP](#)
[Home](#) | [Search](#) | [By Component](#) | [Reports](#)
[General](#) | [Tasks](#) | [Customer](#) | [WC](#) | [SN](#) | [SR](#) | [TOC](#) | [CRAB](#) | [Pubs](#) | [Schem](#) | [Opts](#) | [Files](#) | [Log](#) | [Edit](#) | [CBOM](#) | [SOR Line#12662](#)

CRABS

Tips: You can sort the table below by clicking the header titles.

CRAB#	BU	Status	Entered Date	Part Number	Description	Stage	Who	Department	Code	Found By	Fixed By	Fixed Date	Inspected By	Inspected Name	Inspected Date	Inspected
7	TLD WIN	PENDING	2010-07-08 16:01:12	1031395-0700	TEST CRAB Battery terminals not greased (dielectric, over to protect)	Final	INTERNAL	Electrical	010	808	808	2010-07-08 09:19:36	808	REIS, Susan	2010-07-08 16:01:12	Inspected
6	TLD WIN	PENDING	2010-07-08 09:20:20	1046058	TEST CRAB Rust on inner hubs. Clean up, touch up as required.	Final	INTERNAL	Assembly	260	808	808	2010-07-08 09:20:20			0000-00-00 00:00:00	Inspected

Continue closing CRABS until all are cleared and inspected.

When all CRABS are inspected, responsibility to close the unit then goes to QA.


Log out, you are done.

If successful, the screen will say it closed


Select your browser back arrow button and it will return you to the list of CRABS for this unit.

TLD Shop Employees

How to review unit CRABS and report fixes complete



You start by going to the local shop home page for your factory.
Select ER for Equipment Record, to get to the generated CRAB list you are to work & fix.



Enter the serial number including the "T" to go to the Equipment Record (ER) page

Shop Floor Homepage\ER\SN:T23199 - Microsoft Internet Explorer

Address: http://192.111.1.189/shop/autoselect.php?m[0]=er&m[1]=view&id=23199

TLD WIN\Shop Floor Homepage\ER\SN:T23199 Project# or

Home | ER | CBOM | BOM | Drawings | NCR | CRAB | EAP | Shop Cams | ISOsoft | Procedures | MSDS

General | **CRAB** | Component List | Submit SN | CBOM

NOTE: To create a CRAB, use the CBOM to navigate to the affected part and hit the CRAB link next to the part.

General

Equipment ID#	23199
Equipment SN#	T23199
Status	IN PRODUCTION
Date Entered	2010-03-16
ESR ID#	0
Customer Asset#	
Type	Ground Power Units
Model	GPU-4120-T-DUP
Batch Qty	1
Hour meter	0
Manufacturer location	TLD WIN
Airport	
Unit Location Short	TBA
Description of Installed Options	GPU-4120-T-DUP Tier3/Com3 Safety blockade Cable 20 AC 30 ft Rub rails (plastic)

Use lower line of links to get to CRAB list

Unit serial number

Double check and be sure you are in the correct serial number unit.

Select CRAB in the LOWER row of blue links.

SN:T23199 - Microsoft Internet Explorer

Tools Help

Address: 39/shop/autoselect.php?m[0]=er&m[1]=view&m[2]=crabs&id=23199

TLD WIN\Shop Floor Homepage\ER\SN:T23199 Project# or SN# Search

Home | ER | CBOM | BOM | Drawings | NCR | CRAB | EAP | Shop Cams | ISOsoft | Procedures | MSDS

General | CRAB | Component List | Submit SN | CBOM

CRABS

Tips: You can sort the table below by clicking the header titles.

CRAB#	Entered Date	Part Number	Description	Stage	Who	Department	Code	Employee Number, Found By	Employee Number, Fixed By	Signed Date	Fixed
7	2010-07-08 09:15:20	1031395-0700	TEST CRAB Battery terminals not greased (dielectric, over to protect)	Final	INTERNAL	Electrical	010	808		0000-00-00 00:00:00	Fixed
6	2010-07-08 09:12:06	1046058	TEST CRAB Rust on inner hubs. Clean up, touch up as required.	Final	INTERNAL	Assembly	260	808		0000-00-00 00:00:00	Fixed

This will list all CRABS open for the unit

Open the CRAB you fixed & report it done and completed. Direction of what has to be done will be listed. Complete the reporting of completing it by selecting the blue FIXED link on the right side

SN:T23199 - Microsoft Internet Explorer

Tools Help

Search Favorites

99/shop/autoselect.php?m[0]=er&m[1]=view&m[2]=crabs&m[3]=fixed&id=23199&crabid=7

TLD WIN\Shop Floor Homepage\ER\SN:T23199 Project# or SN# Search

Home | ER | CBOM | BOM | Drawings | NCR | CRAB | EAP | Shop Cams | ISOSoft | Procedures | MSDS

General | CRAB | Component List | Submit SN | CBOM

CRAB#7 Fixed Signoff

Employee Number, Fixed By Submit

CRABs

Tips: You can sort the table below by clicking the header titles.

CRAB#	Entered Date	Part Number	Description	Stage	Who	Department	Code	Employee Number, Found By	Employee Number, Fixed By	Signed Date	Fixed
7	2010-07-08 09:15:20	1031395-0700	TEST CRAB Battery terminals not greased (dielectric, over to protect)	Final	INTERNAL	Electrical	010	808		0000-00-00 00:00:00	Fixed
6	2010-07-08 09:12:06	1046058	TEST CRAB Rust on inner hubs. Clean up, touch up as required.	Final	INTERNAL	Assembly	260	808		0000-00-00 00:00:00	Fixed

Enter your employee number in the open field, then select the SUBMIT button under where you entered your number.

ER\SN:T23199 - Microsoft Internet Explorer

tes Tools Help

Search Favorites

.1.189/shop/autoselect.php

TLD WIN\Shop Floor Homepage\ER\SN:T23199 Project# or SN# Search

Home | ER | CBOM | BOM | Drawings | NCR | CRAB | EAP | Shop Cams | ISOSoft | Procedures | MSDS

General | CRAB | Component List | Submit SN | CBOM

SUCCESS: Crab# 7 signed off

CRABs

Tips: You can sort the table below by clicking the header titles.

CRAB#	Entered Date	Part Number	Description	Stage	Who	Department	Code	Employee Number, Found By	Employee Number, Fixed By	Signed Date	Fixed
7	2010-07-08 09:19:36	1031395-0700	TEST CRAB Battery terminals not greased (dielectric, over to protect)	Final	INTERNAL	Electrical	010	808	808	2010-07-08 09:19:36	Fixed
6	2010-07-08 09:12:06	1046058	TEST CRAB Rust on inner hubs. Clean up, touch up as required.	Final	INTERNAL	Assembly	260	808		0000-00-00 00:00:00	Fixed

The next screen will tell you if it accepted the entry, and your number will show in the Employee Number, Fixed by field.

If you fixed other CRABS, continue to the next one until you have completed all the ones for the work you performed.

When all CRABS are done, advise your Supervisor you are ready for him/her to inspect your work.

Document History

REV	DATE	DESCRIPTION OF STATUS, CHANGES	REF
Released	25 Aug 10	Original Release	RT
A	4 May 12	Add ability for Production personnel to record "CRABS", page 1process overview, pg 2-8 added production and updated notes to be clearer in how to enter the crab and how to report fixing a crab sections.	S.Reis
B	28 Sept 12	Add a field for the person "fixing" the unit to make a comment, trained and added engineering to write crabs, updated process in intro area to not mention "buttons" that don't exist, updated screen shot showing comment field for "fixed by"	S.Reis