



How to mark a unit as having had a Service Bulletin performed on it.

1. Go to the Service Module and click on Bulletins in the left hand side menu. Find the relevant service bulletin either by doing a search using function number 3 or browsing using function number 1. Remember that service bulletin numbers do not have any prefixes such as 'sb'. Always use the numeric number only.



2. Once you have found the correct service bulletin, click the magnifying glass to view the details.



3. At the top of the service bulletin, click the 'Show Stats' link.

TLD Internal Homepage - Microsoft Internet Explorer

File Edit View Favorites Tools Help

TLD www.TLD-GSE.com

HOME | My Account | Directory | Corporate | Sales | News | Inventory | TLD Direct | Service | Manufacturing | RANGER | Admin

Help

Service Bulletins

[Show Stats](#) | [Plain View](#) | [Duplicate](#) | [Edit](#) | [Email](#) | [Delete](#)

[Up](#) | [Back](#)

SB #####	2147
Type	SERVICE BULLETIN
Factory SB#	282
Brand	ERMA
Entered By	FREMONT, Olivier, TLD Europe
Date (yyyy-mm-dd)	2004-03-10
Title	Bridge lifting counter balance valves replacement
Description	
Urgency	SB: COMPULSORY
Filename	
On Extranet?	NO

SN ranges covered | Add lines

Model	From SN	To SN	SN List
121			TLC003; TLC007; TLC008; TLC009; TLC010; TLC016; TLC017; TLC018; TLC020; TLC021

Files | Add lines

Date (YYYY-MM-DD)	File description	Filename
2004-10-29	TLC004 Complete	

4. The next page will be a report showing all units affected by the service bulletin. Any relevant service records will be shown below the serial number of the machine. Next to each serial number are two links: "Mark this unit as COMPLETE for this SB" and "Go to Equipment Record". Clicking on the first link will automatically create a service record

for the machine with all the required fields completed.

TLD Internal Homepage - Microsoft Internet Explorer

www.TLD-GSE.com

HOME | My Account | Directory | Corporate | Sales | News | Inventory | TLD Direct | Service | Manufacturing | RANGER | Admin

Service Module
HOME
Equipment
Warranty
Bulletins
Vault Status
Links

Admins
Equipment
Warranty
Customers
Models
Manuals
Documents
Doc from BOM
TESTING 7165

SB Status per Equipment for SB#2147

TLC003	Mark this unit as COMPLETE for this SB Go to Equipment Record
WARNING: Compulsory SB has NOT been performed on this unit yet.	
TLC007	Mark this unit as COMPLETE for this SB Go to Equipment Record
WARNING: Compulsory SB has NOT been performed on this unit yet.	
TLC008	Mark this unit as COMPLETE for this SB Go to Equipment Record
WARNING: Compulsory SB has NOT been performed on this unit yet.	
TLC009	Mark this unit as COMPLETE for this SB Go to Equipment Record
WARNING: Compulsory SB has NOT been performed on this unit yet.	
TLC010	Mark this unit as COMPLETE for this SB Go to Equipment Record
WARNING: Compulsory SB has NOT been performed on this unit yet.	
TLC016	Mark this unit as COMPLETE for this SB Go to Equipment Record
WARNING: Compulsory SB has NOT been performed on this unit yet.	
TLC017	Mark this unit as COMPLETE for this SB Go to Equipment Record
Service Record#2952 - SB 2147 factory SB 262 replacement of bridge counterbalance valve	

Local intranet

5. The next page confirms the creation of the service record. From here you can edit the service record to add more information or go back to the list of affected units. It is very important that the Status, Work Type and Reason fields in the Service Record are not modified otherwise the machine will not be marked as being done.

TLD Internal Homepage - Microsoft Internet Explorer

www.TLD-GSE.com

HOME | My Account | Directory | Corporate | Sales | News | Inventory | TLD Direct | Service | Manufacturing | RANGER | Admin

Service Module
HOME
Equipment
Warranty
Bulletins
Vault Status
Links

Admins
Equipment
Warranty
Customers
Models
Manuals
Documents
Doc from BOM
TESTING 7165

SB Status per Equipment for SB#2147

A new service record has been created to show that SERVICE BULLETIN# 2147 has been marked as COMPLETED for EQUIPMENT ID# 5743

I want to edit the Service record
Take me back to list

Done

Local intranet