




Service Bulletin Management Process

Rev02 – December 2009

Preamble



- Today, one fact is that, in order to react to product issues and also to continuously improving its products, TLD issues an average of 15 bulletins per month affecting each month hundreds of units
- The second fact is that the SB implementation rate is to today far too low to be satisfactory
- SB implementation is not only the problem of the PSM and Service Managers, their implementation affects our reputation and then requires more TLD Executives involvement
- The TLD SB management is a three step process launched by the factory, implemented by the service managers with an extremely important role of the SSO director in the decision making process.
- To help this process, new internal rules as well as new INTRANET tools have been put in place to help all TLD employees involved in the SB process. The purpose of this document to describe them.

SB Guidelines:

- A Bulletin is raised by a TLD factory when there is a need to act on an equipment that was released (**Green-tag**)
- A Bulletin can occur at any time throughout the equipment life-cycle
- There are two categories of Bulletin – Service bulletin (SB) and Information Bulletin (IB)
- There are two categories of Service Bulletin – Compulsory and Recommended
- Definitions of the Bulletins can be found on the Help page of the SB module
- Bulletin are exclusively managed through TLD website Support module
- SB management process relates to all the actions taken to address the SB
- SB management is a complex process with multiple scenarios and multiple stakeholders
- Roles and responsibilities of the different actors were not clearly set and there was no management tool to easily measure performance

Objectives

Based on the prevailing performances, it was important to review and develop new set of tools with the following scope:

- Flexible so as to adapt to the complexity
- Well structured so as to provide necessary guidance to the users
- Transversal so as to provide useful management tool across the organisation

The main objectives of this project was:

- To put in place a system that improve our SB management performances
- To keep track of all actions and decisions taken through the whole process
- To enable Service Managers to better and more efficiently plan resources
- To have a system that will guide the Service managers by sorting SB's by equipment and customers and therefore minimise data entry and other administrative burden

Reminder

- **COMPULSORY** : A failure or defect has been detected, with a possible impact on safety, or capacity of the equipment to perform its duty.

The retrofit works must be carried out immediately by the sales entity, and all the costs associated with such works (including labor) will be borne by the manufacturing company.

- **RECOMMENDED** : A failure or defect has been detected, with no impact on safety or capacity of the equipment to perform its duty, but with a possible impact on reliability, performance, comfort or corporate image, that should be corrected.

The costs associated with such works are shared as follows :

- Manufacturing companies shall pay for parts, and all related expenses (freight, duties...)
- Sales entities or final customer, if this is the sales entity decision, shall bear the cost of labor, travel and accommodation expenses of employees..


- **INFORMATION** : A operation or maintenance failure or defect or improvement has been detected with no impact on safety, equipment performances, comfort or corporate image.

All Compulsory and Recommended and Information SB's recorded as "to be done" by the SSO becomes immediately and transparently accessible by the customer through the Extranet tools for a specific unit concerned by this SB.

SB becomes now a four stage process exclusively managed by the factory through status changes and task assignment (BP)

1. Factory SB development and issuance: TLD

Factory develops the SB and then the PSM issues the SB directly to the concerned SSO Directors for Approval.




Pending

Approval

2. SSO review and action plan setup: The SSO


Director reviews the content of the SB, challenges if necessary the content of the type of SB and within 2 weeks, the SSO director has to decide with his team (ASM and Service Managers) implementation action plan.



ER-Selection

3. SSO communication and implementation in the fields: The Service Managers implement in the


field the SB according to the SSO Director decision until full implementation is done and recognized by the SSO Director who is in charge of doing the relevant control.



Implementation

Step 1- Internal Management Process: “Pending and Approval”

- When factory creates a new bulletin, then it will be set as “Pending” until it is ready to be communicated to the SSO directors i.e.:
 - Documentation is completed
 - All affected equipment is linked to the SB (ER)
 - Parts required are listed
- “Approval” is a SB status during which factory and SSO directors may have internal discussions on the decision regarding the criticality of the bulletin i.e. Mandatory, Recommended or Information.
- SSO directors have 2 weeks to challenge the factory
- Once agreed or at the end of the 2 weeks period, then factory will issue the final service bulletin by changing status.



Step 2- SSO Management Process: “ER_Selection”

This is the process during which decisions are taken by the SSO directors and the Service managers on the course of actions and select equipment where recommended and information bulletin will have to be implemented.


This process is important for the factory as it will define quantity of parts required for the implementation of Recommended SB.

This process does not apply to mandatory SB

Support Module\SB\SB#2864

[Home](#) | [Personnel](#) | [PDC](#) | [ER](#) | [WC](#) | [SB](#) | [Pubs](#) | [ODP](#) | [Admin](#)
[Home](#) | [By Num](#) | [Search](#) | [Reports](#) | [Owner](#) | [Help](#) | [Maintain SB Records](#)
[General](#) | [Summary](#) | [Tasks](#) | [Files](#) | [Log](#) | [Links](#) | [Parts](#) | [ER](#) | [Cust](#) | [SSO](#) | [Done](#) | [Coverpage](#) | [TBD](#) | [Gen Lin](#)

TBD	
☐	13983 - T13983 - FEDERAL EXPRESS (FEDEX) - - TLD AMERICA
☐	15915 - T15915 - FEDERAL EXPRESS (FEDEX) - ANC - TLD AMERICA
☐	15916 - T15916 - FEDERAL EXPRESS (FEDEX) - ANC - TLD AMERICA
☐	15908 - T15908 - FEDERAL EXPRESS (FEDEX) - CHS - TLD AMERICA
☐	13984 - T13984 - FEDERAL EXPRESS (FEDEX) - ELP - TLD AMERICA
☐	19390 - T19390 - FEDERAL EXPRESS (FEDEX) - EWR - TLD AMERICA
☐	19394 - T19394 - FEDERAL EXPRESS (FEDEX) - EWR - TLD AMERICA
☐	19413 - T15919 - FEDERAL EXPRESS (FEDEX) - EWR - TLD AMERICA
☐	19415 - T15921 - FEDERAL EXPRESS (FEDEX) - EWR - TLD AMERICA
☐	19416 - T15922 - FEDERAL EXPRESS (FEDEX) - EWR - TLD AMERICA
☐	19541 - T19385 - FEDERAL EXPRESS (FEDEX) - EWR - TLD AMERICA




Very Important: All mandatory SB's are automatically viewable on the EXTRANET page by the concerned customers. For Recommended SB's and IB's, only the ones with TBD flag turned at "Y" by the SSO Directors will be viewable by EXTRANET users. In other words, the SSO Directors decide what Recommended SB won't be issued to the final customers.

Step 3- External Management Process: “Implementation”

This third step is entirely and exclusively led by the Service managers.

To keep an extreme level of flexibility the process has been divided into three independent levels of actions:



NOT - Generating a Notification to the customer:

Notification can take different ways and therefore multiple choices are left to the service managers such as:

- Notify customer of the SB + no TLD actions – For example, a service manager might have discussed with customer or know that this specific customer can apply the SB without assistance from TLD. Some SB might only need very limited actions (e.g. manual changes...).
- Notify customer of the SB + TLD actions - In this case we can decide to send a technician to apply the SB (CSR) or/and send parts (SPR)
- No notification – We can decide to apply a SB but not informing the customer. Note that this alternative shall not apply for Compulsory SB.

Customers will receive an email through the system. Customer who does not have an extranet account will have his email address entered by the Service manager and will be offered the option to open an extranet account.

NOT - Generating a Notification to the customer:

- 1- Generate a New NOT – Shows a list of equipment affected by the SB and sorted by customer and airport.
- 2- Select the customer you wish to Notify – You can notify by batch

Support Module\SB\SB#2851\Summary

[Home](#) | [Personnel](#) | [PDC](#) | [ER](#) | [WC](#) | [SB](#) | [Pubs](#) | [ODP](#) | [Admin](#)

[Home](#) | [By Num](#) | [Search](#) | [Reports](#) | [Owner](#) | [Help](#) | [Maintain SB Records](#)

[General](#) | [Summary](#) | [Tasks](#) | [Files](#) | [Log](#) | [Links](#) | [Parts](#) | [ER](#) | [Cust](#) | [SSO](#) | [Done](#) | [Coverpage](#) | [Gen Links](#)

[Home](#) | [New SPR](#) | [New CSR](#) | [New NOT](#)

Generate NOT

- ☐ Select- 66D154 - HONGKONG AIRCRAFT ENGINEERING COMPANY (HAECO) - HKGTLD ASIA
- ☐ Select- 66D151 - AIR FRANCE (AF) - CDGTLD EUROPE
- ☐ Select- 66D153 - AIR FRANCE (AF) - CDGTLD EUROPE
- ☐ Select- T15868 - AIR FRANCE (AF) - CDGTLD EUROPE
- ☐ Select- T16088 - AIRBUS (AB) - TLSTLD EUROPE
- ☐ Select- 66D152 - EFM - MUCTLD EUROPE
- ☐ Select- T14813 - MENZIES AVIATION (AFRICA) (PROPRIETARY) Limited - JNBTLTD EUROPE
- ☐ Select- 66D155 - SOUTH AFRICAN AIRWAYS TECHNICAL - JNBTLTD EUROPE

Submit

NOT - Generating a Notification to the customer:

3- Edit the notification message –

A generic message is proposed with all information required.

Service manager can delete and amend text

4- Send the notification – Select customer name and send message

5- Log updated – SB summary will show log status as done with a log number, date and time.

Subject: TLD Mandatory Service Bulletin SB#2851 for TFX-500-MTS

Message:

Dear Valued Customer,

The purpose of this message is to officially warn you that TLD has issued a Mandatory Service Bulletin SB#2851; following is a description of the bulletin.

In order to get grease on both side of the shalf (better retain the grease) and to avoid damaging the motor, new ref of shalf with spring and seal are to intall (replace) on TFX-500-MTS.

This Bulletin in applicable to the following equipment list you currently uses (as per our records)

TLD Serial Number	Customer Asset#	Last Known Location
66D154		HKG

1.1 : It is mandatory to implement this bulletin on all these units as soon as possible to

1-2 : It is very important to implement this Bulletin of all these units and we

Addresseebook:

- ACKERMAN, Seth
- Adam, Phil
- Allen, Lloyd
- ALLIGNET, Christophe
- ANBOUBA, Fadi
- ANGOT, Cécile
- Aranega, Diego
- ARCHAMBAULT, Luc
- Artes, Tom
- AUDOUIT, Jérémy
- Ayalon, Givon
- BACHA, Richard
- BAILLARGEAU, Eric
- BAYART, Jean-Philippe

Submit

SPR - Generating a Spare Parts Request:

This is a major change as it is now entirely under the control of the Service Manager who will decide if parts should be sent, where and when. Tasks will then be assigned to the selected SPH.

1- Generate a New SPR – Shows a list of equipment affected by the SB and sorted by customer and airport in the same manner as with NOT.

2- Select the equipment/customer for which you will issue spare parts – You can manage by batch in the same manner as with NOT

3- Edit the SPR– Same as for a WC – Enter customer details, parts to be sent, SPH who will take care of the SPR...

SPR#	1006
Status	OPEN
Date/Time Opened	2008-12-11 09:57:11
SSO	TLD EUR
Entered by	SILVA, Frédéric
Requestor	SILVA, Frédéric
Parts Sales Rep	LEMAIRE, Valérie
Customer Name	AIR FRANCE (AF)
Customer Contact	JM MARZILLI
Customer Contact Tel	0174379756
Customer Email	jmmarzilli@airfrance.fr
Ship To Address	AIR FRANCE DE.BT POLE 3 / BAT 6410 Rue PERICHET BP 10201 95703 ROISSY CHARLES DE GAULLE FRANCE
Notes	Ship parts for SB#2851 application on specified Equipment
Tracking Numbers	

Line Items

PH	Description	UM	Qty
SB2851	KIT		1

SPR - Generating a Spare Parts Request:

- 4- Submit the SPR – Selected SPH will receive the SPR task by email and will follow instructions provided by the SPR.
- 5- Send the parts and inform customers: Once parts are sent. Tracking number shall be entered in the SPR module (by the SPH person) and sent to the service manager and customer if instructed to do so.
- 6- Log updated – SB summary will show SPR number and its status:
 - Pending: SPR was prepared by Service manager
 - Open: SPR was received by SPH
 - Closed: SPH has completed the task i.e. parts are sent

Note: It is then possible to follow the status of all the SPR by SPH hub or by factory by going to spare parts SPR module.

Spare Parts Module\Spare Parts Request

[Home](#) | [Personnel](#) | [Search](#) | [SPR](#) | [Inventory](#) | [Customer account](#) | [Reports](#) | [KPI](#)
[Home](#) | [By number](#) | [Search](#) | [Create](#) | [Reports](#) | [Maintain SPR](#)

Spare Parts Request Homepage

Welcome to the Spare Parts Request Homepage!

SPR Count by Status, SPH

	OPEN	CLOSED	Totals
Montlouis - Parts	42	165	207
TLD AME - Parts	30	143	173
TLD ASI		4	4
TLD America - Salinas	15	15	30
TLD SHA	5	24	29
Totals	92	351	443

SPR Count by Status, SSO

	OPEN	CLOSED	Totals
TLD AME	36	159	195
TLD ASI	11	22	33
TLD CHI	2	3	5
TLD EUR	43	165	208
TLD SIN		2	2
Totals	92	351	443

Latest SPR

Tips: You can sort the table below by clicking the header titles.

SPR#	Date/Time Opened	Status	SSO	SPH	Customer Name	ER type Linked	SB Linked
1489	2009-11-27 02:03:18	OPEN	TLD ASI	Montlouis - Parts	HAECO	Towbarless Aircraft Tractors	2990
1488	2009-11-25 15:07:09	OPEN	TLD EUR	TLD AME - Parts	GROUP EUROPE HANDLING	Air Conditioners	
1487	2009-11-24 15:53:29	CLOSED	TLD AME	TLD AME - Parts	INTERCARGO	Loaders	3011
1486	2009-11-30 02:56:57	CLOSED	TLD CHI	Montlouis - Parts	HAIRAN AIRLINES (CHINA)	Towbarless Aircraft Tractors	
1485	2009-11-23 16:04:19	CLOSED	TLD SIN	TLD AME - Parts	Air Asia X Sdn. Bhd.	Loaders	3011
1484	2009-11-23 16:05:03	CLOSED	TLD SIN	TLD AME - Parts	Air Asia X Sdn. Bhd.	Loaders	3011

Step 3- Generating a Customer Service Request - CSR:

This is where Service Manager can plan actions and track down SB implementation. The Service Manager will decide on the action to be taken by who and when. A tasks will then be assigned to the SPH in the same manner as it is currently done for WC.

1- Generate a New CSR – Shows a list of equipment affected by the SB and sorted by customer and airport in the same manner as with NOT.

2- Select the equipment/customer for which you will send a technician– You can manage by batch in the same manner as with NOT

3- Edit the CSR– Similar to a SR – Enter customer details, date of the intervention, service technician who will apply the SB...

Home | Personnel | CSR (BETA) | Service Records
Home | By number | Search | Reports | Maintain CSR
General | Tasks | Links | Files | Log | Edit | Close

General

CSR#	1012
Status	OPEN
SSO	TLD EUR
Entered By	SILVA, Frédéric
Call Via	WORKFLOW
Entered Date	2008-12-11 08:31:35
Scheduled Date and Time	2008-12-22 00:00:00
Airport Code	CDG
Service Technician	MEURISSE, Claude
Customer Name	AIR FRANCE (AF)
Customer Contact	C CHAMBON
Customer Tel	0688154768
Customer Tel Alt	
Notes	Concerne TPX500 AF CDG
Service Description	Apply SB#2851 to the specified Equipment

CSR - Generating a Customer Service Request:

4- Send the CSR – Service technician will receive the task by email and will follow instructions provided by the CSR.

5- Apply the SB and close task: Once technician has completed the task. He will then report it as closed.

6- Log updated – SB summary will show CSR number and its status:

- Open: CSR was sent to technician
- Closed: Technician has completed the task

Note: It is then possible to follow the status of all the SSO by going to Service CSR module.

CSR Count by Status, SSO

	CLOSED	OPEN	Totals
NO SSO		2	2
TLD AME	1	2	3
TLD ASI		3	3
TLD EUR		2	2
Totals	1	9	10

My CSRs

No records...

Latest

CSR#	SSO	Call Via	Status	Entered Date	Scheduled Date and Time	Airport Code	Service Technician	Customer Name	Customer Tel	Customer Contact
1038	TLD ASI	WORKFLOW	OPEN	2009-02-03 05:27:50	0000-00-00 00:00:00	MIR	CARVALHO, Denis		+216.22.25.27.84	KINEN SMIDA