



TLD Technical Bulletin Policy (and internal rules of implementation)

February 2013

In an effort to continuously improve its products, TLD issues on a regular basis some Technical Bulletins to customers to make them benefit from later improvements and to reduce potential reliability or safety concerns on their already delivered equipment.

In case where, after the delivery of products, a failure or defect is detected, or an important communication about the product has to be released, the manufacturing company concerned must issue a technical bulletin, and must absolutely contact directly the sales entities concerned in order to inform them and plan the necessary retrofit operations.

TLD's official and exclusive communication media and implementation tracking system for technical bulletins is the TLD Web site Service Bulletin Module.

There are 3 independent actions for any SSO to implement vis-à-vis its customer after a technical bulletin has been issued: Notification (NOT), Parts supply (SPR) and Field implementation (CSR). The purpose of the internal guidelines is to define the most common practices.

It is important to note that after the SSO have been officially informed of a technical bulletin (SB) release, each SSO has five working days to object or propose to amend the type of technical bulletin proposed by the factory (SB or IB, Compulsory or Recommended) and/or the quality of the content of the SB.

Although, after the bulletin release, the SSO's become responsible for its diligent implementation in the field, in the case of a compulsory service bulletin involving a safety exposure, each factory has the responsibility to control and make sure that such bulletin has been effectively and fully implemented in the fields by all SSO's, before closing its corrective action.

There are three categories of TLD Technical Bulletins:

1. **COMPULSORY SERVICE BULLETINS:** these bulletins correspond to modifications that have to be implemented on the equipment in order to avoid future potential safety or major reliability issues.

A failure or defect has been detected, with a possible impact on safety, or capacity of the equipment to perform its duty. In this case, a compulsory service bulletin must be issued by the TLD factory concerned.

TLD general policy: TLD notifies customers about the Compulsory SB's, provides the related parts free of charge and sends service technicians to implement the SB in the fields at its own cost only during the warranty period. Beyond the equipment warranty period, TLD provides the related parts free of charge, but it is the customer's responsibility to implement the SB on the equipment.

SSO actions:

Notification (NOT): Notifying the customer is mandatory for all SSO's, at the same time it is also automatic on the extranet tools, for all compulsory SB

Parts supply (SPR): Shipping the parts to the customer free of charge and without the customer having to request it is the normal process at TLD for any compulsory SB and is mandatory in case of service bulletins involving safety.

Field implementation (CSR):

- During the warranty period, the normal procedure is that the remediation works must be carried out free of charge for the customer by the SSO's (or if applicable by their subcontractors, under supervision of the sales entities).
- After the warranty period, it is strongly advised that the remediation works are carried out directly by the SSO's (or if applicable by their subcontractors, under supervision of the sales entities).
- In case of a Compulsory SB involving safety, during or outside of the warranty period, it is paramount for TLD SSO's to carry out the implementation in the fields. In case of serious difficulty to do so, it is accepted to consider that the implementation has been made, by the sales entities, by way of sending the Service Bulletin and relevant Parts to the final customer, but compulsorily with formal proof of acknowledgement by the final customer.

TLD Internal Cost repartition: All the TLD costs associated with the implementation of the compulsory SB (including labor at the normal local service billing rate) shall be borne by the TLD factory concerned.

2. **RECOMMENDED SERVICE BULLETIN:** these bulletins correspond to modifications that TLD recommends to implement on the equipment in order to increase reliability or to improve the performance of the unit.

A failure or defect has been detected, with no impact on safety or capacity of the equipment to perform its duty, but with a possible impact on reliability, performance, comfort or TLD corporate image, that should be corrected. In this case, a recommended service bulletin must be issued by the TLD factory concerned.

TLD general policy: TLD notifies the customer about the Recommended SB's and provides the related parts free of charge upon request only within the equipment warranty period. It is the customer's responsibility to implement the SB on the equipment at its own cost.

SSO actions:

Notification (NOT): The decision to notify the customer, partially or for the entire fleet of equipment concerned, is taken by each SSO's Director, and needs to be recorded in the service module. This SSO's director decision to notify the customer or not will determine whether the customer transparently sees or not the SB on its extranet page.

Parts supply (SPR): this is up to the SSO director to decide whether to ship parts free of charge without the customer having to request it, to ship the parts free of charge only upon customer request, or ship and invoice the parts upon customer request.

Field implementation (CSR): In case of a notified recommended SB, it is the SSO director's decision to determine whether technicians will be sent free of charge for the implementation in the field (most common case during the warranty period), or only upon customer request or upon formal PO from the customer (in this later case, the customer could be charged).

TLD Internal Cost repartition: The costs incurred by TLD associated with such works are shared between SSO and factories as follows:

- o Manufacturing companies shall pay for parts, and all related expenses (freight, duties...)
- o Sales entities shall bear the cost of labor, travel and accommodation expenses of employees.

3. **INFORMATION BULLETINS:** these bulletins usually correspond to modifications that have been made by TLD on the equipment definition for units produced later than the delivery to the customer. Some of these bulletins also correspond to additional advices regarding equipment improvements, maintenance and operations. These IB are sent to the customer for information as the customer may decide to implement these modifications or consider these advices on its equipment or operations for extended life or ease of use.

For a common understanding, these qualifications are defined as follows:

IB: "IMPROVEMENT": new design or technical evolution which provides enhanced reliability and extended life.

IB: "MAINTENANCE": changes or addition in the maintenance manual of the unit that participate in lowering the TCO of the unit or in facilitating the maintenance of the unit

IB: "OPERATIONS": advice or operation manual improvement to facilitate or improve the usage of the unit by the operator

TLD general policy: TLD notifies customers about the Information Bulletin's. Upon formal customer request, TLD sends the related parts at the customer's expense, and this is the customer's responsibility to implement the IB on its equipment at its own cost.

SSO actions:

Notification (NOT): The decision to notify the customers, partially or on the entire fleet of equipment concerned, is taken by each SSO Director, and needs to be recorded in the service module. This SSO's director decision to notify the customer or not will determine whether the customer transparently sees the IB or not on its extranet page.

Parts supply (SPR): this is up to the SSO director's to decide whether to ship parts free of charge upon customer request, or ship and invoice the parts upon customer request.

Field implementation (CSR): In case of a notified IB, this is the SSO director's decision to determine whether technicians will be exceptionally sent in for the implementation in the field upon customer request (most common case during the warranty period), or only upon formal PO from the customer (in that later case, the customer shall be charged).

TLD Internal Cost repartition: In the case where costs associated with such works on an IB are incurred by TLD, these costs shall be borne by the SSO only as a sales concession.