



TLD Technical Bulletin Policy

June 2012

In an effort to continuously improve its products, TLD issues on a regular basis some Technical Bulletins to customers to make them benefit from later improvements and to reduce potential reliability or safety concerns on their already delivered equipment.

There are three categories of TLD Technical Bulletins:

1. **COMPULSORY SERVICE BULLETINS:** these bulletins correspond to modifications that have to be implemented on the equipment in order to avoid future potential safety or major reliability issues.

TLD general policy: TLD notifies customers about the Compulsory SB's, provides the related parts free of charge and sends service technicians to implement the SB in the fields at its own cost only during the warranty period. Beyond the equipment warranty period, TLD provides the related parts free of charge, but it is the customer's responsibility to implement the SB on the equipment.

2. **RECOMMENDED SERVICE BULLETIN:** these bulletins correspond to modifications that TLD recommends to implement on the equipment in order to increase reliability or to improve the performance of the unit.

TLD general policy: TLD notifies the customer about the Recommended SB's and provides the related parts free of charge upon request only within the equipment warranty period. It is the customer's responsibility to implement the SB on the equipment at its own cost.

3. **INFORMATION BULLETINS:** these bulletins usually correspond to modifications that have been made by TLD on the equipment definition for units produced later than the delivery to the customer. These SB are sent to the customer for information as the customer may decide to implement these modifications on its equipment for extended life or ease of use.

TLD general policy: TLD notifies customers about the Information Bulletin's. Upon formal customer request, TLD sends the related parts at the customer's expense, and this is the customer's responsibility to implement the IB on its equipment at its own cost.