

PCB Defect Inspection Report

Automated export of completed inspection results and findings

A. Inspection Information

Test Image	01_missing_hole_05.jpg
Reference PCB	01.JPG
Generated Time	2026-09-01 02:13:38
Processing Time	1.76 seconds

B. Inspection Summary

Inspection Result	DEFECTIVE / FAIL
Total Defects	5
Total Defect Area	2,579 px ²
Detected Coverage	0.0536%
Highest Severity	HIGH

C. Inspection Conclusion

5 potential defect regions were identified. D1 received Priority #1 with HIGH relative geometric severity and is located in the TOP_LEFT region. Detected candidate coverage: 0.0536%.

D. Defect Assessment Summary

Defect ID	Area	Size	Severity Score	Severity	Priority	Spatial Region
D1	905 px ²	36 × 32 px	0.006521	HIGH	#1	TOP_LEFT
D2	638 px ²	31 × 26 px	0.005402	HIGH	#3	TOP_LEFT
D3	37 px ²	10 × 6 px	0.001420	LOW	#5	TOP_RIGHT
D4	590 px ²	42 × 26 px	0.006121	HIGH	#2	TOP_RIGHT
D5	409 px ²	24 × 22 px	0.004407	MEDIUM	#4	BOTTOM_LEFT

E. Interpretation Note

- Severity represents relative geometric extent.
- Severity is not a validated manufacturing acceptance limit.
- Measurements remain in pixels and pixel².
- Physical pixel-to-mm scaling is unavailable because the dataset does not provide a validated physical reference.