

## Troubleshoot the alarm that caused the brake to set

### Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

This warning is designed to alert technicians about an active alarm that is causing the brake to apply. In situations where the brake is set too long, damage can occur to the gearbox teeth and main bearing. Turbines with this warning active should therefore be prioritized for a service visit.