Q2 Operations and Incident Review

Service performance, printer incident trend, root cause, corrective actions, and lessons learned

Owner	Service Operations	**Version**	1.0
Effective	10 Jul 2026	**Classification**	Confidential

1. Executive summary

Q2 service performance improved after the X200 firmware issue was identified and corrected.

1.1 Key results

Measure	April	May	June
X200 incidents	30	18	10
Resolved within target	83%	94%	100%
Average resolution time	8 hours	5 hours	3 hours

1.2 Main finding

Firmware 3.2 caused the X200 print service to fail during scheduled restart. The failure produced E-4012 and was often described by users as the printer restarting every night.

1.3 Management conclusion

The response succeeded because Service Operations connected symptom-based tickets with the exact error-code article, then coordinated firmware 3.2.1 deployment with Product Engineering.

Evidence link: The technical recovery steps are documented in MAN-X200 and knowledge article KB-E-4012.

2. Incident analysis and corrective actions

The incident review separates immediate recovery from permanent correction and prevention.

2.1 Timeline

Date	Event
08 Apr	First cluster of nightly restart tickets identified.
12 Apr	E-4012 linked to firmware 3.2.
18 Apr	Temporary reset procedure published.
05 May	Firmware 3.2.1 released.
20 Jun	Deployment reached 96% of affected devices.

2.2 Actions

- Service Desk linked symptom phrases to KB-E-4012.
- Product Engineering released firmware 3.2.1.
- Endpoint Operations created a compliance report for remaining 3.2 devices.
- Support leads reviewed unresolved tickets every weekday.

Residual risk: Four percent of affected devices remained on firmware 3.2 at quarter end because they were offline.

3. Lessons, ownership, and next steps

The incident exposed retrieval, metadata, and change-management weaknesses in the support knowledge base.

3.1 Lessons learned

- Exact error codes and natural-language symptoms must both be searchable.
- Product and firmware metadata should be applied before ranking.
- Superseded support instructions must remain available for audit but excluded from normal answers.
- A reranker cannot recover an article missing from the candidate set.

3.2 Action register

Action	Owner	Due	Status
Add firmware filter to support search	Knowledge Team	31 Jul	Complete
Create E-4012 symptom synonyms	Service Desk	15 Jul	Complete
Retire firmware 3.2	Endpoint Operations	30 Sep	In progress
Build 25-question evaluation set	AI Engineering	15 Aug	Complete

RAG test ideas: Ask for trend calculations, timeline synthesis, cross-document recovery steps, and outstanding actions.