Answer to the question : 1

The Punpose of segment negister is to pointing at accessible block. There are Cs, Ds, Es, Ss asegment negister. Although it is possible to stone data in segment negister, but not wise to stone data in segment negister as while in process segment pointing negister might connupt stoned data.

Answer to the question: 2

There are 4 negister to stone data. those are Ax, Bx, Cx, Dx.

Ax - Accumulator negister.

BX - Base " negister - used to stone offset value

cx - count negister - used in loop

DX - Data negister - used in multiplication an input/out pont add.

These negisten has two sepanate 8 bit negisten, High and low For example Ax = AH+AL. Two 8 bit negisten makes 16 bit