Potential Failure Mode	Potential Failure Effect	Severity (1-10)	Potential Cause	Occurrence (1-10)	Controls	Detection (1-10)	Risk Priority Number
			Adding more items than				
Buffer Fills Faster than Empties	Loses Data	7	removing		Buffer is a fixed size	3	84
					Soldered leads for probing to		
			Oscope probes could touch		prevent having to probe on		
Shorting Signal to Ground	Processor Failure	10	multiple contacts		1 pins	1	. 10
			Terminal set up with		Terminal setup requires		
Mismatched UART speeds	Incorrect Data	8	incorrect buad rate		4 selection of baud rate	2	64
					Care taken when		
					plugging/unplugging dev		
Cable Break	No communication	10	Overruse or gets caught		1 board	1	. 10
			I/O pins not enabled on a		LEDs must be enabled in the		
No LED function	No visual application status	3	new build	-	7 GUI	2	42
	Data is not what was				Keyboard has letters on it and		
Incorrect input	expected	6	Fingers on wrong keys	4	4 can view terminal input	3	72