
Wiring Analog Outputs for an RIO-47100

Wiring Diagram:



Analog 15 pin D-Sub Connector Pinouts:

Pin	Label	Description
PIN	Labei	Description
6	AGND	Analog Ground
7	AO5	Analog Output 5
8	AO2	Analog Output 2
9	AGND	Analog Ground
12	AGND	Analog Ground
15	AGND	Analog Ground
16	A06	Analog Output 6
17	AO3	Analog Output 3
18	AO0	Analog Output 0
24	A07	Analog Output 7
25	AO4	Analog Output 4
26	AO1	Analog Output 1

Electrical Specifications:

Analog Output Voltage Range: 0-5V or +/- 10 VDC depending on model.

For full pinout and electrical specifications see the RIO-47000 user manual