

Questions we cannot answer today

- How many units did we pour last Tuesday — and how many did we scrap?
- Was that scrap empties or filled containers? They cost very different amounts.
- How long was Pump 2 down last week, and what for?
- Which resin lot went into the cartridges that shipped on the 14th?

Every one of those is answered from memory, or not at all. Resin pouring has never had a production record.

Nothing below asks a manager to enter anything. The operators log at the pump; everything else is read back out of that.

What an operator does


Once an hour, at the pump, on their own phone. No app to install — it is a web page on the plant network.

1. Pick the pump, container format and resin.
2. Type the lot code off the bottom of the container.
3. Enter units filled and scrap. Submit.

That is the whole operator screen.

What it costs to try

- Runs on one PC already on site.
- No software licences, nothing charged per person.
- Operators use the phone they already carry.
- No scheduling, assigning or approving by anyone.
- No IT involvement — a manager runs it end to end.
- Stopping it is deleting a folder — nothing else depends on it.



The hourly log, on a phone at the pump.

What that gives you

The numbers, by anything

Units, scrap and first-pass yield — by day, shift, operator, station or resin, comparable week to week.

Downtime with a cause on it

Minutes lost ranked by reason, so the case for fixing something is a number rather than an impression.

Traceability

Which lot went into which containers, at which pump, by whom and at what hour — without a paper search.

Out of the system

Any filtered view exports to CSV. The shift handover comes out as a PDF, emailed automatically if you want it.

WHERE TO START

It installs as a log: the only setup is the list of pumps, and a manager holds the whole console, so nothing waits on an IT person. Work orders are switched off until somebody switches them on; fill-weight limits, the floor display and the handover email are each one setting, and none is needed to record a pour.