
The TRIZ Method

in Engineering Design


TRIZ

- Teoriya Resheniya Izobreatatelskikh Zadatch
- Theory of inventive problem solving (TIPS)
- Started with Altshuller's (Genrich Saulovich Altshuller) interest in invention and work in Soviet Navy patent office.

GENERAL APPROACH TO PROBLEM SOLVING



"Simply" a matter of finding the previously well-solved problem analogous to the problem at hand



Trial and error

What is TRIZ?

TRIZ is an evolving, open-ended system for enhancing human inventiveness through

- Systematic identification of problems and attaining ideal solutions
- Overcoming various blocks through heuristics and approaches that have performed in other disciplines

Context and Issues:

Levels of inventive solutions

Regularities in the evolution of technological systems

Technical contradictions, the matrix

Substance-Field (SU-Field) theory

Levels of Inventive Solution

- Level 1: Standard, routine methods within specialty.
- Level 2: Improvement, new features.
- Level 3: Invention inside paradigm, essential improvement of existing system (automatic transmission).
- Level 4: Invention outside paradigm, new system (use of little known phenomena).
- Level 5: Discovery, essentially new system, new science? (lasers, aircraft, computers).

Regularities in Evolution of Technological Systems

8 Laws of Development of Engineered Systems

- 1. Law of completeness of parts of a system
- 2. Law of energy conductivity of a system
- 3. Law of harmonization of rhythms
- 4. Law of increasing ideality
- 5. Law of uneven development of parts
- 6. Law of transition to a supersystem
- 7. Law of transition from macro to mirco level
- 8. Law of increasing substance-field involvement

Technical Contradictions & the Matrix

- Parameter A improves, but parameter B deteriorates, strength v. weight.
 - Usually involves tradeoff or compromise
 - TRIZ seeks to outdo contradiction.
- In patent study, Altshuler identified 39 engineering parameters and 40 operators (or Inventive Principles)
- 39 x 39 matrix of parameter contradictions

39 System Parameters

- 1. Weight of moving object
- 2. Weight of nonmoving object
- 3. Length of moving object
- 4. Length of nonmoving object
- 5. Area of moving object
- 6. Area of nonmoving object
- 7. Volume of moving object
- 8. Volume of nonmoving object
- 9. Speed
- 10. Force
- 11. Tension, pressure
- 12. Shape
- 13. Stability of object
- 14. Strength
- 15. Durability of moving object
- 16. Durability of nonmoving object
- 17. Temperature
- 18. Brightness
- 19. Energy spent by moving object
- Energy spent by nonmoving object

- 21. Power
- 22. Waste of energy
- 23. Waste of substance
- 24. Loss of information
- 25. Waste of time
- 26. Amount of substance
- 27. Reliability
- 28. Accuracy of measurement
- 29. Accuracy of manufacturing
- 30. Harmful factors acting on object
- 31. Harmful side effects
- 32. Manufacturability
- 33. Convenience of use
- 34. Repairability
- 35. Adaptability
- 36. Complexity of device
- 37. Complexity of control
- 38. Level of automation
- 39. Productivity

40 Inventive Principles (operators)

- 1. Segmentation
- 2. Extraction
- 3. Local quality
- 4. Asymmetry
- 5. Combining
- 6. Universality
- 7. Nesting
- 8. Counterweight
- 9. Prior counter-action
- 10. Prior action
- 11. Cushion in advance

- 12. Equipotentiality
- 13. Inversion
- 14. Spheroidality
- 15. Dynamicity
- 16. Partial or overdone action
- 17. Move to new dimension
- 18. Mechanical vibration
- 19. Periodic action
- 20. Continue useful action
- 21. Rushing through
- 22. Convert harm to benefit

Contd.....40 Inventive Principles

- 23. Feedback
- 24. Mediator
- 25. Self-service
- 26. Copying
- 27. Substitute throwaway
- 28. Replace mechanical system
- 29. Use pneumatic-hydraulic system
- 30. Flexible film or thin membranes
- 31. Use porous material
- 32. Change color

- 33. Make homogeneous
- 34. Rejecting or regenerating parts
- 35. Transform physicalchemical states
- 36. Phase transition
- 37. Thermal expansion
- 38. Use oxidizers
- 39. Inert environment
- 40. Composite material

	N													
	ndesired Result (Conflict) Feature to Improve	Weight of moving object	Weight of non-moving object	Length of moving object	Length of non-moving object	Area of moving object	Area of non-moving object	Yolume of moving object	Volume of non-moving object	pædS	Force (Intersity)		Stress or pressure	Shape
No		1	2	3	4	5	6	7	8	9	10	11		12
1	Weight of moving object	+		15,8, 29,34		29, 17, 38,34		29, 2, 40, 28		2,8,15, 38	8, 10, 18, 37	10, 36, 37, 40		10, 14, 35, 40
2	Weight of non- moving object		+		10, 1, 29, 35		35, 30, 13, 2		5,35, 14,2		8, 10, 19, 35	13, 29, 10, 18		13, 10, 29, 14
Ø	Length of moving object	8, 15, 29, 34		+		15, 17, 4		7, 17, 4, 35		13, 4, 8	17. 10,4	1. 8. 35		1, 8, 10, 29
4	Length of non- moving object		35, 28, 40, 29		+		17, 7, 10, 40		35, 8, 2,14		28, 10	1, 14, 35		13, 14, 15, 7

Sample Contradiction

- Length of non-moving object vs. stress (or pressure)
- Use 1, 14, 35

Segmentation

Spherodiality

Transform physical-Chemical States

 Amounts to an expert system depending upon technical blocks.

Another Sample Contradiction

- Weight of moving object vs force
- Use 8, 10, 18, 37
 - Counterweight
 - Prior action
 - Mechanical vibration
 - Thermal expansion
- Amounts to an expert system depending upon technical blocks.

Resolve the Contradiction


Resolve the contradiction:

Lager engine diameter should produce Increases air intake, and should not produce Decreases ground clearance.

Separate in Space by the Inventive Principle "Different locations"

Idea: make the radius of the air intake large in one direction







Contradictions Matrix

																ı																							
GSA- 1969	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39
1			15.8. 29.34		29. 17. 38. 34		29. 2. 40. 28		2. 8. 15. 38	8. 10. 18. 37	10.36. 37.40	10.14. 35.40		28. 27. 18. 40	5. 34. 31. 35		6. 29. 4. 38	19.1. 32	35. 12. 34. 31		12.36. 18.31	6. 2. 34. 19	5. 35. 3. 31	10. 24. 35	10.35. 20.28	3. 26. 18. 31	3.11. 1.27			22. 21. 18. 27	22. 35. 31. 39	27. 28. 1. 36	35.3. 2.24	2. 27. 28. 11					35. 3. 34. 37
2				10.1. 29.35		35.30. 13.2		5. 35. 14. 2		8. 10. 19. 35	13.29.	13.10.	26.39. 1.40	28. 2.		2. 27. 19. 6	28. 19. 32. 22	35. 19. 32			15.19.		5.8.	10.15.	10. 20. 35. 26	19.6.	10.28.	18. 26. 28		2.19.			6. 13. 1. 32	2. 27. 28. 11	19.15.	1.10.	25. 28. I		. 28.
	15.8.				15. 17.		7. 17.	14.2	13.4.	17. 10.	1.8.	1.8.	1.8.	8.35.		15.0	10.15.		8.35.	20.1		7. 2.	4. 29.		15.2.		10.14.	28.32.	10.28.	1.15.			15. 29.	1.28.	14.15.	1.19.	35.1.	17. 24.	4.4.
3	29.34	35. 28.		l l	4	17. 7.	4.35	35.8.	8	4	35 1.14.		15.34 39.37.	15.14.	19	1.40.	19 3.35.	32	24		1.35	35.39	23. 10 10. 28.	1.24	29 30. 29.	29.35	29. 40 15. 29.	4 32. 28.		17. 24	17. 15	17 15. 17.	35.4	10		26. 24	26.24		8. 29 80. 14.
4	2. 17.	40. 29	14. 15.			10.40	7. 14.	2.14	29.30.	28.1 19.30.	35 10.15.	15.7	35 11.2.	28.26		35	38. 18 2. 15.	3. 25 15. 32.			12.8 19.10.	6.28	24.35	24.26	14	29.30.	28	3 26, 28,	10	1.18 22.33.		27 13. 1.	2. 25 15. 17.	3	1.35	1.26 14.1.	26 2.36.		7. 26 .0. 26.
5	29.4		18.4				17.4			35.2	36.28		13.39		6.3		16		19.32			30.26	2.39	30. 26	26.4	6.13	29.9	32.3	2.32	28.1	18.39		1316	10.1	15.30	13	26.18	28.23	84.2
6		30. 2. 14. 18		26. 7. 9. 39						1.18. 35.36	10. 15. 36. 37		2.38	40		2. 10. 19. 30	35. 39. 38				17.32	17. 7. 30	10.14. 18.39	30.16		40.4	40.4	32.3	18.36	27. 2. 39. 35		40.16	16.4	16		36	2.35. 30.18	23	.0.156. .7.7
7	2. 26. 29. 40		1.7. 35.4		1.7. 4.17				29.4. 38.34	15.35. 36.37	6.35. 36.37		28. 10. 1. 39		6.35. 4		34.39. 10.18	10.13. 2	35				36.39. 34.10	2. 22	2. 6. 34. 10	29.30. 7	14.1. 40.11					29.1. 40	15.13. 30.12	10	15. 29			35.34. 1 16.24 1	
		35. 10. 19. 14		35. 8. 2. 14						2.18.	24. 35	7. 2. 35	34. 28. 35. 40	9.14.		35.34. 38	35.6.				30.6		10.39. 35.34		35. 16. 32. 18	35.3	2.35.			34.39.	30. 18. 35. 4	25		,			2. 17. 26	- 1	35. 37. .0. 2
•	2.28.	19.14	13.14.		29.30.		7. 29.				6.18.	35. 15.	28.33.	8.3.	3.19.	36		10.13.			19.35.		10.13.		32.18	10.19.	11.35.		10.28.	1.28.	2.24.	35. 13.	32. 28.	34. 2.		10.28.	3.34.	ľ	.0. 2
9	13.38 8.1.	18. 13.	8 17. 19.		34 19. 10.	1.18.	34 15.9.	2.36.	13. 28.	15.19	38.40 18.21.		1.18 35.10.		35. 5		36. 2 35. 10.	19	35.38 19.17.	1.16.	38. 2 19. 35.	19.35	28.38 8.35.	13.26	10.37.	29.38 14.29.		1. 24 35. 10.				8. 1 15. 37.	13.12	28. 27 15. 1.	26 15.17.		27.16 36.37.	10.18	3. 28.
10	37. 18 10. 36.		9.36 35.10.		15 10. 15.		12.37 6.35.	18.37	15.12 6.35.	36, 35,	11			14.27 9.18.	19.2 19.3.		21 35.39.		10 14. 24.	36.37	18.37 10.35.	14.15 2.36.	40. 5 10. 36.	_		18.36 10.14.		23. 24 6. 28.		40.18 22.2.		18.1 1.35.	3. 25	11	18.20		10.19 : 2.36.		.0. 14.
11	37.40	10.18	36	14.16	36.28		10	35.34	36	21	24.15	15. 10	2.40	3.40	27		19.2	12.15	10.37		14	25	37	_	4	36	19.35	25	3.35	37		16	11	2		35	37	35. 24	35. 37
12	29.40	26.3	5.4		4.10		14.4. 15.22	7. 2. 35	34.18	37.40	34. 15. 10. 14			10.40			22. 14. 19. 32	32	2. 6. 34. 14		4.6.2	14	35. 29. 3. 5		14. 10. 34. 17		10. 40. 16	28.32. 1		22. 1. 2. 35	35. 1		32. 15. 26	2. 13. 1	29	1.28		32	.7. 26. 34. 10
13	21.35. 2.39	26.39. 1.40	13. 15. 1. 28		2.11. 13		28. 10. 19. 39	34. 28. 35. 40	33. 15. 28. 18	10.35. 21.16	2.35. 40	22.1. 18.4		17. 9. 15		39. 3. 35. 23	35.1. 32	32. 3. 27. 15	13. 19		32. 35. 27. 31	14.2. 39.6	2. 14. 30. 40		35. 27	15.32. 35		13	18	18.30	35. 40. 27. 39	35. 19	32. 35. 30	2. 35. 10. 16			35. 22. 39. 23		3. 35. 0. 3
1.4	1.8.	40.26.	1.15.	15.14. 2 28.26			10.15. 14.7	9.14.	8.13.		10.3. 18.40	10.30. 35.40			27. 3. 26		30. 10. 40	35. 19	19.35.		10. 26. 35. 28	35	35. 28. 31. 40		29.3. 28.10		11.3	3. 27. 16		18.35.	15.35.	11.3.	32.40. 28.2	27.11.	15.3.	2.13.	27. 3. 15. 40		9. 35. .0. 14
	19. 5. 34. 31		2.19.	-	3. 17. 19		10. 2. 19. 30	1	3.35.	19.2.	19.3.	14. 26. 28. 25		27. 3. 10	<u> </u>		19.35. 39		28. 6. 35. 18		19. 10. 35. 38		28. 27. 3. 18	,,	20.10.	3.35.	11. 2. 13		3.27.			27.1.	12.27	29. 10. 27	1.35.	10.4.	19. 29. 39. 35	- 1	35. 17. 4. 19
15		6. 27.	9	1.40.	19		19.30	35. 34.)	16	21	28. 25	39.3.	10			19.18.	4.35	35.18		33.38		27.16.	10	28. 20.	3.35.	34.27.			17.1.	16. 22	4	12.27	21	13	29.15	25.34.	- 1	20.10.
16	36. 22.	19.16 22.35.	15. 19.	35 15. 19. 3	3. 35.		34.39.	38 35. 6.	2. 28.	35. 10.	35. 39.	14. 22.	35. 23 1. 35.	10.30.	19. 13.	19. 18.	36.40	32. 30.	19. 15.		16 2.14.	21.17.	18.38 21.36.	10	10.16 35.28.		6. 40 19. 35.	24 32. 19.		40.33 22.33.	22 22. 35.	35. 10	1	4.10.	2.18.	2.17.	6.35 3.27.		.6. 38 .5. 28.
17		32	9 19. 32.	9 :	39. 18 19. 32.	35.38	40. 18 2. 13.	4	36.30	3. 21 26. 19.		19.32		22.40		36.40	32.35.		3. 17 32. 1.							30.39	3.10	24 11.15.			2.24	26. 27 19. 35.		16 15. 17.	27		35.31		35 2. 25.
18		32	16		26		10		19	6	22.14	32.30	27	35.19	6		19	0.16		1.15	32	1.6	13.1	1.6	26.17	1. 19 34. 23.		32			32.39	28. 26	19	13.16	19	13		10	.6
19	28.31		12. 28		15. 19. 25		35. 13. 18			21.2	23. 14. 25	29	19. 13. 17. 24				19. 24. 3. 14	19			6. 19. 37. 18	12. 22. 15. 24	18.5			16.18	11.27	3.1. 32		6.27	6	28. 26. 30		17. 28	15. 17. 13. 16				35
20		19. 9. 6. 27								36.37			27. 4. 29. 18	35				19. 2. 35. 32					28. 27. 18. 31			3. 35. 31	10.36. 23			10. 2. 22. 37	19. 22. 18	1.4					19.35. 16.25		6
21	8. 36. 38. 31	19. 26. 17. 27	1.10. 35.37		19.38	17. 32. 13. 38		30. 6. 25		26. 2. 36. 35		29.14. 2.40	35. 32. 15. 31	26. 10. 28	19.35. 10.38	16	2. 14. 17. 25	16.6. 19	16.6. 19.37			10. 35. 38	28. 27. 18. 38	10. 19	35. 20. 10. 6	4.34. 19		32. 15. 2				26. 10. 34	26.35. 10	35. 2. 10. 34	19. 17. 34		19.35. 16		8. 35. 84
22		19.6.			15. 26. 17. 30		7.18.	,	16.35. 38	36. 38			14.2. 39.6	26			19.38.	1.13. 32.15			3.38		35. 27. 2. 37	19. 10	10.18.		11.10.	22		21.22.	21.35. 2.22		35. 32.	2. 19			35.3. 15.23		8. 10. 9. 35
	35.6.	35.6.	14.29.	10.28.	35. 2.	10.18.	1.29.	3.39.	10.13.	14.15.	3.36.	29.35.	2.14.	35. 28.	28. 27.	27. 16.		1.6.			28. 27.		2.37	19.10	15.18.	6.3.	10. 29.			33. 22.	10.1.			2.35.		35.10.	35.18.	35.10.	8.35.
23	23. 40 10. 24.		10.39	24	10.31	39.31	30.36		28.38	18.40	37.10	3.5	30.40	31.40	3.18	18.38	39.31	13	24.5	12.31		2.31			24.26.	10.24 24.28.	10.28.	31.28		30. 10 22. 10.	10.21.	33	2. 24	34. 27	2	28.24	10.13		.0. 23 .3. 23.
24	35 10. 20.	5 10. 20.	1.26 15.2.		30. 26 26. 4.	30. 16 10. 35.	2. 5.	2. 22 35. 16.	26.32	10.37.	37. 36.	4. 10.	35. 3.	29.3.	20.10.	10 28, 20,	35. 29.	1. 19.	35. 38.		10. 19 35. 20.	19.10 10.5.	35. 18.	24. 26.	28.32	35 35.38.	23 10.30.	24.34.	24. 26.	1 35. 18.	22 35. 22.	32 35. 28.	27. 22 4. 28.	32.1.			35.33 : 18.28. :		.5
25	37.35	26.5		14.5	5.16		34. 10 15. 20.	32.18	35. 29.	36. 5 35. 14.	4 10.36.	34.17	22.5		28.18	10.16 3.35.	21.18	21.17	19.18 34.29.	1 3 35	10.6	18.32	10.39 6.3.	28.32 24.28.		18.16	4		28.18	34	18.39	34.4	10.34 35.29.	10 2.32.		6.29	32.10 : 3.27.	35.30	3. 29.
26	18.31	18.35	35.18		29	40.4	29	2.05	34. 28	3	14.3		17. 40		10.40	31	39	11. 00	16.18	31	35	25	10.24	35	18316	21.00	28.40	28	33.30	29.31	40.39		10.25	10. 25	29	27.10	29.18	8.35	3. 27
27	10.40	3. 10. 8. 28		28.11	14.16	40.4	3. 10. 14. 24	2.35. 24	11.28	8. 28. 10. 3	10. 24. 35. 19	35. 1. 16. 11		11.28	2. 35. 3. 25	34. 27. 6. 40	3.35. 10	13	21. 11. 27. 19	36. 23	21.11. 26.31	35	10.35. 29.39	10.28		40.3		32. 3. 11. 23	11.32. 1	2.40	35. 2. 40. 26		27. 17. 40	1.11	8.24	1		27	. 35. 29. 38
28	32. 35. 26. 28					26. 28. 32. 3	32. 13. 6		28. 13. 32. 24	32. 2	6. 28. 32	6. 28. 32	32.35. 13	28. 6. 32	28. 6. 32	10. 26. 24	6. 19. 28. 24	6.1. 32	3. 6. 32		3. 6. 32	26. 32. 27	10.16. 31.28		24.34. 28.32		5.11. 1.23			28. 24. 22. 26	3. 33. 39. 10		1.13. 17.34	1.32. 13.11			26. 24. : 32. 28		.0. 34. 28. 32
29	28. 32. 13. 18		10. 28. 29. 37		28. 33. 29. 32	2. 29. 18. 36	32. 28. 2	25. 10. 35	10. 28. 32	28. 19. 34. 36	3. 35	32.30. 40	30. 18	3. 27	3. 27. 40		19. 26	3. 32	32. 2		32.2	13.32. 2	35. 31. 10. 24		32. 26. 28. 18	32, 30	11.32. 1			26. 28. 10. 36	4. 17. 34. 26		1.32. 35.23	25. 10		26. 2. 18			.0. 18. 32. 39
20	22. 21. 27. 39	2. 22.	17. 1. 39. 4	1	22.1.	27. 2.	22. 23. 37. 35		21.22.	13.35.	22. 2.	22. 1. 3. 35		18.35.	22.15.	17.1. 40.33	22. 33. 35. 2	1.19.	1.24.	10. 2. 22. 37	19. 22. 31. 2	21.22. 35.2	33. 22. 19. 40	22. 10.	35.18.			28. 33. 23. 26				24.35.			35.11. 22.31	22. 19.	22. 19. 1 29. 40	33.3.	2. 35.
	19.22.	35. 22.	17.15.		17. 2.	22.1.	17. 2.	30.18.	35. 28.	35. 28.	2.33.		35.40.	15.35.	15. 22.	21.39.	22.35.	19.24.	2.35.	19.22.	2.35.	21.35.	10.1.	10.21.		3.24.	24.2.	3.33.	4.17.			-	20.39			19.1.	2.21.	1	2.35.
	15.39 28.29.	1.27.		15.17.	13.1.		40 13. 29.	35.4	35.13.		27. 18 35. 19.	35. 1 1. 28.	27. 39 11. 13.	1.3.	33.31 27.1.	16.22		28. 24.	6 28. 26.		18 27. 1.	22. 2			35. 28.	35. 23.	40.39	1.35.	34. 26				2. 5.			27. 26.		8.28.	.8. 39 35. 1.
32	15.16 25.2.	36. 13 6. 13.			26. 12 1. 17.	16. 4 18. 16.	1.40	35 4. 18.	8. l 18. 13.	35. 12 28. 13.	1.37	13.27	1 32. 35.	10.32 32.40.	4 29. 3.	35. 16 1. 16.	18 26327.	27. 1 13. 17.	27. 1 1. 13.	1.4	12. 24 35. 34.		33 28, 32,	18.16 4.10.	34. 4 4. 28.	1.24	17, 27,	12. 18 25. 13.	1.32.	24. 2 2. 25.		2. 5.	13.16	11.9 12.26.	15		11.1		.0. 28 .5. 1.
33	13.15		13.12			15.39		31.39		35	12	29.28				25	13	1.24	24			13	2. 24		10.34	12.35 2.28.	8.40	2.34		28.39		12	1.12.		1.16	12.17			. 32.
34	35.11	35.11	10.25	31	13	16.25	35.11	1	34.9	10	13	2.4	2.35	2.9	28.27	1	4.10	13	28.16		32.2	32.19	34.27		10.25	10.25	1.16	13	25. 10	102.16		11.10	26.15		16	13.11		7.13	.0
35	15.8	29.16	35. 1. 29. 2	16	35. 30. 29. 7	15.16		<u> </u>		15. 17. 20	35. 16	15.37. 1.8	14	35. 3. 32. 6	13.1. 35	2.16	27. 2. 3. 35	6. 22. 26. 1	19.35. 29.13		19.1. 29	18. 15. 1	2.13		35. 28		35. 13. 8. 24			35. 11. 32. 31		31	15.34. 1.16	1.16. 7.4		15. 29. 37. 28	1	35 6	35. 28. 5. 37
36	26.30. 34.36		1. 19. 26. 24		14. 1. 13. 16	6.36	34. 26. 6	1.16	34. 10. 28	26.16	19.1. 35			2. 13. 28	10.4. 28.15		2. 17. 13	24. 17. 13	27. 2. 29. 28		20. 19. 30. 34	10. 35. 13. 2	35. 10. 28. 29		6. 29	13.3. 27.10	13. 35. 1	2. 26. 10. 34	26. 24. 32	22. 19. 29. 40		27. 26. 1. 13	27. 9. 26. 24	1.13	29. 15. 28. 37		15.10. 37.28		.2.17.
	27. 26. 28. 13	б. 13.		1	2.13.				3.4.				11.22.	27.3.	19. 29. 25. 39		3. 27. 35. 16	2.24.	35.38	19.35.		35.3.	1.18.	35. 33. 27. 22	18.28.	3.27.	27.40.			22. 19. 29. 28		5. 28. 11. 29	2 5	12.26		15. 10. 37. 28		34. 21	
	28. 26.	28. 26.	14.13.		17.14.		35.13.	20. 31				15.32.				دد .ن	26.2.	8.32.	2.32.	10	28.2.		35.10.		24. 28.		11.27.	28. 26.	28. 26.		£. £1	1.26.	1.12.	1.35.	27.4.	15.24.	34. 27.		5.12.
	35. 26.	28. 27.	28.17 18.4.	30.7.	13 10. 26.	10.35.	16 2.6.	35. 37.			13.35 10.37.	1.13 14.10.	35.3.	25. 13 29. 28.	6.9 35.10.	20.10.	19 35. 21.	19 26. 17.	13 35. 10.		27 35. 20.	23. 28 28. 10.	18.5 28.10.	35.33 13.15.	35.30	35.13	1.35.	10.34 1.10.	32.1.	2. 33 22. 35.	2 35. 22.	35. 28.		13	1.35.	12.17.	25 35. 18.		35. 26
39	24.37	15.3		14.26	34.31	17.7		10.2		10.36	14	34.40	22. 39	10.18	2.18	16.38	28.10	19.1	38. 19	1		29.35	35. 23	23	l nd	35.38	10.38	34. 28	18.10	13.24	18.39		7. 19		28.37	28. 24	27. 2	35. 26	
														()/				uu		<u> </u>		<u>., ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	ے ں	ш														