#### **Answers to Exercise Problems**

```
Q6.1 [Ans p \approx 0.0062]
```

- **Q6.2** [Ans:  $(a)p \approx 0.9192$ ,  $(b) p \approx 0.9973$ ]
- **Q6.3** [Ans: (a)  $p \approx 0.4286$ ; (b) 24.63 hr; (c) 828.82 hr; 1487.42 hr]
- **Q6.4** [Ans: (a)  $p \approx 0.4213$ ; (b) 1743 hr]
- **Q6.5** [Ans: (a)  $10^4$  hr; (b) 6931.47 hr; (c)  $p \approx 0.6321$ ]
- **Q6.6** [Ans: (a)  $p \approx 0.2466$ ; (b)  $p \approx 0.2466$ ; (c) 1151.3 hr]
- **Q6.7** [Ans: (b)  $2 \times 10^4$  hr; (c)  $1.99 \times 10^4$  hr]
- **Q6.8** [Ans: (a) 10000 hr; (c)  $p \approx 0.1353$ ]
- **Q6.9** [Ans: 200 hr; 1.274]
- **Q6.10** [Ans: (a)  $p \approx 0.7836$ ; (b) 514.54 hr]

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 117

[7] Distribution Selection

@ 2025 L L 1 1 L

7 Distribution Selection

Dr. Indranil Hazra RE30003 @ IIT Kharagpur

Spring 2025

# Method of Moments (MoM)

*MoM* is a technique for estimating parameters of probability distributions that is based on *matching* the *sample moments* with the corresponding *distribution moments*.

#### Distribution moments:

1st (raw) moment (mean): 
$$\mu = \int_{-\infty}^{\infty} x f(x) dx$$
  
2nd (central) moment (variance):  $\mu_2 = \int_{-\infty}^{\infty} (x - \mu)^2 f(x) dx$   
3rd (central) moment:  $\mu_3 = \int_{-\infty}^{\infty} (x - \mu)^3 f(x) dx$   
kth (central) moment:  $\mu_k = \int_{-\infty}^{\infty} (x - \mu)^k f(x) dx$ 

Dr. Indranil Hazra

RE30003 @ IIT Kharagpur

Spring 2025

118

119

[7] Distribution Selection • § Method of Moments

© 2025 Indranil Haz

# Method of Moments (MoM) (cont'd)

#### Sample moments:

Sample mean: 
$$\bar{x} = \frac{\sum_{i=1}^n x_i}{n}$$

Sample variance:  $s^2 = \frac{\sum_{i=1}^n (x_i - \bar{x})^2}{n-1}$ 

Sample 3rd (central) moment:  $m_3 = \frac{\sum_{i=1}^n (x_i - \bar{x})^3}{n}$ 

Sample kth (central) moment:  $m_k = \frac{\sum_{i=1}^n (x_i - \bar{x})^k}{n}$ 

## **MoM for Exponential Distribution**

- Exponential PDF:

$$f(x) = \lambda e^{-\lambda x}, \ x \ge 0$$

- Distribution parameter:  $\lambda$
- Relation with sample mean: Dist. mean = sample mean

$$\frac{1}{\lambda} = \bar{x} = \frac{\sum_{i=1}^{n} x_i}{n}$$

Dr. Indranil Hazra

RE30003 @ IIT Kharagpur

Spring 2025

120

121

[7] Distribution Selection • § Method of Moments

© 2025 Indranil Hazr

#### **MoM for Normal Distribution**

Normal PDF:

$$f(x) = \frac{1}{\sigma\sqrt{2\pi}} \exp\left[-\frac{1}{2}\left(\frac{x-\mu}{\sigma}\right)^2\right], -\infty < x < \infty$$

- Distribution parameters:  $\mu, \sigma$
- Relation with sample estimates: Dist. mean/SD = sample mean/SD

$$\mu = \bar{x} = \frac{\sum_{i=1}^{n} x_i}{n}$$

$$\sigma^2 = s^2 = \frac{\sum_{i=1}^{n} (x_i - \bar{x})^2}{n - 1}$$

## **MoM** for Lognormal Distribution

- Lognormal PDF:

$$f(x) = \frac{1}{x\omega\sqrt{2\pi}} \exp\left[-\frac{1}{2}\left(\frac{\ln x - \theta}{\omega}\right)^2\right], \quad 0 < x < \infty$$

- Distribution parameters:  $\theta, \omega$
- Relation with sample estimates: Dist. mean/SD = sample mean/SD

$$\mu = e^{\theta + \omega^2/2} = \frac{\sum_{i=1}^n x_i}{n} = \bar{x}$$

$$\sigma^2 = e^{2\theta + \omega^2} (e^{\omega^2} - 1) = \frac{\sum_{i=1}^n (x_i - \bar{x})^2}{n - 1} = s^2$$

Dr. Indranil Hazra

RE30003 @ IIT Kharagpur

Spring 2025

122

[7] Distribution Selection • § Method of Moments

© 2025 Indranil Hazra

#### **MoM for Gamma Distribution**

– Gamma PDF:

$$f(x) = \frac{\lambda(\lambda x)^{r-1}e^{-\lambda x}}{\Gamma(r)}, \ x \ge 0$$

- Distribution parameters:  $r, \lambda$
- Relation with sample estimates: Dist. mean/SD = sample mean/SD

$$\mu = \frac{r}{\lambda} = \frac{\sum_{i=1}^{n} x_i}{n} = \bar{x}$$

$$\sigma^2 = \frac{r}{\lambda^2} = \frac{\sum_{i=1}^{n} (x_i - \bar{x})^2}{n - 1} = s^2$$

Dr. Indranil Hazra

#### MoM for Weibull Distribution

– Weibull PDF:

$$f(x) = \frac{\beta}{\theta} \left(\frac{x}{\theta}\right)^{\beta-1} \exp\left[-\left(\frac{x}{\theta}\right)^{\beta}\right], \ \ x \ge 0$$

- Distribution parameters:  $\theta, \beta$
- Relation with sample estimates: Dist. mean/SD = sample mean/SD

$$\mu = \theta \Gamma \left( 1 + \frac{1}{\beta} \right) = \frac{\sum_{i=1}^{n} x_i}{n} = \bar{x}$$

$$\sigma^2 = \theta^2 \left[ \Gamma \left( 1 + \frac{2}{\beta} \right) - \left\{ \Gamma \left( 1 + \frac{1}{\beta} \right) \right\}^2 \right] = \frac{\sum_{i=1}^{n} (x_i - \bar{x})^2}{n - 1} = s^2$$

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 124

[7] Distribution Selection • § Method of Moments

© 2025 Indranil Hazra

#### MoM Example

Data on aluminium contamination (ppm) in plastic:

#### **Aluminum Contamination (ppm)**

30	30	60	63	70	79	87
90	101	102	115	118	119	119
120	125	140	145	172	182	
183	191	222	244	291	511	

From "The Lognormal Distribution for Modeling Quality Data When the Mean Is Near Zero," *Journal of Quality Technology*, 1990, pp. 105–110.

- Sample mean,  $\bar{x}=\frac{\sum_{i=1}^n x_i}{n}=142.6538$  ppm, where n=26.
- Sample variance,  $s^2 = \frac{\sum_{i=1}^{n} (x_i \bar{x})^2}{n-1} = 98.2043^2$ .

#### MoM Example (cont'd)

- Let us assume that the data follows the exponential distribution.
- Exponential PDF  $(x \ge 0)$ :

$$f(x) = \lambda e^{-\lambda x}$$

- Distribution parameter:  $\lambda$
- Relation with sample estimates:

$$\frac{1}{\lambda} = \bar{x} = 142.6538 \implies \lambda = 0.00701$$




Figure: Exponential distribution fitted to the aluminium contamination data using method of moments.

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 20

[7] Distribution Selection • § Method of Moments

© 2025 Indranil Hazra

# MoM Example (cont'd)

- Let us assume that the data follows the normal distribution.
- Normal PDF  $(-\infty < x < \infty)$ :

$$f(x) = \frac{1}{\sigma\sqrt{2\pi}} \exp\left[-\frac{1}{2}\left(\frac{x-\mu}{\sigma}\right)^2\right]$$

- Distribution parameters:  $\mu, \sigma$
- Relation with sample estimates:

$$\mu = \bar{x} = 142.6538$$
 $\sigma = \sqrt{s^2} = 98.2043$ 




Figure: **Normal distribution** fitted to the aluminium contamination data using method of moments.

#### MoM Example (cont'd)

- Let us assume that the data follows the lognormal distribution.
- Lognormal PDF  $(0 < x < \infty)$ :

$$f(x) = \frac{1}{x\omega\sqrt{2\pi}} \exp\left[-\frac{1}{2}\left(\frac{\ln x - \theta}{\omega}\right)^2\right]$$

- Distribution parameters:  $\theta, \omega$
- Relation with sample estimates:

$$\omega = \sqrt{\ln\left(1 + \frac{s^2}{\bar{x}^2}\right)} = 0.6228$$

$$\theta = \ln\bar{x} - \frac{\omega^2}{2} = 4.7665$$




Figure: Lognormal distribution fitted to the aluminium contamination data using method of moments.

Dr. Indranil Hazra

RE30003 @ IIT Kharagpur

Spring 2025

128

[7] Distribution Selection • § Method of Moments

© 2025 Indranil Hazra

#### MoM Example (cont'd)

- Let us assume that the data follows the gamma distribution.
- Gamma PDF  $(x \ge 0)$ :

$$f(x) = \frac{\lambda(\lambda x)^{r-1}e^{-\lambda x}}{\Gamma(r)}$$

- Distribution parameters:  $r, \lambda$
- Relation with sample estimates:

$$r = \frac{\bar{x}^2}{s^2} = 2.1101, \qquad \lambda = \frac{\bar{x}}{s^2} = 0.0148$$




Figure: **Gamma distribution** fitted to the aluminium contamination data using method of moments.

#### MoM Example (cont'd)

- Let us assume that the data follows the Weibull distribution.
- Weibull PDF  $(x \ge 0)$ :

$$f(x) = \frac{\beta}{\theta} \left(\frac{x}{\theta}\right)^{\beta-1} \exp\left[-\left(\frac{x}{\theta}\right)^{\beta}\right]$$

- Distribution parameters:  $\theta, \beta$
- Relation with sample estimates:

$$\mu = \theta \Gamma \left( 1 + \frac{1}{\beta} \right) = \bar{x} = 142.6538$$

$$\sigma^2 = \theta^2 \left[ \Gamma \left( 1 + \frac{2}{\beta} \right) - \left\{ \Gamma \left( 1 + \frac{1}{\beta} \right) \right\}^2 \right]$$

$$= s^2 = 98.2043^2$$




Figure: Weibull distribution fitted to the aluminium contamination data using method of moments (solved numerically:  $\theta = 157.727$ ,  $\beta = 1.478$ ).

Dr. Indranil Hazra

RE30003 @ IIT Kharagpur


Spring 2025

130

[7] Distribution Selection • § Method of Moments

© 2025 Indranil Hazra

#### MoM Example (cont'd)



## **Probability Paper Plots (PPP)**

*PPP* is a graphical approach used in statistics to assess whether a dataset follows a particular probability distribution. The *scale of the graph paper* should be such that a *linear relationship* is produced for the plotted data.

- The objective is to write the cumulative distribution function (CDF) in **linear form**: y = mx + c. The distribution parameters can be estimated from the slope m and intercept c.
- The linearity or the lack of linearity can then be used as a basis for determining whether a sample data have come from a particular distribution.
- Statistical tests can then be used to quantitatively assess the goodness of fit between the data and the chosen distribution.

Dr. Indranil Hazra

RE30003 @ IIT Kharagpur

Spring 2025

132

[7] Distribution Selection • § Probability Paper Plots

© 2025 Indranil Hazra

## **Steps for Constructing Probability Paper Plots**

- In order to plot the sample data against a particular probability density function, one need's to assign a probability associated with each data point.
- Arrange the data in an increasing order:  $x_1, x_2, \dots, x_n$   $(x_{i+1} > x_i)$ , and calculate the **rank probability** associated with each data point (mean rank assumption) as:

$$P_i = \frac{i}{n+1}$$

where i  $(i = 1, 2, \dots, n)$  is the rank of the data and n is the number of data points.

 We then equate the rank probability of the data with the chosen cumulative distribution function (CDF) as:

$$P_i = F(x_i) \implies \frac{i}{n+1} = F(x_i) \implies F^{-1}\left(\frac{i}{n+1}\right) = x_i$$

where  $F^{-1}(\cdot)$  is the inverse CDF of the chosen distribution.

## **Constructing Normal Probability Paper Plots**

– Equate the rank probability of the data with the normal CDF:

$$\begin{split} P_i &= F(x_i) = \Phi\bigg(\frac{x_i - \mu}{\sigma}\bigg) \\ \Longrightarrow \Phi^{-1}\bigg(\frac{i}{n+1}\bigg) = \frac{x_i - \mu}{\sigma} \quad \text{(replace: } P_i = \frac{i}{n+1}\text{)} \\ \Longrightarrow x_i = \sigma\Phi^{-1}\bigg(\frac{i}{n+1}\bigg) + \mu \quad \text{(form: } y = mx + c\text{)} \end{split}$$

where  $\Phi(\cdot)$  is the standard normal CDF;  $\Phi^{-1}(\cdot)$  is the standard normal inverse CDF.

- The normal PPP is constructed by plotting the data  $x_i$  against the corresponding percentile value given by  $\Phi^{-1}(P_i)$ .
- Distribution parameters can be estimated from the above straight line equation as: mean  $(\mu) = \text{intercept}(c)$  and standard deviation  $(\sigma) = \text{slope}(m)$ .

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 134

7] Distribution Selection • § Probability Paper Plots

© 2025 Indranil Hazra

#### **Constructing Normal Probability Paper Plots**

- Once  $x_i$  values are plotted against  $\Phi^{-1}(P_i)$  values, they should form a straight line (approximately) on a normal PPP if the data belongs to a normal distribution.
- The best-fit line is obtained through linear regression which minimizes the sum of squares of deviations between the data and the fitted line.
- The **coefficient of determination**  $\mathbb{R}^2$  (normally ranges from 0 to 1) gives information about the goodness of fit of the model:

$$R^{2} = 1 - \frac{\sum_{i=1}^{n} (x_{i} - f_{i})^{2}}{\sum_{i=1}^{n} (x_{i} - \bar{x})^{2}}$$

where  $f_i=m\Phi^{-1}(P_i)+c$  is predicted from the best-fit line and  $\bar{x}=\frac{\sum_{i=1}^n x_i}{n}$ .

- The  $\mathbb{R}^2$  value reflects the strength of the linear association of the data. The **higher** the  $\mathbb{R}^2$  value, the **better the fit**.

## **Example: Normal PPP**

 A total of 25 samples of concrete strength were taken during the construction of a building and tested for crushing strength in the lab.
 The data set is shown below.

Test No.	Crushing Strength (MPa)
1	40.0
2	37.9
3	29.0
4	31.7
5	39.3
6	40.7
7	42.7
8	40.0
9	50.3

Test No.	Crushing Strength (MPa)
10	33.8
11	39.3
12	42.1
13	45.5
14	41.4
15	47.6
16	38.6
17	35.9
18	41.4

Test No.	Crushing Strength (MPa)
19	44.1
20	40.0
21	40.7
22	42.1
23	38.6
24	36.5
25	40.7

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 136

[7] Distribution Selection • § Probability Paper Plots

© 2025 Indranil Hazra

(Sten 3)

# **Example: Normal PPP** (cont'd)


- Step 1: Arrange (or sort) the data in an increasing order.
- Step 2: Calculate the probability based on the rank assumption.
- Step 3: Calculate the corresponding percentile value.
- Step 4: Plot the data.
- Step 5: Fit a straight line through the data.

		(Step 1)	(Step 2)	(Step 3)
Test No.	Crushing Strength (MPa)	Rank (i)	P <sub>i</sub>	$\Phi^{-1}(P_i)$
3	29.0	1	0.0385	-1.7688
4	31.7	2	0.0769	-1.4261
10	33.8	3	0.1154	-1.1984
17	35.9	4	0.1538	-1.0201
24	36.5	5	0.1923	-0.8694
2	37.9	6	0.2308	-0.7363
16	38.6	7	0.2692	-0.6151
23	38.6	8	0.3077	-0.5024
5	39.3	9	0.3462	-0.3957
11	39.3	10	0.3846	-0.2934

(Sten 1)

(Sten 2)

# **Example: Normal PPP** (cont'd)



Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 138

[7] Distribution Selection • § Probability Paper Plots

© 2025 Indranil Hazra

#### **Lognormal Probability Paper Plots**

- Equate the rank probability of the data with the lognormal CDF:

$$P_i = F(x_i) = \Phi\left(\frac{\ln x_i - \theta}{\omega}\right)$$


$$\Longrightarrow \Phi^{-1}(P_i) = \frac{\ln x_i - \theta}{\omega} \quad \text{(replace: } P_i = \frac{i}{n+1}\text{)}$$

$$\Longrightarrow \ln x_i = \omega \Phi^{-1}\left(\frac{i}{n+1}\right) + \theta \quad \text{(form: } y = mx + c\text{)}$$

where  $\Phi(\cdot)$  is the standard normal CDF;  $\Phi^{-1}(\cdot)$  is the standard normal inverse CDF.

- The lognormal PPP is constructed by plotting the logarithm of data  $\ln(x_i)$  against the corresponding percentile value given by  $\Phi^{-1}(P_i)$ .
- Distribution parameters can be estimated from the above straight line equation as:  $\theta = \text{intercept}$  and  $\omega = \text{slope}$ .

#### **Example: Lognormal PPP**



Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 140

[7] Distribution Selection • § Probability Paper Plots

© 2025 Indranil Hazra

#### Weibull Probability Paper Plots

- Equate the rank probability of the data with the Weibull CDF:

$$P_{i} = F(x_{i}) = 1 - e^{-\left(\frac{x_{i}}{\theta}\right)^{\beta}} \implies \ln\left(1 - P_{i}\right) = -\left(\frac{x_{i}}{\theta}\right)^{\beta}$$


$$\implies \frac{1}{\beta}\ln\left(-\ln\left(1 - P_{i}\right)\right) = \ln x_{i} - \ln \theta$$

$$\implies \ln x_{i} = \frac{1}{\beta}\ln\left(-\ln\left(1 - P_{i}\right)\right) + \ln \theta \quad \text{(replace: } P_{i} = \frac{i}{n+1}\text{)}$$

$$\implies \ln x_{i} = \frac{1}{\beta}\ln\left(-\ln\left(1 - \frac{i}{n+1}\right)\right) + \ln \theta \quad \text{(form: } y = mx + c\text{)}$$

- The Weibull PPP is constructed by plotting the logarithm of data  $\ln(x_i)$  against the corresponding value given by  $\ln(-\ln(1-P_i))$ .
- The distribution parameters can be estimated as:  $\beta=\frac{1}{\text{slope}}$  and  $\theta=e^{\text{intercept}}$

# Example: Weibull PPP (cont'd)



Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 142

7] Distribution Selection • § Probability Paper Plots

© 2025 Indranil Hazra

## **Exponential Probability Paper Plots**

– Equate the rank probability of the data with the exponential CDF:

$$\begin{split} P_i &= F(x_i) = 1 - e^{-\lambda x_i} \\ \Longrightarrow &\ln \left( 1 - P_i \right) = -\lambda x_i \\ \Longrightarrow x_i &= -\frac{1}{\lambda} \ln \left( 1 - P_i \right) \quad \text{(replace: } P_i = \frac{i}{n+1} \text{)} \\ \Longrightarrow x_i &= -\frac{1}{\lambda} \ln \left( 1 - \frac{i}{n+1} \right) \quad \text{(form: } y = mx + 0 \text{)} \end{split}$$

- The exponential PPP is constructed by plotting the data  $x_i$  against the corresponding value given by  $\{-\ln(1-P_i)\}$ .
- The distribution parameter can be estimated as:  $\lambda = \frac{1}{\text{slope}}$

## **Maximum Likelihood Estimation (MLE)**

**MLE** is a statistical method used to estimate the parameters of a statistical model. The goal of MLE is to find the values of the model parameters that *maximize the likelihood function*, which measures how well the model explains the observed data.

- Assume that the sample data  $x_1, x_2, \dots, x_n$  follow a probability distribution with PDF  $f(x|\theta_1, \theta_2, \dots, \theta_k)$ , where  $\theta_{1:k}$  are the distribution parameters.
- The likelihood of obtaining these n independent data points from the chosen distribution can be mathematically expressed as

$$L(\theta_{1:k}|x_{1:n}) = f(x_1|\theta_{1:k}) \times f(x_2|\theta_{1:k}) \times \cdots \times f(x_n|\theta_{1:k})$$
$$= \prod_{i=1}^n f(x_i|\theta_{1:k})$$

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 144

[7] Distribution Selection • § Maximum Likelihood Estimation

© 2025 Indranil Hazra

# Maximum Likelihood Estimation (MLE) (cont'd)

- The distribution parameters can be estimated by **maximizing** the **likelihood** function  $L(\theta_{1:k}|x_{1:n})$  or by maximizing the **logarithm of the likelihood** function  $\ln L(\theta_{1:k}|x_{1:n})$ .
- For estimating k number of parameters, a system of k equations can be obtained by maximizing the log-likelihood function as

$$\begin{split} \frac{\partial (\ln L(\theta_{1:k}|x_{1:n}))}{\partial \theta_1} &= 0 \quad \text{Equation (1)} \\ \frac{\partial (\ln L(\theta_{1:k}|x_{1:n}))}{\partial \theta_2} &= 0 \quad \text{Equation (2)} \\ & \vdots \\ \frac{\partial (\ln L(\theta_{1:k}|x_{1:n}))}{\partial \theta_k} &= 0 \quad \text{Equation (k)} \end{split}$$

#### **MLE** for Exponential Distribution

– Exponential PDF:

$$f(x) = \lambda e^{-\lambda x}, \ x \ge 0$$

– Likelihood function:

$$L(\lambda|x_{1:n}) = \prod_{i=1}^{n} f(x_i|\lambda) = \lambda^n \prod_{i=1}^{n} e^{-\lambda x_i}$$

– Log-likelihood function:

$$\ln L(\lambda|x_{1:n}) = n \ln \lambda - \lambda \sum_{i=1}^{n} x_i$$

Parameter estimation by maximizing the log-likelihood:

$$\frac{d \ln L(\lambda | x_{1:n})}{d \lambda} = 0 \implies \frac{n}{\lambda} - \sum_{i=1}^{n} x_i = 0 \implies \lambda = \frac{n}{\sum_{i=1}^{n} x_i}$$

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 146

7] Distribution Selection • § Maximum Likelihood Estimation

© 2025 Indranil Hazra

#### **MLE for Normal Distribution**

- Normal PDF:

$$f(x) = \frac{1}{\sigma\sqrt{2\pi}} \exp\left[-\frac{1}{2}\left(\frac{x-\mu}{\sigma}\right)^2\right], -\infty < x < \infty$$

– Likelihood function:

$$L(\mu, \sigma | x_{1:n}) = \prod_{i=1}^{n} f(x_i | \mu, \sigma) = \frac{1}{\sigma^n (2\pi)^{n/2}} \prod_{i=1}^{n} e^{-\frac{1}{2} \left(\frac{x_i - \mu}{\sigma}\right)^2}$$

Log-likelihood function:

$$\ln L(\mu, \sigma | x_{1:n}) = -n \ln \sigma - \frac{n}{2} \ln 2\pi - \frac{1}{2\sigma^2} \sum_{i=1}^{n} (x_i - \mu)^2$$

#### **MLE for Normal Distribution** (cont'd)

- Parameter estimation by maximizing the log-likelihood for  $\mu$ :

$$\frac{\partial \ln L(\mu, \sigma | x_{1:n})}{\partial \mu} = 0$$

$$\implies + \frac{1}{\sigma^2} \sum_{i=1}^n (x_i - \mu) = 0$$

$$\implies \mu = \frac{\sum_{i=1}^n x_i}{n}$$

- Parameter estimation by maximizing the log-likelihood for  $\sigma$ :

$$\frac{\partial \ln L(\mu, \sigma | x_{1:n})}{\partial \sigma} = 0$$

$$\implies -\frac{n}{\sigma} + \frac{1}{\sigma^3} \sum_{i=1}^n (x_i - \mu)^2 = 0$$

$$\implies \sigma^2 = \frac{\sum_{i=1}^n (x_i - \mu)^2}{n}$$

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 148

[7] Distribution Selection • § Maximum Likelihood Estimation

© 2025 Indranil Hazra

#### **MLE for Lognormal Distribution**

- Lognormal PDF:

$$f(x) = \frac{1}{x\omega\sqrt{2\pi}} \exp\left[-\frac{1}{2}\left(\frac{\ln x - \theta}{\omega}\right)^2\right], \quad 0 < x < \infty$$

– Likelihood function:

$$L(\theta, \omega | x_{1:n}) = \prod_{i=1}^{n} f(x_i | \theta, \omega) = \frac{1}{\omega^n (2\pi)^{n/2}} \prod_{i=1}^{n} \frac{e^{-\frac{1}{2} \left(\frac{\ln x_i - \theta}{\omega}\right)^2}}{x_i^n}$$

– Log-likelihood function:

$$\ln L(\theta, \omega | x_{1:n}) = -n \ln \omega - \frac{n}{2} \ln 2\pi - \frac{1}{2\omega^2} \sum_{i=1}^{n} (\ln x_i - \theta)^2 - n \sum_{i=1}^{n} \ln x_i$$

#### MLE for Lognormal Distribution (cont'd)

- Parameter estimation by maximizing the log-likelihood for  $\theta$ :

$$\frac{\partial \ln L(\theta, \omega | x_{1:n})}{\partial \theta} = 0$$

$$\implies + \frac{1}{\omega^2} \sum_{i=1}^n (\ln x_i - \theta) = 0$$

$$\implies \theta = \frac{\sum_{i=1}^n \ln x_i}{n}$$

- Parameter estimation by maximizing the log-likelihood for  $\omega$ :

$$\frac{\partial \ln L(\theta, \omega | x_{1:n})}{\partial \omega} = 0$$

$$\implies -\frac{n}{\omega} + \frac{1}{\omega^3} \sum_{i=1}^n (\ln x_i - \theta)^2 = 0$$

$$\implies \omega^2 = \frac{\sum_{i=1}^n (\ln x_i - \theta)^2}{n}$$

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 150

7] Distribution Selection • § Maximum Likelihood Estimation

© 2025 Indranil Hazra

151

#### **MLE for Gamma Distribution**

- Gamma PDF:

$$f(x) = \frac{\lambda(\lambda x)^{r-1}e^{-\lambda x}}{\Gamma(r)}, \ x \ge 0$$

– Likelihood function:

$$L(r, \lambda | x_{1:n}) = \prod_{i=1}^{n} f(x_i | r, \lambda) = \frac{\lambda^{nr}}{\Gamma(r)^n} \prod_{i=1}^{n} x_i^{r-1} e^{-\lambda x_i}$$

– Log-likelihood function:

$$\ln L(r, \lambda | x_{1:n}) = nr \ln \lambda - n \ln \Gamma(r) + (r-1) \sum_{i=1}^{n} \ln x_i - \lambda \sum_{i=1}^{n} x_i$$

#### MLE for Gamma Distribution (cont'd)

- Parameter estimation by maximizing the log-likelihood for  $\lambda$ :

$$\frac{\partial \ln L(r, \lambda | x_{1:n})}{\partial \lambda} = 0$$

$$\implies \frac{nr}{\lambda} - \sum_{i=1}^{n} x_i = 0 \implies \lambda = \frac{nr}{\sum_{i=1}^{n} x_i}$$

- Parameter estimation by maximizing the log-likelihood for r:

$$\frac{\partial \ln L(r,\lambda|x_{1:n})}{\partial r} = 0$$

$$\implies n \ln \lambda - n \frac{d \ln \Gamma(r)}{dr} + \sum_{i=1}^{n} \ln x_{i} = 0 \quad \text{(replace } \lambda\text{)}$$

$$\implies \ln r - \psi(r) = \ln \frac{\sum_{i=1}^{n} x_{i}}{n} - \frac{\sum_{i=1}^{n} \ln x_{i}}{n}$$

$$\text{(digamma function: } \psi(r) = \frac{d \ln \Gamma(r)}{dr}\text{)}$$

- Can you solve it analytically? No! Use a numerical solver.

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 152

7] Distribution Selection • § Maximum Likelihood Estimation

© 2025 Indranil Hazra

#### **MLE** for Weibull Distribution

- Weibull PDF:

$$f(x) = \frac{\beta}{\theta} \left(\frac{x}{\theta}\right)^{\beta-1} \exp\left[-\left(\frac{x}{\theta}\right)^{\beta}\right], \ \ x \ge 0$$

Likelihood function:

$$L(\beta, \theta | x_{1:n}) = \prod_{i=1}^{n} f(x_i | \beta, \theta) = \frac{\beta^n}{\theta^{n\beta}} \prod_{i=1}^{n} x_i^{\beta - 1} e^{-(\frac{x_i}{\theta})^{\beta}}$$

– Log-likelihood function:

$$\ln L(\beta, \theta | x_{1:n}) = n \ln \beta - n\beta \ln \theta + (\beta - 1) \sum_{i=1}^{n} \ln x_i - \frac{1}{\theta^{\beta}} \sum_{i=1}^{n} x_i^{\beta}$$

#### MLE for Weibull Distribution (cont'd)

- Parameter estimation by maximizing the log-likelihood for  $\theta$ :

$$\frac{\partial \ln L(\beta, \theta | x_{1:n})}{\partial \theta} = 0 \implies -\frac{n\beta}{\theta} + \frac{\beta}{\theta^{\beta+1}} \sum_{i=1}^{n} x_i^{\beta} = 0 \implies \theta = \left(\frac{\sum_{i=1}^{n} x_i^{\beta}}{n}\right)^{\frac{1}{\beta}}$$

- Parameter estimation by maximizing the log-likelihood for  $\beta$ :

$$\frac{\partial \ln L(\beta, \theta | x_{1:n})}{\partial \beta} = 0$$

$$\Rightarrow \frac{n}{\beta} - n \ln \theta + \sum_{i=1}^{n} \ln x_{i} - \frac{1}{\theta^{\beta}} \sum_{i=1}^{n} x_{i}^{\beta} \ln x_{i} + \frac{\ln \theta}{\theta^{\beta}} \sum_{i=1}^{n} x_{i}^{\beta} = 0$$

$$\Rightarrow \frac{n}{\beta} - n \ln \theta + \sum_{i=1}^{n} \ln x_{i} - \frac{n \sum_{i=1}^{n} x_{i}^{\beta} \ln x_{i}}{\sum_{i=1}^{n} x_{i}^{\beta}} + n \ln \theta = 0 \quad \text{(replace } \theta\text{)}$$

$$\Rightarrow \frac{1}{\beta} + \frac{1}{n} \sum_{i=1}^{n} \ln x_{i} - \frac{\sum_{i=1}^{n} x_{i}^{\beta} \ln x_{i}}{\sum_{i=1}^{n} x_{i}^{\beta}} = 0 \quad \text{(Use a numerical solver!)}$$

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 154

7] Distribution Selection • § Maximum Likelihood Estimation

© 2025 Indranil Hazra

## **MLE Example**

- Data on aluminium contamination (ppm) in plastic:

#### **Aluminum Contamination (ppm)**

30	30	60	63	70	79	87
90	101	102	115	118	119	119
120	125	140	145	172	182	
183	191	222	244	291	511	

From "The Lognormal Distribution for Modeling Quality Data When the Mean Is Near Zero," *Journal of Quality Technology*, 1990, pp. 105–110.

- Sample mean,  $\bar{x}=\frac{\sum_{i=1}^{n}x_{i}}{n}=142.6538$  ppm, where n=26.
- Sample variance,  $s^2 = \frac{\sum_{i=1}^{n} (x_i \bar{x})^2}{n-1} = 98.2043^2$ .

## MLE Example (cont'd)




Figure: The **log-likelihood profile** for the **exponential** distribution fitted to the aluminium contamination data.

Dr. Indranil Hazra RE30003 @ IIT Kharagpur Spring 2025 156

[7] Distribution Selection • § Maximum Likelihood Estimation

#### MLE Example (cont'd)




Figure: The **log-likelihood profiles** for **normal** (*left*) and **lognormal** (*right*) distributions fitted to the aluminium contamination data.

#### MLE Example (cont'd)




Figure: The log-likelihood profiles for gamma (left) and Weibull (right) distributions fitted to the aluminium contamination data.

Dr. Indranil HazraRE30003 @ IIT KharagpurSpring 2025158

[7] Distribution Selection • § Maximum Likelihood Estimation

© 2025 Indranil Hazra

# MLE Example (cont'd)

Table: Maximum likelihood (ML) estimates of distribution parameters.

Prob. Dist.	Parameter	ML estimate	Log-likelihood	MoM estimate
Exponential	λ	$\hat{\lambda}_{mle} = 0.0070$	-154.9709	$\hat{\lambda}_{mom} = 0.0070$
Normal	$\mu,\sigma$	$\hat{\mu}_{mle} = 142.654$ $\hat{\sigma}_{mle} = 98.204$	-155.6458	$\hat{\mu}_{mom} = 142.654$ $\hat{\sigma}_{mom} = 98.204$
Lognormal	$ heta,\omega$	$\hat{\theta}_{mle} = 4.7729$ $\hat{\omega}_{mle} = 0.6314$	-148.5235	$\hat{\theta}_{mom} = 4.7665$ $\hat{\omega}_{mom} = 0.6228$
Gamma	$r,\lambda$	$\hat{r}_{mle} = 2.8215$ $\hat{\lambda}_{mle} = 0.0198$	-149.0262	$\hat{r}_{mom} = 2.1101$ $\hat{\lambda}_{mom} = 0.0148$
Weibull	eta,  heta	$\hat{\beta}_{mle} = 1.6312$ $\hat{\theta}_{mle} = 160.57$	-150.3446	$\hat{\beta}_{mom} = 1.478$ $\hat{\theta}_{mom} = 157.727$

Figure: Various distributions fitted to the aluminium contamination data using method of moments (*left*) and method of maximum likelihood (*right*).

1000

1000

800

Aluminium contamination (ppm)

200 400 600 Aluminium contamination (ppm)