

Kenny Dang

Professor Money

ECE4156

22 April 2025

V. Reading the NIST test results

Basically if the P-value is 1, the data passes the test and is considered statistically consistent with randomness, which is “truly random”.

A P-value of 0 means that it did not pass the test, showing the data does not meet the expected behavior for randomness.

The significance level is the threshold that is set before the tests. It is asking how small the P-value must be for the test result to be considered significant.

The proportion column in the test results indicates the number of passing sequences out of the total number of sequences tested.