Intel Assembly I – Arithmetic & Logic Operations

Arithmetic & Logic Operations

Arithmetic Operations

- Addition
- Subtraction
- Multiplication
- Division
- Comparison
- Negation
- Increment
- Decrement

Logic Operations

- AND
- OR
- XOR
- NOT
- shift
- rotate
- compare (test)

Arithmetic & Logic Operations

 Some bits of EFLAGS can change for arithmetic and logic instructions

- Z (result zero)

- S (result positive)

- C (carry out) - P (result has even parity)

A (half carry out)O (overflow occurred)

Addition

 Addition, Increment, Add-with-carry and Exchange-and-add

```
add al, [ARRAY + esi]
inc byte [edi] ;Adds 1 to any reg/mem except seg
adc ecx, ebx ;Adds registers + Carry flag.
;Used for adding 64 bit nums.
xadd ecx, ebx ;ecx=ecx+ebx, ebx=original ecx.
```

Subtraction

 Subtraction, Decrement and Subtract-withborrow

```
sub eax, ebx ; eax=eax-ebx
dec edi
sbb ecx, ebx ; Subs registers - Carry flag.
```

- Comparison
 - The operands are subtracted, but the result is not stored; Changes only the flag bits.
 - Often followed with a conditional branch:

```
cmp al, 10H
jae LABEL1     ;Jump if equal or above.
jbe LABEL2     ;Jump if equal or below.
cmpxchg ecx, edx     ;if ecx==eax, eax=edx else eax=ecx
```

INC and DEC

• INC

- INC reg
- Increment reg value
- Same to ADD reg, 1

• DEC

- DEC reg
- Decrement reg value
- Same to SUB reg, 1

CMP

```
; If the first input is larger output 1
         ; If the second input is larger output 2
         ; The program uses subtraction:
         ; B < A is true if and only if B - A is negative.
         MOV EDX. 0
         IN EAX, [DX]
         MOV EBX, EAX
                          The first input is now in EBX
         IN EAX, [DX]
                           ;The second input is now in EAX.
         CMP EBX, EAX
                           ; This is first - second.
         JL SIB
                           ; Second is Bigger
         MOV EAX, 1
                           ; Otherwise First is Bigger
         JMP END
                           : Don't drift into the other case!
SIB:
         MOV EAX, 2
         MOV EDX, 1
END:
                           : Either way now EAX is ready.
         OUT [DX], EAX
         RET
```

Program 4.6

Multiplication and Division

- Multiplication and Division
 - mul/div: *Unsigned*.
 - imul/idiv: *Signed* integer multiplication/division.
 - al always holds the *multiplicand* (or ax or eax).
 - Result is placed in ax (or dx and ax or edx or eax).

```
mul bl
imul bx
imul cx, dx, 12H
mul ecx
; ax=al*bl (unsigned)
; dx | ax=ax*bx (signed)
; Special, cx=dx*12H (signed only)
```

Multiplication and Division

- *C* and *O* bits are cleared if most significant 8 bits of the 16-bit product are zero (result of an 8-bit multiplication is an 8-bit result).
- Division by zero and overflow generate errors.
- Overflow occurs when a small number divides a large dividend.

```
div cl;ah | al=ax/cl, unsigned quotient; in al, remainder in ahidiv cx;dx | ax=(dx | ax)/cx
```

AND, OR, and XOR

- Allow bits to be set, cleared and complemented
 - Commonly used to control I/O devices.
 - Logic operations always clear the *carry* and *overflow* flags.
- *AND*: 0 *AND* anything is 0.
 - Commonly used with a MASK to clear bits

```
XXXX XXXX Operand
0000 1111 Mask and al, bl ;al=al AND bl
0000 XXXX Result
```

AND, OR, and XOR

- OR: 1 OR anything is 1.
 - Commonly used with a MASK to set bits

```
XXXX XXXX Operand
0000 1111 Mask or eax, 10 ; eax=eax OR 0000000AH
XXXX 1111 Result
```

- XOR: Truth table: 0110.
 - Commonly used with a MASK to complement bits:

```
XXXX XXXX Operand

0000 1111 Mask xor ah, ch ;ah=ah XOR ch

XXXX XXXX Result
```

TEST

• *TEST*: Operates like the AND but doesn't effect the destination.

```
- Sets the Z flag to the complement of the bit being tested:

test al, 4


; Tests bit 2 in al -- 00000100

jz LABEL

; Jump to LABEL if bit 2 is zero.
```

- *BT*: Test the bit, *BTC*: Tests and complements...
- *NOT* (logical one's complement)
- *NEG* (arithmetic two's complement sign of number inverted)


```
not ebx
neg TEMP
```



Shift

- Shift: Logical shifts insert 0, arithmetic right shifts insert sign bit.
 - Shift 대상 오퍼랜드와 shift count 오퍼랜드로 구성; count 오퍼랜드 는 최대 5bit만 유의함
 - shift 된 비트는 CF로 들어감
- SHL과 SAL은 기본적으로 동작이 동일
 - unsigned multiplication of the destination operand by powers of 2
 - do not work for signed values
- SHR
 - unsigned division of the destination operand by powers of 2.
- SAR
 - 빈자리는 원래 값의 sign bit로 채움
 - signed division of the destination operand by powers of 2.


```
shl eax, 1   ;eax is logically shifted left 1 bit pos.
sar esi, cl ;esi is arithmetically shifted right
```




SHL/SAL Instruction Operation


Initial State CF Operand X 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 1 1 1 1 After 1-bit SHL/SAL Instruction 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 1 1 1 1 0 0 4 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 0 0 0 1 1 1 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0

SHR Instruction Operation



SAR Instruction Operation






Double Precision Shift

• shld / shrd


```
shdr eax, ebx, 12 ;eax shifted right by 12 and filled
;from the left with the right
;12 bits of ebx.
```



shdl ax, bx, 14

- shld dst, src, count
 - dst: reg / mem
 - src : register-only
 - count: CL or 8-bit immediate

SHLD and SHRD Instruction Operations



Rotate

 Rotate: Rotates bits from one end to the other or through the carry flag.


```
rol si, 14  ;si rotated left by 14 places.
rcr bl, cl ;bl rotated right cl places through carry.
```


• Commonly used to operate on numbers wider than 32-bits:

```
shl ax, 1    ;Original 48-bit number in dx, bx and ax.
    ;Shift ax left 1 binary place.


rcl bx, 1    ;Rotate carry bit from previous shl into
    ;low order bit of bx.

rcl dx, 1   ;Rotate carry bit from previous rcl in dx.
```





ROL, ROR, RCL, and RCR Instruction Operations



Bit/String Scan

- Bit Scan Instruction (80386 and up):
 - Scan through an operand searching for a 1 bit.
 - Zero flag is set if a 1 bit is found, position of bit is saved in destination register.

```
bsl ebx, eax ; eax scanned from the left. bsr bl, cl ; cl scanned from the right.
```

- String Scan Instructions:
 - *scasb/w/d* compares the al/ax/eax register with a byte block of memory and sets the flags.
 - Often used with *repe* and *repne*
 - *cmpsb/w/d* compares 2 sections of memory data.