



GUTENBERG ELITE HOME & PROPERTY MANAGEMENTS

Find a Home. Leave the Management to Us

Dealers in: Rent management, property and General Consultancy
Located in Ruiru, Juja | Tel: +254 702 705 821 | Email: jujaview@gmail.com

MAINTENANCE WORK ORDER

15 August 2026

WORK ORDER NO: GEHPM-WO-202608-000032

Property:PROPERTY NAME HOUSE PAYBILL UNIT(S) CARETAKER
MARIANA HOUSE 123456 B37, B13, B16, B29, B38, B39, B17, B18, B6, B42, B43, ME7, MB7, MC2, MC5 ROSE NDUKO

DATE REQUESTED
10 Jul 2026

WORK STARTED

COMPLETED

PRIORITY
High

ASSIGNED TECHNICIAN

TECHNICIAN NAME PHONE NO DATE ASSIGNED EXPECTED COMPLETION
MUGO,PATO,KIM,ALEX & RICHARD 0713785987/0725914323/0721969327

ISSUE REGISTER

#	Unit	Problem	Repair Required	Materials	Responsible Party	Mat. Cost	Labour	Total Cost	Status
B37									
1	B37	Ceiling requires painting	Painting	4ltr brilliant white	Management / Property Owner	1,500	—	1,500	New
B13									
2	B13	Door requires repainting	Painting	—	Management / Property Owner	—	—	—	New
B16									
3	B16	Window lock is missing and requires installation	General Maintenance	—	Management / Property Owner	—	—	—	New
4	B16	Does not receive adequate water	Plumbing	—	Management / Property Owner	—	—	—	New
B29									
5	B29	Window lock is missing and requires installation	General Maintenance	—	Management / Property Owner	—	—	—	New
B38									
6	B38	Window lock is missing and requires installation	General Maintenance	—	Management / Property Owner	—	—	—	New
7	B38	Does not receive adequate water	Plumbing	—	Management / Property Owner	—	—	—	New
B39									
8	B39	Does not receive adequate water	Plumbing	—	Management / Property Owner	—	—	—	New

#	Unit	Problem	Repair Required	Materials	Responsible Party	Mat. Cost	Labour	Total Cost	Status
B17									
9	B17	Does not receive adequate water	Plumbing	—	Management / Property Owner	—	—	—	New
B18									
10	B18	Does not receive adequate water	Plumbing	—	Management / Property Owner	—	—	—	New
B6									
11	B6	Does not receive adequate water	Plumbing	—	Management / Property Owner	—	—	—	New
B37									
12	B37	Water pipes inspection	Plumbing	—	Management / Property Owner	—	—	—	New
BLUE									
13	BLUE	Unused tank requires to regain functionality and proper lid	Plumbing	—	Management / Property Owner	—	—	—	New
MARIANA/BLUE									
14	MARIANA/BLUE	Blue and MARIANA HOUSE Water tanks require cleaning	General Maintenance	—	Management / Property Owner	—	—	—	New
MARIANA									
15	MARIANA	Direct borehole water to external taps	Plumbing	—	Management / Property Owner	—	—	—	New
16	MARIANA	Additional drying lines required	General Maintenance	—	Management / Property Owner	—	—	—	New
SUNVIEW									
17	SUNVIEW	SUNVIEW-Additional drying lines required	General Maintenance	—	Management / Property Owner	—	—	—	New
MC2									
18	MC2	Electricity token meter is faulty and requires replacement	Electrical	—	Management / Property Owner	—	—	—	New
MC5									
19	MC5	Electricity token meter is faulty and requires replacement	Electrical	—	Management / Property Owner	—	—	—	New
MARIANA									
20	MARIANA	Mariana water meter installation	Plumbing	—	Management / Property Owner	—	—	—	New

Labour involved: —

TOTAL MATERIAL COST	KES 1,500
TOTAL LABOUR COST	KES 0
TOTAL REPAIR COST	KES 1,500

This work order authorizes the listed repairs. The corresponding maintenance invoice is raised on completion.