DELPHI
POWER EQUIPMENT

二手叉车验车总结

Used Forklift Inspection Summary

Doosan GC45BCS-9（订单写作 **CGC45 / listed as CGC45 on the order**） | **S/N FGB1B-3620-00507**

项目 **Item**	内容 **Details**
买方 Buyer	Delphi Power Equipment Inc.（1717 Brittmoore Rd, Houston, TX 77043）
卖方 / 经销商 Seller / Dealer	Lonestar Forklift（销售 Salesperson: Logan Loving）
订单 / 库存号 Order / Stock No.	QUO-162146 / RF6143
价格 Price	机组 Unit $59,900；含税 incl. tax $64,947.83（8.25% 销售税 sales tax $4,941.75 + HE tax $106.08）
质保 Warranty	动力总成 180 天 180-day power train warranty
退出条款 Exit clause	休斯顿验车不合格，可无成本退出（订单第 2 页手写条款） If the Houston inspection fails, the buyer may back out at no cost (handwritten clause, order p. 2)
现场验车 On-site inspector	Jeff（现场拍摄照片 / photos taken on site）
依据资料 Sources	一页摘要、销售订单、发票（xls）、整备单、现场照片 25 张、视频（由买方查看） One-page summary, sales order, invoice (xls), make-ready worksheet, 25 site photos, video (reviewed by the buyer)

一、总体结论 / Overall Conclusion

车辆本体：验收通过。 铭牌、序列号、工时、发动机、门架、轮胎、安全装置核对无误，视频功能测试无问题。
Machine itself: ACCEPTED. Nameplate, serial number, hour meter, engine, mast, tires and safety equipment all check out. The video function test showed no problems.

文件与披露：暂不建议付款或签收。 有 4 项必须在付款前解决：发票品牌型号错误、订单卖方未签字、电汇信息需回拨确认、车身后部有碰撞和补漆迹象。
Paperwork and disclosure: do NOT pay or sign for delivery yet. Four items must be resolved before payment: wrong make/model on the invoice, order not signed by the seller, wire instructions need a call-back, and signs of impact and repainting at the rear of the body.

二、核对通过项 / Items Verified

#	项目 **Item**	实车情况 **Observed**	对照 **Compared with**	结论 **Result**
1	制造商 Manufacturer	Doosan（韩国制造 / made in Korea）	订单 Doosan Order: Doosan	✅

#	项目 **Item**	实车情况 **Observed**	对照 **Compared with**	结论 **Result**
2	序列号 Serial no.	FGB1B-3620-00507	订单、发票一致 Matches order and invoice	✅
3	燃料 Fuel	LP（铭牌和 UL 标牌 / nameplate and UL plate）	LPG	✅
4	工时 Hours	593.1 h	摘要 591–595 h，整备单 591 h Summary 591–595 h; make-ready 591 h	✅
5	仪表单位 Display units	mph（英制 / imperial）	—	✅
6	出厂年份 Model year	发动机 Kubota WG3800-L-EW，序列号 2PJ3068，出厂 **2023/05** Engine Kubota WG3800-L-EW, S/N 2PJ3068, **built 2023/05**	订单 2023 Order: 2023	✅ 倾向 2023，车架钢印待核 Likely 2023; frame stamp still to be checked
7	门架 Mast	三节，最大起升 185 in（4700 mm），FFT 3-stage, max lift 185 in (4700 mm), FFT	整备单 3/185 Make-ready 3/185	✅
8	侧移 Side shift	有，铭牌属具 HSS Yes; attachment HSS on nameplate	订单和整备单有侧移 Order and make-ready list side shift	✅
9	轮胎规格 Tire size	前 22×12×16，后 18×?×12.125，Solideal 实心胎 Front 22×12×16, rear 18×?×12.125, Solideal cushion tires	铭牌规格一致 Matches nameplate	✅
10	发动机舱 Engine bay	干净，无渗漏，线束整齐，机滤看起来是新的 Clean, no leaks, tidy wiring, oil filter looks new	整备单 500 h PM Make-ready: 500 h PM	✅
11	起升油缸、门架 Lift cylinder, mast	外观无油污 No oil residue visible	—	✅
12	驾驶室磨损 Cab wear	地垫、踏板、座椅磨损轻 Light wear on mat, pedals, seat	与 593 h 吻合 Consistent with 593 h	✅
13	安全装置 Safety equipment	频闪灯、灭火器、护顶架、LED 工作灯、后视镜、安全带齐全 Strobe, fire extinguisher, overhead guard, LED work lights, mirrors, seat belt all present	整备单 YES Make-ready: YES	✅
14	制动 Brakes	油冷盘式制动、座椅感应系统 Oil-cooled disc brakes, operator sensing system	—	✅
15	视频功能测试 Video function test	买方已查看，无问题 Reviewed by the buyer; no problems	—	✅
16	价格算术 Price arithmetic	59,900 × 8.25% = 4,941.75；× 0.1771% = 106.08；合计 total 64,947.83	订单价格一致 Matches order price	✅
17	额定载荷 Rated capacity	8,500 lb（3,860 kg），24 in 载荷中心，185 in 起升高度 8,500 lb (3,860 kg) at 24 in load center, 185 in lift height	摘要写"约 10,000 lb 级" Summary says "about 10,000 lb class"	✅ 两者不矛盾，要按铭牌曲线使用 Not contradictory; operate per the nameplate curve

#	项目 Item	实车情况 Observed	对照 Compared with	结论 Result
18	气罐 LP tank	现有罐是 Lonestar 租赁罐，卖方将换新罐 Current tank is a Lonestar rental tank; seller will supply a new one	整备单 LP TANK 为 NO Make-ready: LP TANK = NO	✅ 待书面确认 Pending written confirmation

三、合同要求项：货叉 / Contract Item: Forks

要求 Requirement	来源 Source	现状 Status
已装 **48 in** 货叉 **48 in forks installed**	订单第 2 页："48 INCH FORKS" Order p. 2: "48 INCH FORKS"	照片里车上有货叉，长度未实测 Forks are on the truck in the photos; length not measured
另附一套 **72 in** 备用货叉 **Plus an extra set of 72 in forks**	订单第 2 页："ALSO AN EXTRA SET OF 72 INCH FORKS"；整备单也要求 Order p. 2: "ALSO AN EXTRA SET OF 72 INCH FORKS"; also required by the make-ready worksheet	未见照片，待现场确认 **Not seen in photos; to be confirmed on site**
货叉状态 Fork condition	—	外观可见划痕和磨损，厚度、弯曲、裂纹未拍特写 Scratches and wear visible; thickness, bending and cracks not photographed up close

验车时请逐项勾选，并拍照留证：
Please tick each item during inspection and keep photo evidence:

- ☐ 48 in 货叉：长度实测为 _____ / 48 in forks: measured length _____
- ☐ 48 in 货叉：叉尖、厚度无明显磨损，无弯曲、裂纹 / 48 in forks: tips and thickness not excessively worn; no bending or cracks
- ☐ 72 in 备用货叉：一套（2 支）到位 / 72 in spare forks: one set (2 pcs) present
- ☐ 72 in 备用货叉：外观无损伤 / 72 in spare forks: no visible damage
- ☐ 交付时两套货叉一并运到 / Both fork sets delivered together with the truck

四、问题与差异清单 / Issues and Discrepancies

A. 付款前必须解决 / Must Be Resolved Before Payment

#	问题 Issue	依据 Evidence	要求 Required action
A1	发票品牌型号错误：写成 CLARK CGC55 **Wrong make/model on the invoice**: shown as CLARK CGC55	铭牌是 Doosan GC45BCS-9，订单是 Doosan CGC45 Nameplate: Doosan GC45BCS-9; order: Doosan CGC45	重开发票，按铭牌填写 Reissue the invoice per the nameplate

#	问题 **Issue**	依据 **Evidence**	要求 **Required action**
A2	订单卖方未签字 **Order not signed by the seller**	文件名含 NOT_SIGNED，只有买方签了字 File name contains NOT_SIGNED; only the buyer has signed	Lonestar 签字盖章。订单条款第 1 条要求修改须有卖方书面签署，第 3 条规定订单不得取消，退出条款在卖方签字前不一定有效 Lonestar to sign. Terms §1 require changes to be signed by the seller and §3 says the order may not be cancelled, so the exit clause may not be effective until the seller signs
A3	电汇风险 **Wire-transfer risk**	发票抬头电话 713-695-3675，底部联系人 Terry Foster 电话 713-694-3675，差一位数字。订单抬头是 Lonestar Forklift USA 2017 INC.（Garland），发票和支票抬头是 Lonestar Forklift（Houston） Invoice header phone 713-695-3675 vs. contact Terry Foster 713-694-3675 — one digit differs. Order shows Lonestar Forklift USA 2017 INC. (Garland); invoice and check payee show Lonestar Forklift (Houston)	用官网或订单上的固定电话回拨确认电汇指示，核对收款户名与合同主体一致 Call back on a number from the website or the order to confirm wire instructions; verify the payee name matches the contracting entity
A4	车身后部碰撞和补漆迹象 **Signs of impact and repainting at the rear**	配重左后转角有竖直折痕，漆面起伏，下角崩缺；右后轮罩漆面光亮并有橘皮纹，掉漆处露白色底层，有洋红色蹭漆；尾部拖拽销凹槽大面积掉漆生锈 Vertical crease and wavy paint at the left rear counterweight corner, chipped lower corner; glossy orange-peel paint on the right rear fender with white primer showing and magenta paint transfer; tow-pin recess heavily chipped and rusted	请 Jeff 检查配重和车架接缝、后桥、焊点；要求 Lonestar 书面说明是否有碰撞和钣金修复。可作议价依据 Jeff to inspect the counterweight-to-frame seam, rear axle and welds; Lonestar to state in writing whether there was an impact or bodywork repair. Can be used in price negotiation

B. 需要澄清 / Needs Clarification

#	问题 **Issue**	依据 **Evidence**	要求 **Required action**
B1	库存号不一致 **Stock number mismatch**	订单 **RF6143**；车上标签和门架 **5675**；整备单 **RF5675** Order **RF6143**; labels on truck and mast **5675**; make-ready **RF5675**	序列号一致，所以车辆身份可确认。要求 Lonestar 书面解释库存号和"RF"前缀的含义 The serial number matches, so the unit's identity is confirmed. Lonestar to explain in writing the stock numbers and the "RF" prefix
B2	整备单序列号少一位 Make-ready serial number is one digit short	整备单 FGB1B-3620-**0057**，铭牌 **00507** Make-ready FGB1B-3620-**0057**; nameplate **00507**	视为笔误，要求更正 Treat as a typo; ask for correction
B3	整备单年份 2021，订单 2023 Make-ready says 2021, order says 2023	发动机出厂 2023/05 支持 2023 Engine build date 2023/05 supports 2023	要求书面确认 2023，并核对车架钢印或出厂日期贴纸 Get written confirmation of 2023 and check the frame stamp or build-date decal
B4	整备单未完成 Make-ready not completed	完成日期和工单号为空；PM 勾 NO，附注却要求 500 h PM 和换滤芯 Completion date and work order blank; PM ticked NO, yet notes call for a 500 h PM and filter changes	要求提供保养工单和日期 Request the service work order and date

#	问题 Issue	依据 Evidence	要求 Required action
B5	税费和交货条款不明 Unclear taxes and delivery terms	"HE tax"未说明；订单为 CIP，发票为 F.O.B. Houston；发货日 TBD "HE tax" not explained; order says CIP, invoice says F.O.B. Houston; ship date TBD	要求写明费用构成，确认运输风险在卖方，直至送到你们厂址 Get the charges itemized; confirm transport risk stays with the seller until delivery to your site
B6	气罐换新 **New LP tank**	卖方口头承诺 Verbal commitment from the seller	写进更正后的订单：新罐随车交付并转移所有权，规格与罐架匹配，写明是否带气，费用是否包含在 $59,900 内，DOT 认证且在复检期内 Put in the corrected order: new tank delivered with the truck and ownership transferred, fits the existing bracket, state whether filled, confirm cost is included in the $59,900, DOT-certified and within its requalification date

C. 较小问题和建议 / Minor Issues and Recommendations

#	问题 Issue	建议 Recommendation
C1	安全带织带紫外线老化褪色 Seat-belt webbing faded by UV	交付前更换，并测试锁扣和卷收器 Replace before delivery; test the latch and retractor
C2	后轮比前轮显旧，后轮上方胎侧有折痕 Rear tires look older than the front; crease in the upper sidewall of a rear tire	用卡尺量磨损线，必要时向卖方要求更换或议价 Measure the wear line with calipers; request replacement or a price adjustment if needed
C3	链条略带锈色，润滑一般 Chain slightly rusty; lubrication average	实测 12 in 链节伸长量，超出约 3% 就应更换 Measure elongation over 12 in of chain; replace if it exceeds about 3%
C4	灭火器压力表和检验标签未读 Extinguisher gauge and inspection tag not read	现场拍照确认在有效期内 Photograph on site and confirm it is in date
C5	质保条款偏"as is"，条款第 1、10、11 条排除一切默示保证 Warranty terms lean "as is"; terms §1, §10, §11 exclude all implied warranties	要求提供 180 天动力总成保修的书面细则 Request written details of the 180-day power train warranty
C6	整备单划掉了 -9 系列项目（调整仪表语言、单位、称重校准） Make-ready struck out the -9 series items (display language, units, scale calibration)	仪表已是英制 mph，无需处理 Display is already in mph; no action needed
C7	车架钢印和出厂日期贴纸未见 Frame stamp and build-date decal not seen	补拍，用于核对年份 Photograph them to verify the model year

五、付款前待办清单 / Pre-Payment Checklist

序 No.	事项 Action	负责 Owner	完成 Done
1	Lonestar 重开发票（Doosan，按铭牌写型号） Reissue the invoice (Doosan, model per nameplate)	Lonestar	☐
2	Lonestar 签字盖章后的订单，含退出条款、气罐换新、货叉两套 Order signed and stamped by Lonestar, including the exit clause, new LP tank and both fork sets	Lonestar	☐
3	回拨确认电汇信息，核对户名 Call back to confirm wire instructions; verify payee name	买方 Buyer	☐

序 No.	事项 Action	负责 Owner	完成 Done
4	书面说明后部碰撞和补漆情况，现场检查配重和车架 Written explanation of rear impact and repaint; on-site check of counterweight and frame	Lonestar、Jeff	☐
5	书面解释库存号 RF6143 / 5675 / RF5675 Written explanation of stock numbers RF6143 / 5675 / RF5675	Lonestar	☐
6	书面确认年份 2023，补拍车架钢印 Written confirmation of model year 2023; photograph the frame stamp	Lonestar、Jeff	☐
7	货叉清单勾选完成并拍照（见第三节） Fork checklist completed and photographed (see Section 3)	Jeff	☐
8	更换安全带，量轮胎磨损线和链条伸长量 Replace the seat belt; measure tire wear lines and chain elongation	Lonestar、Jeff	☐
9	确认运费、保险、交货日期 Confirm freight, insurance and delivery date	买方 Buyer、Lonestar	☐

六、说明 / Notes

- 本总结依据照片和文件做出。"功能测试无问题"是买方的验收反馈。
  This summary is based on photos and documents. "Function test passed" is the buyer's own inspection feedback.
- 货叉、车架钢印、灭火器压力表、车底漏油情况在照片中没有拍到，按上文清单现场确认。
  The forks, frame stamp, extinguisher gauge and underside leaks were not captured in the photos; confirm them on site using the checklists above.
- 照片无法判断是否发生过事故，A4 的结论需要现场结构检查。
  Photos cannot establish whether an accident occurred; item A4 requires an on-site structural inspection.