

19/06/26 Day 24 "Kamineni Dhana Sri Keerthi"

Cadence OIP-19-06

Defect free.

Creating PDF named Cadence.
doubts

1 password: abcd1234

2 no need for driver (it is only for perform analysis)


3 for PL components $\rightarrow$ analog.lib

4 To open Instance press I.

5 for wire press ctrl+w or w.ig.

6 * check arrow mainly in pictures

Circuit.




get the values from the file.
and plot them in origin.

* Copy paste in cadence

$\rightarrow$ select $\rightarrow$ press only C $\rightarrow$ click anywhere space $\rightarrow$ a duplicate structure will pop $\rightarrow$ take that structure to whatever window you need and give it a left click.

* to change R, L, C values select and click Q.

Defected Cg [chao liu / Proposed]



* After doing Click. Ctrl + S and save for that to open again.

file → new
open → select and choose the file.

Defected R_L (N/P)

